


1 SCREENING CHAMBER SLIDE GATE P&ID DRAWING



2 BAR RACK P&ID DRAWING

NOTES:

- SEE SHEETS GI-1 AND GI-2 FOR INSTRUMENTATION SYMBOL LISTS, ABBREVIATIONS, AND GENERAL NOTES.
- REFER TO SHEET E10 FOR SLIDE GATE CONTROL WIRING DIAGRAM.
- PROVIDE INTRINSICALLY SAFE RELAYS AND BARRIERS FOR CONTROL AND INSTRUMENT CABLES RUN FROM HAZARDOUS LOCATIONS INTO CONTROL PANELS, AS REQUIRED TO INSURE SAFE OPERATION IN HAZARDOUS LOCATIONS.
- CONTROL STATION IS INTEGRAL TO ACTUATOR.