



NOTES:


- SEE SHEETS GI-1 AND GI-2 FOR INSTRUMENTATION SYMBOL LISTS, ABBREVIATIONS, AND GENERAL NOTES.
- REFER TO SHEET E10 FOR CONTROL WIRING DIAGRAMS FOR SLIDE GATE AND RECIRCULATION VALVE MOTORS.
- REFER TO SHEET E10A FOR SUMP PUMP CONTROL SYSTEM BLOCK DIAGRAM.
- PROVIDE INTRINSICALLY SAFE RELAYS AND BARRIERS FOR CONTROL AND INSTRUMENT CABLES RUN FROM HAZARDOUS LOCATIONS INTO CONTROL PANELS, AS REQUIRED TO INSURE SAFE OPERATION IN HAZARDOUS LOCATIONS.
- CONTROL STATION IS INTEGRAL TO ACTUATOR.



1 SUMP PUMP P&ID DRAWING



2 RECIRCULATION SYSTEM P&ID DRAWING



3 DISCHARGE CHAMBER SLIDE GATE P&ID DRAWING