STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Various Routes
OVD SIN STR REP & REPL 2006-9
Various Counties
Sheet 32 of 89
Contract Number 44904

District 3
Schedule of Locations for Overhead Sign Structure Replacement

Location No.:	3-01	State I.D.	No.:	38	050103	9L059.6		Loc	ation N	
County:	LaSalle	Route:	I-39	M.P.:	59.6	Direc	tion: SB		ınty:	L
Description of	Work			· · · · · · · · · · · · · · · · · · ·		Unit	Quantity	i announce of	criptio	
~~~	RHEAD SIGN S	TRUCTUR	E-SPAN			EACH	1.00		MOVE ERHEA	
OVERHEAD SI	IGN STRUCTUR	E-SPAN, T	YPE II-A			FOOT	108.00		MOVE	
REMOVE & RE	INSTALL SIGN	PANEL				SQ FT	342.50		MOVE	
REMOVE & RE	INSTALL WALK	WAY				FOOT	31.00	OVI	ERHE/	AD SIG
OVERHEAD SI	IGN SUPPORT	GROUT RE	PAIR			EACH	4.00		RNISH	
FURNISH & IN	STALL SAFETY	CHAIN				EACH	2.00	DIS	CONN	ECT/F
DISCONNECT	RECONNECT E	LECTRIC	SERVICE		1	EACH	1.00			
									s struct	
This structure is	s being downsize	ed from a T	ype IV trus	ss to a				בוענים	- n uu	JJ.
Type II truss.	•									

Location No.: 3-02 State I.D. No.: 3S050I						39R057.7			
County:	county: LaSalle Route: I-39 M.P.: 57.7								
Description of	Work		· · · · · · · · · · · · · · · · · · ·			Unit	Quantity		
REMOVE OVE	RHEAD SIGN S	TRUCTUR	E - SPAN			EACH	1.00		
OVERHEAD SI	GN STRUCTUF	E-SPAN, T	YPE II-A			FOOT	124.00		
REMOVE & RE	INSTALL SIGN	PANEL				SQ FT	299.00		
REMOVE & REINSTALL WALKWAY							44.00		
OVERHEAD SIGN SUPPORT GRPOUT REPAIR							4.00		
DISCONNECT/	RECONNECT E	LECTRIC	SERVICE			EACH	1.00		
This structure is	being downsize	ed from a T	ype IV tru	iss to a					
Type II truss.									

Location No.:	cation No.: 3-03 State I.D. No.: 3S050103				9R057.2			
County:	LaSalle	Route:	I-39	Direc	tion: NB			
Description of	Unit	Quantity						
REMOVE OVE	REMOVE OVERHEAD SIGN STRUCTURE-SPAN							
OVERHEAD SI	OVERHEAD SIGN STRUCTURE-SPAN, TYPE II-A							
REMOVE & RE	SQ FT	299.00						
REMOVE & RE	FOOT	44.00						
OVERHEAD SIGN SUPPORT GROUT REPAIR							4.00	
FURNISH & INSTALL SAFETY CHAIN							2.00	
DISCONNECT/RECONNECT ELECTRIC SERVICE							1.00	
		,						
This structure is being downsized from a Type IV truss to a								
Type II truss.								

Location No.: 3-04	State I.D	). No.:	350	501039	R058.3		
County: LaSalle	Route:	Route: I-39 M.P.: 58.3 Direction					
Description of Work					Unit	Quantity	
REMOVE OVERHEAD SIG	N STRUC	TURE-SP	AN		EACH	1.00	
OVERHEAD SIGN STRUCT	URE-SP/	N, TYPE	II-A		FOOT	124.00	
REMOVE & REINSTALL SIG		SQ FT	413.25				
REMOVE & REINSTALL WA		FOOT	49.00				
OVERHEAD SIGN SUPPOR		EACH	4.00				
FURNISH & INSTALL SAFE		EACH	2.00				
DISCONNECT/RECONNECT		EACH	1.00				
This structure is being down	sized fron	n a Type I	V truss to	а			
Type II truss.							

Location No.:	3-05	State I.D. No.: 3S050I-39			9L060.3			
County:	LaSalle	Route:	I-39	M.P.:	60.3	Direc	tion: SB	
Description of	Unit	Quantity						
REMOVE OVE	RHEAD SIGN S	rructu	RE-SPAN			EACH	1.00	
OVERHEAD SI	GN STRUCTUR	E-SPAN	, TYPE II-A			FOOT	108.00	
REMOVE & RE	REMOVE & REINSTALL SIGN PANEL							
REMOVE & RE	FOOT	52.00						
FURNISH & INSTALL SAFETY CHAIN							2.00	
OVERHEAD SIGN SUPPORT GROUT REPAIR							4.00	
DISCONNECT/RECONNECT ELECTRIC SERVICE							1.00	
This structure is being downsized from a Type IV truss to a								
Type II truss.								