

COUNTY TOTAL SHEETS SECTION F.A.I. SHEE NO. COOK 94/90 2003-0291 344 201 STA. TO STA. FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT 62581

Notes:

Existing longitudinal reinforcement in slab and barriers shall be cleaned, straightened and incorporated into new construction.

Bend #4 vertical parapet bars in field to clear the top flange of fascia girders as needed.

Remove existing rails, posts, anchors or other attachments as required for the partial removal of barriers for the joint reconstruction. Reinstall removed components as required to restore original condition. Cost included with "Concrete Removal" and "Concrete Superstructure".

Place bars in parapet to maintain  $I_2^{l}$ " cl.

Care should be exercised during concrete removal not to damage existing shear studs.

BILL OF MATERIAL

Item	Unit	Total
Deck Silicone Joint Sealer, 1"	Foot	107
Silicone Joint Sealer, 1"	Foot	10,486

REVISIONS NAME DATE	ILLINOIS DEPARTMENT O	· · · · · · · · · · · · · · · · · · ·
	F.A.I. 94/90 (DAN R)	
	SB DAN RYAN ELE	VATED BRIDGE
	REPAIR FROM 15TH T	0 28TH STREETS
	TYPICAL DECK SLAB AND SILICONE JOINT	
	SCALE: NTS	
	DATE: 5/25/2006	DRAWN BY: BDC CHECKED BY: BLU