



<u>PIER 3</u> (Looking North)

N. ABUT. TOP VIEW





<u>PIER 3</u> (Looking South)

<u>PIER 2</u> (Looking North)

Note:
Repair of the existing abutment and piers shall include but may not be limited to the areas shown. The actual areas to be repaired will be determined by the Engineer at the time of Construction.

## BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth equal to or less than 5 in.)	Sq. Ft.	55

## <u>LEGEND</u>



Structural Repair of Concrete (Depth equal to or less than 5 in.)

Square Feet

	USER NAME =
LIN ENGINEERING,LTD.	FILE NAME =
Consulting Engineers	PLOT SCALE =
Chatham, Illinois	PLOT DATE =

	USER NAME =	DESIGNED	-	TBP	REVISED	-
Э.	FILE NAME =	CHECKED		ADB	REVISED	
	PLOT SCALE =	DRAWN	-	AJF	REVISED	
	PLOT DATE =	CHECKED	-	MTH	REVISED	-

STATE	0F	ILLINOIS
DEPARTMENT (	)F	TRANSPORTATION

SUBSTRUCTURE REPAIR	F.A.P. RTE.	,
TRUCTURE NO. 016-0218	345	8
SUEET NO. 5 OF 7 SUEETS		

F.A.P. RTE.	SECTION	COUNTY	TOTAL	SHEET NO.
345	8R-1-RS-4	COOK	124	98
		CONTRACT	NO. 6	OM46
	ILLINOIS FED. A	ID PROJECT		