

## SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

## WORK ZONE EXIT OPENING





## NOTES:

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS)
UNLESS OTHERWISE SHOWN

REVISIONS		ILLINOIS DEPARTMENT OF TRANSPORTATION	
NAME	DATE	ILLINOI.	3 DEFARTMENT OF TRANSPORTATION
DWS	8/98		
JAF	4/03		
JAF	2/06	SIGNING	FOR FLAGGING OPERATIONS
SPB	1/07	1 , —	WORK ZONE OPENINGS
SPB	12/09	AI	WORK ZONE OF ENTINGS
		SCALE: NONE	DDAWN DV CADD
		SCALE: NUNE	DRAWN BY CADD
			CHECKED BY
			TC-18

FILE DAME = 17-02-2019 FILE DAME = 13-02-2019 PLOT SCALE = 50.000 '/ IN