FOR INDEX OF SHEETS, SEE SHEET NO. 2

FOR SUMMARY OF QUANTITIES, SEE SHEET NO. 3

STATE OF ILLINOIS

COUNTY

*(10-78-1 & 10-7VB)I

SECTION

D-95-062-06

LOCATION OF SECTION INDICATED THUS: -

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

PRINTED BY THE AUTHORITY


OF THE STATE OF ILLINOIS

DEPARTMENT OF TRANSPORTATION

PROPOSED HIGHWAY PLANS

FAI ROUTE 74 (=-74) SECTION (10-7B-1 & 10-7VB)I **CHAMPAIGN COUNTY**

C-95-063-06



TOTAL LENGTH OF SECTION & PROJECT = 326.50 FEET = 0.062 MILES

NET LENGTH OF SECTION & PROJECT = 326.50 FEET = 0.062 MILES

DIVISION OF HIGHWAYS

BRIDGE REHABILITATION OVER SALT FORK RIVER WEST OF ST. JOSEPH & BRIDGE REHABILITATION OVER UNION PACIFIC RAILROAD 1.5 MILE EAST OF ST. JOSEPH

CONTRACT NO. 70548

1--800--892--0123

CURRENT ADT

F. A. I. 74 (WESTBOUND) S. N. 010-0030 = 19,600 (2006) S. N. 010-0032 = 12,500 (2006)

DESIGN DESIGNATION

FILL SIZE PLANS HAVE REEN PREPARED LISING STANDARD

JOINT UTILITY LOCATION INFORMATION FOR EXCAVATION

ST. JOSEPH TOWNSHIP

ENGINEERING SCALES. REDUCED SIZED PLANS WILL NOT CONFORM TO STANDARD SCALES. IN MAKING MEASUREMENTS ON REDUCED PLANS, THE ABOVE SCALES MAY BE USED.

CUNITACI NO. 10348				
SECTION	COUNTY	TOTAL	SHEET NO.	
	CHARACTER		_	

TO STA.

FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT • (10-78-1 & 10-7VB)I

INDEX OF SHEETS

SHEET NO.	ITEM
1	COVER SHEET
2	INDEX OF SHEETS
2	LIST OF HIGHWAY STANDARDS
2	GENERAL NOTES
3	SUMMARY OF QUANTITIES
4	PLAN VIEW FOR S. N. 010-0030 & S. N. 010-0032
5	STAGE CONSTRUCTION TRAFFIC CONTROL FOR S. N. 010-0030
6-7	BRIDGE OFFICE PLANS FOR S.N. 010-0030
8-9	BRIDGE OFFICE PLANS FOR S.N. 010-0032

STANDARD NUMBER	NAME OF STANDARD
000001-04	STANDARD SYMBOLS, ABBREVIATIONS AND PATTERNS
001001	AREAS OF REINFORCEMENT REBARS
001006	DECIMAL OF AN INCH AND OF A FOOT
701400-02	APPROACH TO LANE CLOSURE, FREEWAY/EXPRESSWAY
701401-03	LANE CLOSURE, FREEWAY/EXPRESSWAY
701406-04	LANE CLOSURE, FREEWAY/EXPRESSWAY, DAY OPERATIONS ONLY
702001-06	TRAFFIC CONTROL DEVICES

LIST OF STANDARDS

GENERAL NOTES

PLAN DIMENSIONS AND DETAILS RELATIVE TO THE EXISTING STRUCTURES HAVE BEEN TAKEN FROM EXISTING PLANS AND ARE SUBJECT TO NOMINAL CONSTRUCTION VARIATIONS. IT SHALL BE THE CONTRACTOR'S RESPONSIBILITY TO VARIFY SUCH DIMENSIONS AND DETAILS IN THE FIELD AND MAKE NECESSARY APPROVED ADJUSTMENTS PRIOR TO CONSTRUCTION OR ORDERING OF MATERIALS. SUCH VARIATIONS SHALL NOT BE CAUSE FOR A CHANGE IN SCOPE OF WORK. HOWEVER, THE CONTRACTOR WILL BE PAID FOR THE QUANTITY ACTUALLY FURNISHED AT THE UNIT PRICE BID FOR THE WORK.

G. N. - 100

ENGLISH UNITS OF MEASUREMENT SHALL GOVERN OVER AND SUPERSEDE ANY METRIC UNITS SHOWN IN THIS CONTRACT. WHERE INCLUDED, METRIC UNITS ARE FOR INFORMATION ONLY.

RTE.	SECTION	C	OLINTY	SHEETS	NO.
74	•	СН	AMPAIGN	9	3
STA.	-,	TO S	TA.		
CCD DOU	מא דפות	tunte !	CO 410	AGO IFAT	,

· (10-78-1 & 10-7VB)]

SUMMARY OF QUANTITIES

LOCATION OF WORK:

FAI ROUTE 74 S. N. 010-0030 RURAL

FAI ROUTE 74 S.N. 010-0032 RURAL

STA. 738+42.00 STA. 740+02.00 STA. 857+24.75

STA. 858+91.25

FUNDING BREAKOUT:

100% STATE


100% STATE

CONSTRUCTION TYPE CODE:


SFTY-ZA

SFTY-ZA


CODE NO	ITEM	UNIT	TOTAL QUANTITY	OUANTITY	VTITMAUO
67100100	MOBILIZATION	L SUM	1.0	0. 7	0.3
70100700	TRAFFIC CONTROL AND PROTECTION, STANDARD 701406	L SUM	1.0		1.0
70100800	TRAFFIC CONTROL AND PROTECTION, STANDARD 701401	L SUM	1.0	1.0	
X0322194	POLYMER MODIFIED PORTLAND CEMENT MORTAR	SO FT	2.0	2.0	
X0322905	PPC I-BEAM REPAIRS	L SUM	1.0	0. 7	0. 3
X0323984	PORTABLE TEMPORARY BARRIER SYSTEM	FOOT	208.0	208. 0	
X7015005	CHANGEABLE MESSAGE SIGN	CAL DA	14.0	7. 0	7. 0




STAGE CONSTRUCTION TRAFFIC CONTROL S.N. 010–0030 W.B.



10 15 1 0 10 1





SCHEDULE

PORTABLE TEMPORARY BARRIER SYSTEM

STATION	OFFSET	ТО	STATION	OFFSET	LENGTH (FOOT)
	,	*******	***************************************		
739+26.00	3.00' RT.	ТО	740+30.00	3.00' RT.	104.0
740+30.00	3.00' RT.	TO	741+33.75	10.25' RT.	104.0

TOTAL = 208.0 FOOT

NOTES

STAGE CONSTRUCTION TRAFFIC CONTROL DETAIL SHALL BE USED IN CONJUNCTION WITH HIGHWAY STANDARDS 701400 AND 701401 FOR PPC I-BEAM REPAIRS ON STRUCTURE NUMBER 010-0030.

THE PORTABLE TEMPORARY BARRIER SYSTEM SHALL INCLUDE STEADY BURN MONODIRECTIONAL LIGHTS AND TYPE C MONODIRECTIONAL REFLECTORS FOR NIGHTTIME DELINEATION. THE SPACING SHOULD NOT EXCEED 20 FEET, BUT MAY VARY DEPENDING ON THE TYPE OF SYSTEM USED, NIGHTTIME DELINEATION WILL NOT BE PAID FOR SEPARATELY, BUT SHALL BE INCLUDED IN THE PRICE OF THE PORTABLE TEMPORARY BARRIER SYSTEM.

CHANGEABLE MESSAGE SIGNS SHALL BE IN PLACE ONE WEEK PRIOR TO THE START OF CONSTRUCTION AND MAY BE ADJUSTED TO MEET FIELD CONDITIONS.

THE RESIDENT ENGINEER AND TRAFFIC CONTROL SUPERVISOR WILL PROVIDE APPROPRIATE MESSAGE FOR THE CHANGEABLE MESSAGE SIGN.

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

TOTAL SMERT NO. 9 FEO, ROMO DIST. NO. 7

SHEET NO. I2 sheets

Contract Number: 70548


GENERAL NOTES

The contractor's proposed preloading system, with computations, sealed and signed by an Illinois Structural Engineer shall be submitted to the Bureau of Bridges and Structures for approval. The preloading system shall be placed


The preloading system shall not be paid for separately but will be included in the unit price for PPC-I Beam Repairs.

strength of 5,000 psi.

shortly after bridge closure for repairs.



ELEVATION



PLAN

- (A) Location of PPC I-Beam Repairs.
- (B) Location of PPC I-Beam Repairs with Pre-Loading
- © Location of Polymer Modified Portland Cement Mortar Repiar.

TOTAL BILL OF MATERIAL


ITEM	UNIT	QUANTITY
PPC I-Beam Repairs	L.S.	0.7
Polymer Modified Portland Cement Mortar	S.F.	2.0

PLAN AND ELEVATION F.A.I. RT 74 W.B. I-74 / SALT FORK RIVER CHAMPAIGN COUNTY SN 010-0030


DRAWN Drew Christopher



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION 10'-0"




Contract Number: 70548




ELEVATION BEAM 8

(Looking North)

Existing draped strands at end of PPC I-Beam



SUGGESTED FORM DETAIL



Existing draped strands at center of PPC I-Beam 4 Spa at 4" = 1'-4 See Detail A 3 Spa at 7 Spa at

−@ Beam

SECTION A-A PATCHING DETAIL

REPAIR PROCEDURES FOR BEAM 8 (SPANS 1 AND 3)

7 PPC I Beam Spaces at 5'-3" = 36'-9'

Note A:

CROSS SECTION SPANS 1 AND 3

(4)

PPC I-Beams to be repaired as detailed.

(5)

12'-0"

1. The damaged area of the beam shall be cleaned of all loose and spalled concrete, and sealant. Hand tools shall be used for the removal of concrete adjacent to the prestressing strands. While a 15 pound chipping hammer may be used away from prestressing strands, extreme care shall be taken not to damage the exposed prestressing strands. Any exposed portions of the strands shall be sandblasted.

2. Using the same tools, remove the existing concrete to sound concrete along the edges of the damaged area to a depth of 1" min. to 1^l_2 " max. The edges shall be saw cut $\frac{3}{4}$ " deep or less.

3. Power driven pins as shown in Detail A shall be placed at 9" alternate centers along damaged length of beam at locations shown in Detail A. Use wire ties in areas where the strands are exposed as shown in Detail A. Place 1" x 1" x 18 gauge welded wire fabric in repair areas and attach it to the pins or strands with wire ties. The clearance between the finished surface of the new concrete and the welded wire fabric shall be 1" minimum. All beams involved in this work shall be rebuilt to their original dimensions.

4. All surfaces of existing concrete and reinforcing strands in the area to be repaired shall be coated with an epoxy-resin primer bonding agent. The concrete beam to be repaired or crack sealed must be at a temperature of at least 50° F. or higher. All other minor mortar repair, crack sealing, or surface sealing of gouges on the beam shall be performed as directed by the Engineer.

5. The repair shall be made using a concrete meeting all the requirements

specified in Section 1020 of the Standard Specifications for Class PS Concrete for precast prestressed concrete members, except the maximum size of the aggregate shall be l_2 ". Place the lower form on the bottom of the beam and compact by vibrating (or other approved methods) the concrete mix into the voids. After accessible voids have been filled and compacted, the top vertical form shall be raised into position and the remaining voids filled and compacted. The sloping upper surface shall be finished to the configuration of the existing PPC I-Beam flange.

MAY 8, 2006 DESIGNED V.H.V. CHECKED S.J.B.

CHECKED V.H.V. S.J.B.

PRELOADING FOR PPC I-BEAM REPAIRS

(Service Moment)

SOUTH FASCIA

Distance

35′-0"

From

Abutment

5′-0"

See Note A

2'-10"

DRAWN **Drew Christopher**

ELEVATION BEAM 8

(Looking South)

Moment

(kip-ft)

490

12'-0"

6

- Area of Polymer Modified

Portland Cement Mortar

ℚ Roadway -

The cost of concrete removal, Class PS Concrete, power driven pins, wire ties, wire mesh, epoxy bonding agent, Epoxy Crack Sealing and all other work required to perform repairs on Beam 8 in Spans 1 and 3 shall be included in the cost of P.P.C. I Beam Repairs.


PPC -BEAM REPAIR DETAILS F.A.I. RT 74 W.B. I-74 / SALT FORK RIVER CHAMPAIGN COUNTY SN 010-0030


2 Spa at

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

PEO, HOMO DIST. NO. 7 SALEMENT FED, HIGH PROJECT.

Contract Number: 70548





PLAN

(A) Location of PPC I-Beam Repairs.

For repair procedure see sheet 2 of 2.

TOTAL BILL OF MATERIAL

ITEM	UNIT	QUANTITY
PPC I-Beam Repairs	L.S.	0.3

PLAN AND ELEVATION

F.A.I. RT 74

W.B. I-74 / U.P. RAILROAD

CHAMPAIGN COUNTY

SN 010-0032

DESIGNED Victor H. Velo May 8, 2006

CHECKED Ato CHIEF DOWN A. Morrie

DRAWN Drew Christopher

CHECKED SJB/VHV

CHECKED SJB/VHV



Expires: November 30, 2006

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

(3)

10'-0"

2

³₈" Power driven pins spaced to miss strands.

1" x 1" - 18 ga.

Welded Wire Fabric

(Typ.)

Wire ties to exposed

cables and anchors

12'-0"

SHEET NO. SHEET NO. 2TOTAL SHEETS 9 9 2 SHEETS Champaian

Contract Number: 70548



 3_{Δ} " Chamfer (Typ.)

Side form in lowered position.

1'-6"

Hinges


3 3 3 3 3 3

DETAIL A

SUGGESTED FORM DETAIL

4'-0" © Brg. W. Abut. 4'-0"

> **ELEVATION BEAM 8** (Looking North)



SECTION A-A

PATCHING DETAIL

The cost of concrete removal, Class PS Concrete, power driven pins, wire ties, wire mesh, epoxy bonding agent, Epoxy Crack Sealing and all other work required to perform repairs on Beam 8 in Span 1 shall be included in the cost of P.P.C. I Beam Repairs.

5′-0"

See Note A

2'-10"

(8)

12'-0"

6

CROSS SECTION SPAN 1 Note A: PPC I-Beams to be repaired as detailed.

7 PPC I Beam Spaces at 5'-3" = 36'-9'

(4)

(5)

REPAIR PROCEDURES FOR BEAM 8

- 1. The damaged area of the beam shall be cleaned of all loose and spalled concrete, and sealant. Hand tools shall be used for the removal of concrete adjacent to the prestressing strands. While a 15 pound chipping hammer may be used away from prestressing strands, extreme care shall be taken not to damage the exposed prestressing strands. Any exposed portions of the strands shall be sandblasted.
- 2. Using the same tools, remove the existing concrete to sound concrete along the edges of the damaged area to a depth of 1" min. to $1\frac{1}{2}$ " max. The edges shall be saw cut $\frac{3}{4}$ " deep or less.
- 3. Power driven pins as shown in Detail A shall be placed at 9" alternate centers along damaged length of beam at locations shown in Detail A. Use wire ties in areas where the strands are exposed as shown in Detail A. Place 1" x 1" x 18 gauge welded wire fabric in repair areas and attach it to the pins or strands with wire ties. The clearance between the finished surface of the new concrete and the welded wire fabric shall be 1" minimum. All beams involved in this work shall be rebuilt to their original dimensions.
- 4. All surfaces of existing concrete and reinforcing strands in the area to be repaired shall be coated with an epoxy-resin primer bonding agent. The concrete beam to be repaired or crack sealed must be at a temperature of at least 50° F or higher. All other minor mortar repair, crack sealing, or surface sealing of gouges on the beam shall be performed as directed by the Engineer.
- 5. The repair shall be made using a concrete meeting all the requirements specified in Section 1020 of the Standard Specifications for Class PS Concrete for precast prestressed concrete members, except the maximum size of the aggregate shall be $\frac{1}{2}$ ". Place the lower form on the bottom of the beam and compact by vibrating (or other approved methods) the concrete mix into the voids. After accessible voids have been filled and compacted, the top vertical form shall be raised into position and the remaining voids filled and compacted.

MAY 8, 2006 DESIGNED V.H.V. CHECKED S.J.B. PASSED DRAWN Drew Christopher CHECKED V.H.V. S.J.B.

PPC -BEAM REPAIR DETAILS F.A.I. RT 74 W.B. I-74 / U.P. RAILROAD CHAMPAIGN COUNTY SN 010-0032