

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

	FILE NAME = .	USER NAME = leyse .	DESIGNED -	REVISED ~ J.A.F. 04-03		SIGNING FOR FLAGGING OPERATIONS	F.A.T.	SECTION CO	OUNTY TO	OTAL SHEET
	W:\diststd\22x34\tc18.dgn		DRAWN -	REVISED - J.A.F. 02-06	STATE OF ILLINOIS		K7 14	114.2B Co	JIIL	516 202
		PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED - S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION	AT WORK ZONE OPENINGS		2-18 CON	NTRACT N	0 60727
l		PLOT DATE = 1/26/2010	DATE -	REVISED - S.P.B. 12-09		SCALE: NONE SHEET NO. 1 OF 1 SHEETS STA. TO STA.	FED. ROAD DIST. NO	O. 1 ILLINOIS FED. AID PRO	JECT IV	0.00321