

## DRIVEWAY PAVEMENT REMOVAL AND RESTORATION

CONTRACT NO. 83981

TYPICAL CROSS SECTION OF MADISON STREET FROM ARDMORE AVENUE TO VILLA AVENUE STA. 30+48 TO STA. 57+12



### TYPICAL CROSS SECTION OF MADISON STREET FROM VILLA AVENUE TO ILLINOIS ROUTE 83 WEST FRONTAGE ROAD STA. 57+57 TO STA. 77+48



# VILLAGE OF VIL ENGINEERING DIVISION 20 SOUTH ARDMORE AVENUE VILLA PARK, ILLINOIS 60181-2696

VILLAGE OF VILLA PARK

VILLAGE OF VILLA PARK

ENGINEERING DIVISION

VYDAS JUSTICUS, P.E. - VILLAGE BYOMEER

20 SOUTH ARDMORE AVENUE

PHONE (630) 834-8505

FAX (630) 834-8509

VILLAGE OF VILLA PARK, ILLINOIS

TYPICAL SECTIONS

(70)/09


DETAILS

MADISON STREET

SHEET 2 OF 2

SCALE: NONE DRAWN BY: K.L.M.
DATE: 11/07/2007 CHECKED BY: V.I.V.

#### PLAN



#### NOTES

- I. ALL DRIVEWAYS SHALL BE IN ACCORDANCE WITH ILLINOIS DEPARTMENT OF TRANSPORTATION (IDOT) DISTRICT I STANDARD DETAILS BD-01 (DRIVEWAY DETAILS DISTANCE BETWEEN R.O.W. AND FACE OF CURB \$\frac{1}{2}\$ EDGE OF SHOULDER >= 15') AND BD-02 (DRIVEWAY DETAILS DISTANCE BETWEEN ROW AND FACE OF CURB \$\frac{1}{2}\$ SHOULD ANY DISCREPANCIES EXIST BETWEEN THIS DETAIL AND THE IDOT DISTRICT I STANDARD DETAILS REFERENCED, THE IDOT STANDARD DETAILS SHALL GOVERN.
- 2. ALL SUBBASE GRANULAR MATERIAL SHALL BE MECHANICALLY COMPACTED.
- 3. CONTRACTOR SHALL MATCH ANY EXISTING TROWEL JOINTS AND CONTRACTION JOINTS WHEN RESTORING PORTLAND CEMENT CONCRETE DRIVEWAYS.

#### SECTION

