STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



DECK REPAIRS

NOTE "A"

Four pipe hangers supporting the conduit connected to the bottom of the deck are within the repair area. These Pipe hangers shall be re-installed, either by reattachment prior to forming the concrete repair, or by relocation to a portion of the existing deck within two feet of the repair area. Cost included with Deck Slab Repair (Full Depth, Type I).

NOTES:

For Expansion Joint Reconstruction Details, See Sht's. S8 thru S13. For Approach Siab Repairs, see Sht's. S14 & S15. Areas of Deck Repairs shown are estimated. The Engineer shall show actual locations of Deck Repairs on As-Built Plans. During Full Depth Repair over Scuppers, the Contractor must not disturb or damage the existing beams beneath the drainage scuppers.



 DESIGNED 2010

 CHECKED EXAMINED
 ENDINCER OF BRIDGE DESIGN

 DRAWN PASSED
 ENDINCER OF BRIDGE AND STRUCTURES

 CHECKED ENDINCER OF BRIDGES AND STRUCTURES

