STATE OF ILLINOIS

DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS

PROPOSED HIGHWAY PLANS

FAI ROUTE 80 (I-80) SECTION (81–1B)M–4

C-92-192-09



ROCK ISLAND COUNTY

TRAFFIC VOLUMES: I-80

 \bigcirc


FOR INDEX OF SHEETS, SEE SHEET NO. 2 FOR STATE STANDARDS, SEE SHEET NO. 2

CURRENT ADT: 30,300 (2007) 33% TRUCKS

IMPROVEMENT BEGINS STA. 1440 + 00

SECTION BEGINS STA. 16 + 65.99

STA EQUATION = IOWA STA 1497 + 80.00 = IL STA 16+69.53



FULL SIZE PLANS HAVE BEEN PREPARED USING STANDARD ENGINEERING SCALES. REDUCED SIZED PLANS WILL NOT CONFORM TO STANDARD SCALES. IN MAKING MEASUREMENTS ON REDUCED PLANS, THE ABOVE SCALES MAY BE USED.

JOINT UTILITY LOCATION INFORMATION FOR EXCAVATION


PROJECT ENGINEER: REBECCA MARRUFFO PROJECT MANAGER: ED CONDERMAN (815)-284-5947 HAMPTON TOWNSHIP, SECTION 10, 11, 14

CONTRACT NO. 64F31

FAI 80 (I-80)

SECTION (81--1B)M-4

NET LENGTH OF IMPROVEMENT = 3,487 FEET = 0.66 MILES GROSS LENGTH OF IMPROVEMENT = 3,487 FEET = 0.66 MILES




D-92-094-09

SECTION ENDS STA. 51 + 52.83

LOCATION OF SECTION INDICATED THUS: -

IMPROVEMENT ENDS STA. 85 + 50



PRINTED BY THE AUTHORITY OF THE STATE OF ILLINOIS

ROCK ISLAND

INDEX OF SHEETS AND STANDARDS

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

INDEX

1	COVER SHEET
2	INDEX OF SHEETS AND STANDARDS
3 - 4	SUMMARY OF QUANTITIES
5	GENERAL NOTES
6 - 8	TYPICAL SECTIONS
9 - 10	SCHEDULE OF QUANTITIES
11	SEQUENCE OF WORK
12 - 27	STAGING DETAILS
28 - 60	STRUCTURE SHEETS
61 - 63	44" CONCRETE BARRIER WALL - DETAIL
64	STAGING SIGN DETAILS
65	CONCRETE BARRIER TRANSITION
66 - 67 : 68	SLIDING PLATE DETAIL STA. 52+86 DELINEATION OF CENTER BARRIER (DIST STD 25.4)
90	
	ROAD CLOSED TO OVERSIZED LOADS (DIST STD 40.4)
	TYPICAL MEDIAN CROSSOVER CLOSURE (WITH EMERGENCY OPENING) (DIST STD 87.4)
69	EROSION CONTROL DETAILS FOR SILT FENCE (DIST STD 29.2)
	INFORMATINOAL WARNING SIGN (FOR NAROW TRAVEL LANES) (DIST STD 39.2)
70	TRAFFIC CONTROL & PROTECTION AT TURN BAYS (DIST STD 94.2)
71	TRAFFIC CONTROL TYPICAL WEAVE (DIST STD 39.1)
72 - 74	TYPICAL PAVEMENT MARKINGS (DIST STD 41.1)
75	PAINTING DETAILS (DIST STD 44.1)

STATE STANDARDS

000001-05	Standard Symbols, Addreviations and Patterns
001001-02	Areas of Reinforcement Bars
001006	Decimal Equivalents of an Inch and of a foot
280001-04	Temporary Erosion Control Systems
635011-02	Reflector Marker and Mounting Details
637006-02	Concrete Barrier 1065 mm (42 in.) Height
638001-02	Glare Screen Blades
701101-02	Off-Road Operations, Multilane, 4.5 m (15′) to 600 mm (24*) From
701106-02	Off-Road Operations, Multilane, More Than 4.5 m (15') Away
701400-03	Approach to Lane Closure, Freeway/Expressway
701401-05	Lane Closure, Freeway/Expressway
701411-05	Lane Closure, Multilane, at Entrance or Exit Ramp, for Speeds ≥ 45
701416-06	Lane Closure, Freeway/Expressway, with Crossover and Barrier
701426-03	Lane Closure, Multilane, Intermittent or Moving Operation, for
701451	Ramp Closure Freeway/Expressway
701901-01	Traffic Control Devices
704001-05	Temporary Concrete Barrier
780001-02	Typical Pavement Markings
781001-03	Typical Applications Raised Reflective Pavement Markers

		The state of the s	
FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED -
c:\pw_work\pwidot\cushmanbw\d0149192\d09	409-sht-schedule.dgn	DRAWN -	REVISED -
	PLOT SCALE = 50.0000 '/ [N.	CHECKED -	REVISED -
	PLOT DATE = Thu Sep 17 09:51:35 2009	DATE	REVISED -

INDEX	0F	SH	IEET	S AN	D	STANDARDS
.E:	SHEET	NO.	OF	SHEETS	STA.	TO STA.

F.A.I. RTE.	SECTION		СО	UNTY	TOTAL SHEETS	SHEET NO.
80	(81-IB) M-4		ROCK	ISLAND	75	2
			CO	NTRAC	T NO. 6	64F31
	ILLINOIS	FED. A	ID PROJ	ECT		

SUMMARY OF QUANTITIES

AY CODE #	LONG DESCRIPTION	LINITE	OLIANTITIES	100% ST	BRIDGE
AT CODE	LONG - DESCRIPTION -	UNITS	QUANTITIES	J000	SFTY-2A
25100630	EROSION CONTROL BLANKET	SQ YD	45.00	45.00	
28000400	PERIMETER EROSION BARRIER	FOOT	150.00	150.00	
44000157	HOT-MIX ASPHALT SURFACE REMOVAL, 2"	SQ YD	374.00	374.00	
48203005	HOT-MIX ASPHALT SHOULDERS, 2"	SQ YD	374.00	374.00	
5010240 0	CONCRETE REMGV AL	CU YD	427.20		427.
50104650	SLOPE WALL REMOVAL	SQ YD	11.70		11.
50157300	PROTECTIVE SHIELD	SQ YD	6 ,123. 00		6,123.
50300255	CONCRETE SUPERSTRUCTURE	CU YD	611.60		611.
50300260	BRIDGE DECK GROOVING	SQ YD	1,479.00		1,479.
50300300	PROTECTIVE COAT	SQ YD	2,224.00		2,224.
50500105	FURNISHING AND ERECTING STRUCTURAL STEEL	L SUM	1.00		1.
50500505	STUD SHEAR CONNECTORS	EACH	4,312.00		4,312.
50501110	STRUCTURAL STEEL REMOVAL	POUND	155,620.00		155,620.
50501130	STRUCTURAL STEEL REPAIR	POUND	211,520.00		211,520.
50606701	CLEANING AND PAINTING STRUCTURAL STEEL, LOCATION 1	L SUM	1.00		1.
50800105	REINFORCEMENT BARS	POUND	10,108.00	10,108.00	
50800205	REINFORCEMENT BARS, EPOXY COATED	POUND	16 7,32 0.00		167,320.
51100100	SLOPE WALL 4 INCH	SQ YD	11.70		11.
52000110	PREFORMED JOINT STRIP SEAL	FOOT	1,636.00		1,636.
52100010	ELASTOMEREC BEARING ASSEMBLY, TYPE 1	EACH	100.00		100.6
59200100	BRIDGE WASHING	EACH	1.00		1.
63700275	CONCRETE BARRIER, DOUBLE FACE, 42 INCH HEIGHT	FOOT	1,398.00	1,398.00	
63700805	CONCRETE BARRIER TRANSITION	FOOT	20.00	20.00	
63801205	TEMPORARY MODULAR GLA re S CRE EN	FOOT	1,200.00	1,200.00	. *
67000400	ENGINEER'S FIELD OFFICE, TYPE A	CAL MO	16.00		16.
67100100	MOBILIZATION	L SUM	1.00		1.
70100205	TRAFFIC CONTROL AND PROTECTION, STANDARD 701401	EACH	5.00	5.00	
70100410	TRAFFIC CONTROL AND PROTECTION, STANDARD 701416	EACH	1.00	1.00	
70100420	TRAFFIC CONTROL AND PROTECTION, STANDARD 701411	EACH	1.00	1.00	
70100820	TRAFFIC CONTROL AND PROTECTION, STANDARD 701451	L SUM	1.00	1.00	
	CHANGEABLE MESSAGE SIGN	CAL MO	172.00	172.00	

* SPECIALITY TIEMS

FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED -
c:\pw_work\PWIDOT\CUSHMANBW\dØ149192\d@	9409-sht-schedule.dgn	DRAWN -	REVISED -
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED
	PLOT DATE = Thu Sep 17 13:13:51 2009	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

	S	UMMA	RY	0F	Q	UAN'	TITIES	,
F.		SHEET NO.	OF	SHEE	TS	STA	7	O STA

F.A.I. RTE.	SECT	ION		C	YTMUC	TOTAL SHEETS	SHEE NO.
80	(81-1B) M-4		ROCK	ISLAND	75	3
				CO	ONTRAC	T NO.	64F31
		ILLINOIS	FED.	AID PRO	JECT		
	F.A.I. RTE. 80	80 (81-18	107.107	80 (81-1B) M-4	80 (81-1B) M-4 ROCK	80 (81-1B) M-4 ROCK ISLAND	80 (81-1B) M-4 ROCK ISLAND 75 CONTRACT NO. (

SUMMARY OF QUANTITIES

				100% \$7	
PAY CODE #	LONG DESCRIPTION	UNITS	QUANTITIES	ROADWAY JOOO	BRIDGE SFTY-2A
70300625	TEMPORARY PAINT PAVEMENT MARKING LINE 4"	FOOT	41,420.00	41,420.00	
70300635	TEMPORARY PAINT PAVEMENT MARKING LINE 6"	FOOT	96.00	96.00	
70300645	TEMPORARY PAINT PAVEMENT MARKING LINE 12"	FOOT	492.00	492.00	
70301000	WORK ZONE PAVEMENT MARKING REMOVAL	SQ FT	18,162.00	18,162.00	
70400100	TEMPORARY CONCRETE BARRIER	FOOT	6,245.00		6,245.0
70400200	RELOCATE TEMPORARY CONCRETE BARRIER	FOOT	1,618.00		1,618.0
70400600	RELOCATE TEMPORARY CONCRETE BARRIER (STATE OWNED)	FOOT	2,581.00	2,581.00	
78008210	POLYUREA PAVEMENT MARKING TYPE I - LINE 4"	FOOT	20,272.00	20,272.00	· · · ·
78008230	POLYUREA PAVEMENT MARKING TYPE I - LINE 6"	FOOT	4,094.00		
	POLYUREA PAVEMENT MARKING TYPE I - LINE 8"			4,094.00	
78008240		FOOT	4,079.00	4,079.00	
78008250	POLYUREA PAVEMENT MARKING TYPE I - LINE 12"	FOOT	1,333.00	1,333.00	
78008310	POLYUREA PAVEMENT MARKING TYPE II - LINE 4"	FOOT	13,932.00	13,932.00	
78008330	POLYUREA PAVEMENT MARKING TYPE II - LINE 6"	FOOT	1,742.00	1,742.00	
78100105	RAISED REFLECTIVE PAVEMENT MARKER (BRIDGE)	EACH	86.00	86.00	
78200100	MONODIRECTIONAL PRISMATIC BARRIER REFLECTOR	EACH	339.00	339.00	
78200200	BIDIRECTIONAL PRISMATIC BARRIER REFLECTOR	EACH	222.00	222.00	
78300100	PAVEMENT MARKING REMOVAL	SQ FT	7,000.00	7,000.00	
Z0021400	EXPANSION JOINT (SPECIAL)	FOOT	233.00		233.0
Z0030260	IMPACT ATTENUATORS, TEMPORARY (FULLY REDIRECTIVE, NARROW), TEST LEVEL 3	EACH	1.00	1.00	
Z0031300	JACKING AND CRIBBING	L SUM	1.00		1.0
Z0073500	TEMPORARY SUPPORT SYSTEM	L SUM	1.00		1.0
XX002866	CONCRETE BARRIER WALL (SPECIAL)	CU YD	84.00	84.00	
XX004656	EMBANKMENT	CU YD	6,30	04.00	6.3
X0321781	MECHANICAL SPLICE	EACH	10,228.00		
X0323644	PAVEMENT MARKING GROOVING	FOOT	15,674.00	1E C74 00	10,228.0
	IMPACT ATTENUATORS (FULLY RED)RECTIVE, NARROW), TEST LEVEL 3, SPECIAL			15,674.00	
X0325194		EACH	1.00	1.00	
X0325305	STRUCTURAL REPAIR OF CONCRETE (DEPTH EQUAL TO OR LESS THAN 5 INCHES)	SQ FT	11.60	11.60	
X0325939	IMPACT ATTENUATORS, TEMPORARY (FULLY REDIRECTIVE, NARROW), TEST LEVEL 3, SPECIAL	EACH	1.00	1.00	
X7011015	TRAFFIC CONTROL AND PROTECTION (EXPRESSWAYS)	L SUM	1.00	1.00	
X0326720	MECHANICAL TREATMENT OF WELDS	EACH	828.00		828.0
X0326721	FIELD WELDING OF STIFFENERS	EACH	828.00		828.0
		1		1	

CHECKED

REVISED

PLOT SCALE = 50.0000 '/ IN.

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

	S	UMMA	RY	OF C	UANI	TITIES	
SCALE:		SHEET NO.	OF	SHEETS	STA.	TO	STA

-	F.A.I. RTE.	SECT	ION		co	UNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1E) M-4	F	ROCK	ISLAND	75	4
					CO	NTRAC	T NO.	54F31
			ILLINOIS FEE	. AID	PRO.	JECT		

GENERAL NOTES

The Contractor shall seed all disturbed areas within the project limits. Seeding Class 4 or 2A shall be used. Class 2A shall be used on front slopes and ditch bottoms. Class 4 shall be used on all backslopes and areas behind the backslope, and beyond the toe of front slope on fill sections without ditches. This work will be included in the contract unit price per Square Yard for SLOPE WALL 4".

Fertilizer shall be applied to all disturbed areas and incorporated into the seedbed prior to seeding or placement of sod at the rate specified in Sections 250 and 252 of the Standard Specifications. This work shall be included in the cost of SLOPE WALL 4".

Mulch Method II shall be applied over all seeded areas. This shall be included in the cost of the SLOPE WALL 4".

The following Mixture Requirements are applicable for this project:

Mixture Uses(s):	Top Shoulder	Bottom Shoulder
PG:	PG 58-22	PG 58-22
Design Air Voids	3 @ N90	2 @ N90
Mixture Composition	IL 9.5 or 12.5	BAM
(Gradation Mixture)		
Friction Aggregate	D	N/A
20 Year ESAL	N/A	N/A
Mix Unit Weight	112 lbs/sy/in	

Bituminous and Aggregate prime coat shall be placed in accordance with Section 406 of the Standard Specifications. The cost of the prime coats shall be included in the contract unit price per Square Yard for HOT-MIX ASPHALT SHOULDERS, 6".

in the state of the state of

and the second of the second o

ia is casa sagi i **Signa fil**adi di Signa di Pasa. Piliti i evo pundi i **Signa** di Chara (Piliti i Nacionali Chara) (C

The same with the contract of the con-

This structure will retain the same number 081-0011.

The contractor shall submit four copies of the required shop drawings for review and approval to the Bureau of Bridges and Structures, 2300 South Dirksen Parkway, Springfield, IL 62764. After approval of initial submittal, the contractor shall submit one set of shop drawings to Dave Lippert, Engineer of Materials, 126 East Ash Street, Springfield, IL 62704, and eight (8) sets of shop drawings to be distributed to:

District 2 District Engineer (1)
Fabricator (1)
Contractor (2)
Resident Engineer (2)
District 2 Bureau of Materials (2)

At bridge expansion joints, if temporary expansion joint bulkheads are attached to adjacent deck slabs or abutments for support, the Contractor shall cut the attachments as soon as the concrete has set to prevent joint damage due to horizontal contraction or expansion.

The Contractor shall sandblast the top of the beams upon removal of the bridge deck. This work will be included in the cost of removing the bridge deck.

Work on this project will be in progress at the same time as work on the adjacent I-80 roadway reconstruction project and I-74 bridge and pavement repairs. Work on these projects shall be scheduled to keep interference between all the projects to a minimum. The contractors shall inform each other of progress of the projects and give fair warning to the other contractors when a problem might be encountered.

The Contractor shall be responsible for protecting utility property during construction operations as outlined in Article 107.31 of the Standard Specifications. A minimum of 48 hours advance notice is required for non-emergency work. The JULIE number is 800-892-0123. The following listed utilities located within the project limits or immediately adjacent to the project construction limits are members of JULIE:

AT&T Communications Frontier/Citizens Mediacom Lightcore Rapids City Village Office

MidAmerican Energy Co. McLeod USA City of East Moline Iowa Network Services, Inc.

Following are the known utilities located within the project limits or immediately adjacent to the project construction limits which are not members of JULIE and should be notified individually by the contractor:

Mr. Kyle Lorenz IDOT – District 2 819 Depot Avenue Dixon, IL 61021 Ph. 815/284-5469

The Contractor shall not use the lowa Ramp Infields for any project activity.

The Contractor shall not use the IL 84 Ramp Infields for any project activities without prior written approval by the District Construction Engineer.

The Contractor shall replace the median crossover (Sta. 82+50) closure components (posts, cable, panels) to that shown in the District Two Standard 98.4, TYPICAL MEDIAN CROSSOVER CLOSURE. This work shall be included in the various traffic control pay items and no additional compensation will be allowed.

Partial depth saw cuts on face of barrier wall(s) shall be 1 inch in depth. This work shall be included in the various barrier wall pay items.

Temporary Concrete Barrier Wall shall not be pinned to new continuously reinforced concrete pavement without prior written approval of the Engineer.

Temporary Impact Attenuators shall not be anchored to the new continuously reinforced concrete pavement without prior written approval of the Engineer.

	USER NAME =	DESIGNED - Engineering Systems	REVISED -			_					ROUTE	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
ELE NAME - 64E21 ON DOCY		DRAWN -	REVISED -	STATE OF ILLINOIS		G	BENE	ERAL N	OTES		FAI 80	(81-1B)M-4	Rock Island	75	5
THE NAME - OFFICINDOCK	PLOT SCALE = :	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION	***	-					(l-80)		CONTRACT N	iO. 64F31	
	PLOT DATE = 9/17/2009 9:51 AM	DATE - 9/8/2009 9:19 AM	REVISED -		SCALE:	SHEET NO.	OF	SHEETS	STA.	TO STA.		ILLINOIS	FED. AID PRO	JJECT	

STAGE I - BRIDGE SECTION TYPICAL

(Looking from Iowa to Illinois)

WESTBOUND

DRAWN

DATE

CHECKED

PLOT SCALE = 100,0000 '/ IN.

REVISED


EASTBOUND

STAGING TYPICAL

TO STA.

SHEET NO. OF SHEETS STA.

SCALE:



STATE OF ILLINOIS

DEPARTMENT OF TRANSPORTATION

STAGE II – BRIDGE SECTION TYPICAL

(Looking from Iowa to Illinois)

WESTBOUND

CHECKED

DATE

PLOT DATE = Thu Sep 17 09:13:53 2009


REVISED

REVISED

EASTBOUND

CONTRACT NO. 64F31

FED. ROAD DIST. NO. | ILLINOIS FED. AID PROJECT



DEPARTMENT OF TRANSPORTATION

SCALE:

SHEET NO. OF SHEETS STA.


TO STA.

STAGE III – PERMANENT BRIDGE PAVEMENT MARKINGS

(Looking from Iowa to Illinois)

WESTBOUND

EASTBOUND



FILE NAME = DESIGNED - EEC REVISED SECTION DRAWN -EEC REVISED STATE OF ILLINOIS STAGING TYPICAL (81-1 B) M-4 ROCK ISLAND 75 PLOT SCALE = 100.0000 '/ IN. CHECKED REVISED **DEPARTMENT OF TRANSPORTATION** CONTRACT NO. 64F31 PLOT DATE = Thu Sep 17 09:14:05 2009 DATE REVISED SCALE: SHEET NO. OF SHEETS STA. TO STA. FED. ROAD DIST. NO. | ILLINOIS | FED. AID PROJECT

SCHEDULE OF QUANTITIES

70300635 TEMPORARY PAINT PAVEMENT MARKING LINE 6"

							S []
25100630	EROSION CONTROL B						UUI
	SO YD	LOCATION		17 : 22	CLODE WALL CT:-	- OF 10	
	45.00 TO	16 + 69 TAL	†o	17 + 20	SLOPE WALL - STAT	L OF IOWA	
	40.00 IC) I AL					
28000400	PERIMETER EROSION						
	EOOI	LOCATION		47 . 00	CLODE WALL CTAT		
	150.00 TO	16 + 69 TAL	†o	17 + 20	SLOPE WALL - STAT	E OF IOWA	second to the
	150.00) I AL					1000
14000157	HOT-MIX ASPHALT S		2"				
	SQ_YD	LOCATION				REM	
	373.33 373.33 TO	1492 + 00 TAL	to	1497 + 60	6' wide, see specie	ıl provisi	on
	313.33	TAL					
18203005	HOT-MIX ASPHALT S						
	SO YD	LOCATION				REM	
	373.33 373.33 TO	1492 + 00 TAL	to	1497 + 60	SEE GENERAL NOTES	FOR MIX	DESIGN
	313,33	TAL					
0800105	REINFORCEMENT BAR						
	POUNDS	LOCATION			REMARKS		
	10108.00	1492 + 00		1497 + 60	State of IOWA bar	rier wall	
	10,108.00 TC)TAL					
3700275	CONCRETE BARRIER,	DOUBLE FACE. 42	INCH	HEIGHT			
	FOOT	LOCATION				REM	ARKS
		STAGE THREE					
	1397.50	51 + 72		65 + 69.50			\$4000
	1,397.50 TC	TAL					
3700805	CONCRETE BARRIER	TRANSITION					
	FOOT	LOCATION				REM	ARKS
		STAGE THREE					
	20.00	51 + 52		51 + 72.00			
	20.00 TO	TAL					
3801205	TEMPORARY MODULA	R GLARE SCREEN				A Company	
	FOOT	LOCATION				REM	ARKS
		STAGE TWO					-
	600.00	1494 + 00		18 + 89.53	IOWA STA 1497+80 =	IL STA 16	5+69.53
	600,00	82 + 00		88 + 00			
	1,200 TO	TAL					
0300625	TEMPORARY PAINT P		LINE 4'	,			
	EQQI	LOCATION				REMA	ARKS
	2225 00	EASTBOUND	4-	1/17E + 25	Stace I V-II-	33 oldo	
	2225 . 00 1025 . 00	1453 + 00 75 + 25	to to	1475 + 25 85 + 50	Stage I - Yellow in: Stage I - White CL	5100	
	770.00	77 + 80	to	85 + 50	Stage I - White ou	tside	
	770.00	77 + 80	to	85 + 50	Stage I - Yellow in		
	1320.00	77 + 80	to	91 + 00	Stage I - Yellow, S	cenic ove	rlook ramp
	1440.00	1483 + 00	†o	1497 + 40	Stage II- Yellow in		
	601,00	55 + 39 75 + 24	†o	61 + 40 85 + 50	Stage II - White or		8
	1026.00 770.00	75 + 24 77 + 80	to to	85 + 50 85 + 50	Stage II - White Cl Stage II - White o		
	770.00	77 + 80	†o	85 + 50	Stage II - Write or		
	1320.00	77 + 80	to	91 + 00	Stage II - Yellow I		erlook ramp
	7311.00	1483 + 00	to	75 + 00	Stage III - Yellow i		- 11 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
	19348.00 Sub-T						
	0070 00	WESTBOUND		44 : 74			gir egg och til
	2872.00	1497 + 00 47 + 62	†o	44 + 61 83 + 00	Stage I - White ou		
	3538.00 1618 . 00	47 + 62 77 + 82	†0 †0	83 + 00 94 + 00	Stage I - Yellow in: Stage I - White ou		1. July 1. S. C. C.
	1425.00	61 + 65	†0	75 + 90	Stage II - White or		
	2135.00	61 + 65	to	83 + 00	Stage II - Yellow in	side	
	1618.00	77 + 82	†o	94 + 00	Stage II - White or		
	6891.00	1491 + 20	to	79 + 00	Stage III - Yellow i	nside	
	20097.00 Sub-T	otd MISC					
	600.00	US 67 Eastbo	und		Stage I - Yellow		
	300.00	US 67 Westbo			Stage I - White		
	550.00	IL 84 Eastbou			Stage II - White		
	525.00	IL 84 Westbou	und		Stage II - Yellow	3.7	- A
	1975.00 Sub-T						+ 1 1
	41,420.0 TO	TAL				**	
	USER NAME = cushman	nbw	DESIG	NED "	REVISED -		
\dØ149192\d	09409-sht-schedule.dgn		DRAW		REVISED -		

CHECKED

REVISED

REVISED

FILE NAME =

	FOOT		MENT MARKING LOCATION	LINE 6		DCMARKS
	1.001					REMARKS
	06.50		EASTBOUND		55 . 30	
	96.50		51 + 53	to	55 + 39	Stage II - Turkey tracks, 2' long, 6' between - White
	96.50	TOTAL				
70300645	TEMPODARY	DAINT DAVE	MENT MARKING	1 THE 19/	,	
10300643	EOOT	FAINI FAVEN	LOCATION	LINE IZ		REMARKS
	5001		WESTBOUND			OCMADA3
	163.93		63 + 50	†o	73 + 20	Stage I - Diagonals, 16.9' long, 100' between - White
	163.93		63 + 50	†o	73 + 20	Stage II - Diagonals, 16.9' long, 100' between - White
	163.93		63 + 50	to	73 + 20	Stage III - Diagonals, 16.9' long, 100' between - White
	491.79	TOTAL	63 + 30	10	13 + 20	31age III - Diagonais, 16.3 long, 100 between - willte
	451.15	TOTAL				
70400100	TEMPORARY	CONCRETE BA	ARRIER			
	FOOT		LOCATION			REMARKS
			STAGE ONE			COMPANIE COM
	507.5		1491 + 93		1497 + 00	IN STATE OF IOWA
	80.0		1497 + 00		1497 + 80	IN STATE OF IOWA
	400.0		47 + 50		51 + 50	ILLINOIS
	748.0		51 + 50		59 + 00	ILLINOIS
	652.0		59 + 00		65 + 52	ILLINOIS
	2,387.5	Sub-Totd				
			STAGE TWO			
	175.0	ŧ	1496 + 05		1497 + 80	IN STATE OF IOWA
	32.5		16 + 69		17 + 00	ON BRIDGE
	3,452.0		17 + 00		51 + 52	ON BRIDGE
	198.0	9	51 + 52		53 + 50	ILLINOIS
	6,245.0	TOTAL	31 . 32		33 . 30	TEE TO TO
	0,2 10.0					
70400200	RELOCATE T	EMPORARY CO	ONCRETE BARR	IER		
	FOOT		LOCATION			REMARKS
		. 1	STAGE TWO			
	587.5		1491 + 80		1497 + 00	IN STATE OF IOWA
	80.0		1497 + 00		1497 + 80	IN STATE OF IOWA
	950.0		53 + 50		62 + 00	ILLINOIS
	1,617.5	TOTAL				
70400600	RELOCATE T	EMPORARY CO	ONCRETE BARR	IER	(STATE OWNED)	
	FOOT		LOCATION			REMARKS
			STAGE ONE			
	515.5		1491 + 88		1497 + 00	DELIVER TO STATE OF IOWA
	515.5 77.5				1497 + 00 1497 + 80	DELIVER TO STATE OF IOWA DELIVER TO STATE OF IOWA
			1491 + 88			
	77.5		1491 + 88			DELIVER TO STATE OF IOWA
	77 . 5 75 . 0		1491 + 88			DELIVER TO STATE OF IOWA ON BRIDGE
	77.5 75.0 62.5	_	1491 + 88 1497 + 00		1497 + 80	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE
	77.5 75.0 62.5 400.0	TOTAL	1491 + 88 1497 + 00 47 + 50		1497 + 80 51 + 52	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE
	77.5 75.0 62.5 400.0 1,450.0		1491 + 88 1497 + 00 47 + 50		1497 + 80 51 + 52	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE
	77.5 75.0 62.5 400.0 1,450.0 2,580.5	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52		1497 + 80 51 + 52 66 + 02	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I	• LINE 4	1497 + 80 51 + 52 66 + 02	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I	• LINE 4	1497 + 80 51 + 52 66 + 02	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND		1497 + 80 51 + 52 66 + 02	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00	to	1497 + 80 51 + 52 66 + 02	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00 2505.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00	†0 †0	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00 2505.00 1731.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTROUND 1440 + 00 1440 + 00 1474 + 00	†o †o †o	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05 1491 + 31	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQT 5780.00 2505.00 1731.00 1467.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTROUND 1440 + 00 1440 + 00 1474 + 00 51 + 53	to to to	1497 + 80 51 + 52 66 + 02 11111 1497 + 80 1465 + 05 1491 + 31 66 + 20	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00 2505.00 1731.00 1467.00 821.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99	to to to to	1497 + 80 51 + 52 66 + 02 1'' 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow Right edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQT 5780.00 2505.00 1731.00 1467.00 821.00 1930.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20	to to to to	1497 + 80 51 + 52 66 + 02 1497 + 80 1455 + 05 1491 + 31 66 + 20 66 + 20 85 + 50	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White Left edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P E001 5780.00 2505.00 1731.00 1467.00 821.00 1930.00 163.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99	to to to to	1497 + 80 51 + 52 66 + 02 1'' 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow Right edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQT 5780.00 2505.00 1731.00 1467.00 821.00 1930.00	ŢOTAL	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTROUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20	to to to to	1497 + 80 51 + 52 66 + 02 1497 + 80 1455 + 05 1491 + 31 66 + 20 66 + 20 85 + 50	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White Left edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQT 5780.00 2505.00 1731.00 1467.00 821.00 1930.00 163.00 14397.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESTBOUND	to to to to to	1497 + 80 51 + 52 66 + 02 11111 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Left edge line - Yellow Right edge line - Yellow Right edge line - Yellow Right edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00 2505.00 1467.00 821.00 1930.00 163.00 14397.00 780.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESIBOUND 1490 + 00	to to to to to to	1497 + 80 51 + 52 66 + 02 1111 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P E001 5780.00 2505.00 1731.00 1467.00 821.00 1930.00 14397.00 780.00 182.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESTBOUND 1490 + 00 1490 + 00	to to to to to to to	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow Right edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P E001 5780.00 2505.00 1731.00 1467.00 821.00 1930.00 14397.00 780.00 182.00 1467.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTROUND 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESIBOUND 1490 + 00 51 + 53	to to to to to to to to	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EOOT 5780.00 2505.00 1467.00 821.00 1930.00 163.00 14397.00 780.00 182.00 184.00 185.00 186.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTROUND 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 WESTBOUND 1490 + 00 1490 + 00 51 + 53 62 + 52	to t	1497 + 80 51 + 52 66 + 02 1111 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20 66 + 20 66 + 20	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Left edge line - Yellow Right edge line - White Left edge line - Yellow Right edge line - White Left edge line - Yellow Right edge line - White Left edge line - Yellow Right edge line - White
78008210	77.5 75.0 62.5 400.0 1.450.0 2.580.5 POLYUREA P EQQT 5780.00 1731.00 1467.00 821.00 1930.00 163.00 780.00 14397.00 780.00 182.00 19467.00 368.00 1930.00 1930.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESIBOUND 1490 + 00 1490 + 00 51 + 53 62 + 52 66 + 20	to t	1497 + 80 51 + 52 66 + 02 11111 1497 + 80 1465 + 05 1491 + 31 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20 85 + 50 66 + 20 85 + 50	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow Right edge line - Yellow Right edge line - White Left edge line - Yellow
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P E001 5780.00 2505.00 1731.00 1467.00 182.00 14397.00 780.00 182.00 1467.00 368.00 1930.00 1950.00 167.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESTBOUND 1490 + 00 1490 + 00 51 + 53 62 + 52 66 + 20 66 + 20 66 + 20 66 + 20 66 + 20	to t	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20 66 + 20 66 + 20 66 + 20 67 + 20 68 + 20 73 + 70 73 + 70 74 + 70 75 + 70 76 + 70	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White Left edge line - Yellow Right edge line - White Left edge line - White Left edge line - White Left edge line - Yellow Right edge line - White Left edge line - White
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P EQQI 5780.00 2505.00 1731.00 1467.00 821.00 1930.00 14397.00 780.00 182.00 1467.00 368.00 1930.00 1950.00 1950.00 1950.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESIBOUND 1490 + 00 1490 + 00 51 + 53 62 + 52 66 + 20	to t	1497 + 80 51 + 52 66 + 02 11111 1497 + 80 1465 + 05 1491 + 31 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20 85 + 50 66 + 20 85 + 50	DELIVER TO STATE OF 10WA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - Yellow Right edge line - Yellow Right edge line - White Left edge line - Yellow
78008210	77.5 75.0 62.5 400.0 1,450.0 2,580.5 POLYUREA P E001 5780.00 2505.00 1731.00 1467.00 182.00 14397.00 780.00 182.00 1467.00 368.00 1930.00 1950.00 167.00	TOTAL AVEMENT MAF	1491 + 88 1497 + 00 47 + 50 51 + 52 RKING TYPE I LOCATION EASTBOUND 1440 + 00 1440 + 00 1474 + 00 51 + 53 57 + 99 66 + 20 66 + 20 WESTBOUND 1490 + 00 1490 + 00 51 + 53 62 + 52 66 + 20 66 + 20 66 + 20 66 + 20 66 + 20	to t	1497 + 80 51 + 52 66 + 02 1497 + 80 1465 + 05 1491 + 31 66 + 20 66 + 20 85 + 50 67 + 83 1497 + 80 1491 + 82 66 + 20 66 + 20 66 + 20 66 + 20 67 + 20 68 + 20 73 + 70 73 + 70 74 + 70 75 + 70 76 + 70	DELIVER TO STATE OF IOWA ON BRIDGE ON BRIDGE ILINOIS ABUTMENT ON BRIDGE ILLINOIS REMARKS Left edge line - Yellow Right edge line - White Right edge line - White Left edge line - White Left edge line - Yellow Right edge line - White Left edge line - White Left edge line - White Left edge line - Yellow Right edge line - White Left edge line - White

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SCH	IED	ULE	0F	QUANT	ITIES
CHEET	10	05	CHEETC	P. T	TO CT.

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
80	(81-1B) M-4	ROCK ISLAND	75	9
		CONTRAC	T NO.	54F31
	ILLINOIS FED. A	ID PROJECT		

SCHEDULE OF QUANTITIES

					4 1 1						
78008230	POLYLIREA P	AVEMENT MARKING	TYPE I . II	INF 6			1.00				
0000230	FOOT		CATION	INL U					REMARKS		
	L. M. D.		TBOUND				The Bridge		GEMBUILD		
	1445.00			+ ^	1407 + 90	CI	l okio doob	White			
				to	1497 + 80		L skip dash				
	72.25			to	1467 + 94		ight edge li		sn - White		
	366.75			to	66 + 20		L skip dash				
	482.50			to	85 + 50		L skip dash				
	352.00	71	+ 42 1	to	85 + 50	Ri	ight edge lir	ne skip do	ish - White		
	2718.50	Sub-Totd									
		WES	TBOUND								
	195.00	. 149	0 + 00	to	1497 + 80	CL	L skip dash	- White			
	124.50	149	12 + 82 1	to	1497 + 80	Rī	ight edge lir	ne skip do	sh - White		
	206.25	51	+ 30 1	to	59 + 55	Ri	ight edge lir	ne skip do	sh - White		
	366.75			to	66 + 20		L skip dash				
	482,50			to	85 + 50		L skip dash				
	1375.00	Sub-Totd			05 . 50	0.	L ONIP GGOIT	***************************************			
	4.093.5	TOTAL									
	4,033.3	TOTAL									
8008240	POLYUREA P.	AVEMENT MARKING	G TYPE I • LI	NE 8	"						
	EQOI	LO	CATION						REMARKS		
		EAS	TBOUND								
	606.00	146	7 + 94 1	to	1474 + 00	E×	xit ramp lef	t edae lin	e - White		
	606.00			to	1474 + 00		xit ramp lef				
	100.00			to	1491 + 31		ntrance rai	-		i+a	
									-		int+-
	25.00			to	1492 + 31		ntrance rai			uasn - W	INITE
	363.00			to	57 + 99		xit ramp lef	_			
	363.00			to	57 + 99		xit ramp lef	-			
	359,00			to	71 + 42	Er	ntrance rai	np left ec	ge line - Wh	ite	
	359.00	67	r + 83 1	to	71 + 42	Er	ntrance rai	np left ec	ge line - Wh	ite	
	2781.00	Sub-Totd						ું જેવું છે.			
		WES	TBOUND					91,24			
	200.00			to	1492 + 82	E×	xit ramp lef	t edge lin	e - White		
	200.00			to	1492 + 82		xit ramp lef				
	74.25			to	62 + 52		ntrance rai	-		doch = M	/bi+o
	95.00				63 + 47						111111111111111111111111111111111111111
				to			ntrance rar			тe	
	364.00			to.	76 + 81		xit ramp lef				
	364.00		3 + 17 1	to	76 + 81	Ł×	xit ramp lef	t edge lin	e - White		
	1297.25	Sub-To†d					- Negritar	549618 H			
	4,078.3	TOTAL					11,475 (1,4)				
						1.0	100 100 100 100 100 100 100 100 100 100	Kadi a			
8008250	POLYUREA PA	AVEMENT MARKING	G TYPE I * LI	NE 12	2"			all Market			
	EOOT	LOC	CATION				a the free file	the carried or	REMARKS		
			TBOUND								
	100.00			to	57 + 99	Fx	xit ramp dic	igonols - V	White		
	174.75			to	68 + 33		utside shou			v 100′ 16	9' 1000
	334.45			to	86 + 00		utside shou				
			D T 21 1	10	86 + 00	Ü	u i side si iod	ider diago	indis - ever	y 100 , 16	.9 long
	609.20	Sub-Totd									
			TBOUND								
	334.45			to	86 + 00		utside shou	-		-	_
	163.93			to	73 + 17		utside shou			y 100' , 16	.9' lonç
	225.00	73	3 + 17 †	to	76 + 81	E×	xit ramp dic	igonals - N	Vhite		
	723.38	Sub-Totd									
	1,332.6	TOTAL									
	-,	- · · · · -									
OLE BUUE	POLYLIDEA D	AVEMENT MARKING	TYPE II .	INC .	1"						
0000010				TINE 4	•				DEMARKS		
	FOOT		CATION						REMARKS		
			TBOUND				40.5				
	3483.00			to	51 + 53	Br	ridge - Left	edge line	- Yellow		
	3483.00	16	+ 70 t	to	51 + 53	Br	ridge – Righ	t edge lin	e - White		
	6966.00	Sub-Totd									
		₩ES	TBOUND				2010 100 BM				
	3483.00			to	51 + 53	Rr	ridge - Left	edde line	- Yellow		
	3483.00			to	51 + 53		ridge - Righ				
			. , , 5		21 + 22	ВF	inda - viðu				
								Section 1			
	13,932.0	TOTAL									
							45	Aud			
								3 4 4 4			
3008330	POLYUREA PA	AVEMENT MARKING	TYPE II . L	INE 6	5"		The second second				
	EOOT		CATION					est en record Frances in			
			TBOUND				er retirit				
	870.75			to	51 + 53	Br.	ridne - CL s	kin dash -			
	010.13	16	, 10 T	. 0	21 ± 22	Br	ridge – CL s	KID aasn -	MIIII E		
			TROUBER								
			TBOUND								
	870.75		+ 70 t	to	51 + 53	Br	ridge – CL s	kip dash -	White		
	1,741.5	TOTAL									

78100106	RAISED REFLEC	TIVE PAVE	MENT MARKER	>	(BRIDGE)	
,0100100		SIIVE FAVE		,	(BKIDGE)	PELLABUR
	EACH		LOCATION			REMARKS
	43.0		16 + 69		51 + 52	80' SPACING, EASTBOUND
	43.0		16 + 69		51 + 52	80' SPACING, WESTBOUND
	86.0	TOTAL				
		TOTAL				
78200100	MONODIRECTION	NAL PRISMA	ATIC BARRIER		REFLECTOR	
	EACH		LOCATION			REMARKS
	140.0		16 + 69		51 + 52	50' SPACINGS ON PARAPET WALLS
	140.0		16 + 69		51 + 52	50' SPACINGS ON MEDIAN BARRIER WALL
	59.0		51 + 52		66 + 20	50' SPACINGS ON MEDIAN BARRIER WALL
	339.00	TOTAL				
78200200	BIDIRECTIONAL	PRISMATION	C BARRIER		REFLECTOR	
	EACH		LOCATION			REMARKS
	140.0		16 + 69		51 + 52	50' SPACINGS ON CENTER BARRIER WALL
	59.0		51 + 52		66 + 20	50' SPACINGS ON MEDIAN BARRIER WALL
	23.0		1492 + 00		1497 + 60	50' SPACING ON State of IOWA barrier wall
	222.00	TOTAL				
70030260	IMPACT ATTEN	LIATORS TE	MPORARY (FUI	ΙY	REDIRECTIVE NAM	RROW). TEST LEVEL 3
20030200		CATOLO, IL			NEDINEOTITE; NA	•
	EACH		LOCATION			REMARKS
			STAGE ONE			
	1.00		65 + 52			ILLINOIS PAVED MEDIAN
	1.0	TOTAL				
VVOCOCC	CONCELL DAD	DIED WALL	(CDECIAL)			
XX002866	CONCRETE BAR	KIEK WALL				
	CU.YD.		LOCATION			REMARKS
	84.00		1492 + 00	†o	1497 + 60	State of IOWA barrier wall
	84.00	TOTAL				
X0323644	PAVEMENT MAR	NINC CROO	VINC			
X0323644		INTING GROO				
	EOOT		LOCATION			REMARKS
			EASTBOUND			
	870.75		16 + 70	to	51 + 53	Bridge - 6" CL skip dash
	3483.00		16 + 70	to	51 + 53	Bridge - Left edge line -4"
	3483.00		16 + 70	to	51 + 53	Bridge - Right edge line - 4"
		Sub-Totd	10 . 10	, 0	51 . 55	Bridge Bigiti edge and 1
	1030*13	300-1010				
			WESTBOUND			
	870.75		16 + 70	to	51 + 53	Bridge - 6" CL skip dash
	3483.00		16 + 70	to	51 + 53	Bridge - Left edge line -4"
	3483.00		16 + 70	to	51 + 53	Bridge - Right edge line - 4"
	7836,75	Sub-To+d		-	==	
	15,673.50	TOTAL				
	15,615.50	TOTAL				
X0325194	IMPACT ATTEN	UATORS (FU	LLY REDIRECT	TIVE,	NARROW), TEST LE	VEL 3, SPECIAL
	EACH		LOCATION			REMARKS
	1.00		65 + 69.50			END OF PAVED MEDIAN. QUADGUARD ELITE
	1.00	TOTAL	23 . 33.30			E-15 OF FRIED INCOMING GORDOURING CETTE
	1.00	TOTAL				
X0325939	IMPACT ATTEN	UATORS, TE	MPORARY (FUL	LY	REDIRECTIVE, NAF	RROW), TEST LEVEL 3, SPECIAL
	EACH		LOCATION			REMARKS
	1.00		53 + 30			END OF TEMP BARRIER WALL, REACT 350, SELF RESETTING
			20 . 00			E. S. Tam British Harry NEAD 1 3001 OEE NESE 1 1110
	1.00	TOTAL				
	1.00	TOTAL				
	1.00	TOTAL				

FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED -
c:\pw_work\pwidat\cushmanbw\d0149192\d0	409-sht-schedule.dgn	DRAWN -	REVISED -
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -
	PLOT DATE = Thu Sep 17 10:49:02 2009	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SCALE:

CCLLD	r	۸r	OHARI		F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEE NO.
SCHED	ULE	UF	UUAN		80	(81-1B) M-4	ROCK ISLAND	75	10
 			т				CONTRAC	Γ. ΝΟ.	64F3
SHEET NO.	OF	SHEETS	STA.	TO STA.		ILLINOIS FED. A	ID PROJECT		

SEQUENCE OF WORK

NOVEMBER LETTING - No work activities prior to Spring of 2010.

2010 CONSTRUCTION

Pre-staging

Detour eastbound Interstate 80 traffic. Close eastbound Interstate 80 access across bridge. Maintain current Westbound traffic pattern of only one (1) lane
Falcon Protection shall be in place prior to February 1, 2010.


YEAR 2010

- Stage I Repair eastbound travel lanes by "STAGE ONE, COMPLETION DATE". All work necessary to provide two-lane, two-way traffic shall be completed by this date.
 - Set-up temporary concrete barrier wall across bridge for Stage Two head-to-head traffic and all associated temporary pavement markings.
 - Set-up temporary barrier wall at median cross-overs to move westbound traffic onto the eastbound passing lane.
 - Open eastbound driving lane across bridge to eastbound traffic. Move westbound traffic through median cross-overs and onto eastbound passing lane. Head-to-head traffic to be in place by 6:00 pm on "STAGE ONE, COMPLETION DATE".
 - Close access to westbound bridge lanes.
- Stage II Repair Westbound travel lanes by "STAGE TWO, COMPLETION DATE". All work necessary to provide four-lane, two-way traffic shall be completed by this date and as a minimum, temporary winter paint pavement markings shall be completed.
 - Move westbound traffic into westbound lanes across the bridge. Maintain eastbound traffic in eastbound driving lane across bridge.
 - Move eastbound traffic into pasing lane and complete all remaining winter paint pavement markings.

YEAR 2011


- Stage III The Contractor will not begin any work prior to April 4, 2011.
 - Traffic Control on the bridge is restricted to that shown in the staging plans.
 - Install/Repair permanent concrete median barrier wall(s).
 - Grind bridge surfaces and install permanent bridge pavement markings, Reflective Raised Pavement Markings (RRPM), and concrete wall reflectors.
 - Repair Iowa concrete slope wall includes any seeding
 - Bridge washing Spring 2011 only.

FILE NAME =	USER NAME = oushmanbw	DESIGNED -	REVISED ~			······					F.A.I.	SECTION	COUNTY	TOTAL SHEET
c:\pw_work\pwidot\oushmanbw\d0149166\d09	409stg-Aldgn	DRAWN ~	REVISED	STATE OF ILLINOIS							80	(81-1B) M-4	ROCK ISLAN	D 75 11
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION									CONTRAC	T NO. 64F31
	PLOT DATE = Thu Sep 17 09:15:45 2009	DATE -	REVISED -		SCALE:	SHEET NO.	OF	SHEETS	STA.	TO STA.		ILLINOIS FE	D. AID PROJECT	



STAGE I







	V//2	= WORK AREA
	þ	= SIGN
	∲	= DIRECTION INDICATOR BARRICADE WITH STEADY BURN MONODIRECTIONAL LIGHT
	Ŧ	= TYPE II BARRICADE, DRUM, WITH STEADY BURN MONODIRECTIONAL LIGHT
-	◁	= MONODIRECTIONAL BARRIER WALL/GUARDRAIL MARKER
		= IMPACT ATTENUATOR

SYMBOLS


= ARROW BOARD


FILE NAME =	USER NAME = cushmanbs	DESIGNED -	REVISED -						F.A.I.	SECTION	COUNTY TOTAL SHEET
c:\pw_work\pwsdot\cushmanbw\d0149166\d09	109stg-A.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS		9	STAGE I		80	(81-1R) M-4	ROCK ISLAND 75 13
	PLOT SCALE = 50.0000 '/ IN.		REVISED -	DEPARTMENT OF TRANSPORTATION		•	OINGE !		50	(OI ID) W 4	CONTRACT NO. 64F31
	PLOT DATE = Thu Sep 17 09:16:12 2009	DATE -	REVISED -		SCALE: SHEET NO. OF SHEETS STA. TO STA.		ILLINOIS FED. AID PROJECT				







STAGE I 17+00 30+00 STA <u>پ</u> I-80 WB MATCH Sta.20+62.19 S+0,2[+21,62 S+0.17+96.82 S+a.20+02,7] CL21-8-1 S+0.18+71.82 S+0.19+42.54 S+0.21+82,46 S+a.25+08.58 S+a,28+95,00 SYMBOLS = ARROW BOARD = WORK AREA = MONODIRECTIONAL BARRIER WALL/GUARDRAIL MARKER 31+00 = IMPACT ATTENUATOR 40+00 ST I-80 WB MATCH S+0,44+58,33 Sta.33465.00 S+0.36+89.33 S+a.43+[8.33 DESIGNED FILE NAME REVISED USER NAME = cushmanbw SECTION TOTAL SHEE NO. STATE OF ILLINOIS STAGE I DRAWN REVISED ROCK ISLAND 75 PLOT SCALE = 50.00000 '/ IN. CHECKED REVISED **DEPARTMENT OF TRANSPORTATION** CONTRACT NO. 64F31 DATE REVISED SCALE: SHEET NO. OF SHEETS STA. TO STA.











STAGE II














STAGE III








Bench Mark: Brass Monument in top center of concrete headwall approx. 150 ft. east of I-80 and 10 ft. t north of north edge of concrete pavement of ramp on north side Route 67. Elev. 100.00

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

Existing Structure: The existing structure was originally built in 1966 with 12 approach spans and 16 main spans. The steel main spans consist of a two girder system with floorbeams and stringers in which the reinforced concrete deck is composite in the positive moment regions of the stringers. The approaches consist of steel multi-girder spans.



reinstalled.

EXPIRES 11/30/2010

09/17/09

33 SHEETS


SN 081-0011

FED. ROAD DIST. NO. 7 | ILLINOIS | FED. AID PROJECT


CONTRACT NO. 64F31

LOCATION SKETCH

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



PART ELEVATION



INDEX OF SHEETS

1 General Plan and Elevation - 1 General Plan and Elevation - 2 General Notes and Bill of Material 4 Typical Stage Construction Cross Sections 5 Temporary Concrete Barrier for Stage Construction 6 Repair and Replacement Items - 1 Repair and Replacement Items - 2 8 Cantilever Floorbeam Replacement - Single Girder Spans 9 Cantilever Floorbeam Replacement - Double Girder Spans Slab/Stringer Temporary Support Conceptual Details Stringer End Repair Details - 1 Stringer End Repair Details - 2 Stringer End Repair Details - 3 Stringer End Repair Details - 4 Stringer End Repair Details - 5 Elastomeric Bearing Assembly 17 Miscellaneous Steel Repair Details - 1 18 Miscellaneous Steel Repair Details - 2 19 Miscellaneous Steel Repair Details - 3 20 Miscellaneous Steel Repair Details - 4 21 Miscellaneous Steel Repair Details - 5 22 Partial Deck Removal and Replacement at Expansion Dams
23 Partial Deck Removal and Replacement at Expansion Dams Pier 8 and 24
24 Partial Deck Removal and Replacement at Hinge 14 25 Partial Deck Removal and Replacement at Relief Joints - 1 26 Partial Deck Removal and Replacement at Relief Joints - 2 27 Concrete Median Details 28 Light Standard Support and Miscellaneous Concrete Details 29 Expansion Dam Repair and Replacement 30 Preformed Joint Strip Seal 31 Slope Wall Repair Details 32 Concrete Repair Details 33 Field Welding of Stiffeners

GENERAL PLAN AND ELEVATION - 2

I-80 OVER

MISSISSIPPI RIVER

STRUCTURE NO. 081-0011

SHEET NO. 2

SHEET NO. 2

80

(81-1B)M-4

ROCK ISLAND

55

29

SN 081-0011

FED. ROAD DIST. NO. 7 | ILLINOIS | FED. AID | PROJECT

CHECKED PSS

CHECKED DWP

DRAWN PRC

CHECKED YSS

CHECKED YSS

09/17/09

GENERAL NOTES

Fasteners shall be AASHTO M164 Type 1, mechanically galvanized bolts. Bolts $^{7}_{8}$ in. ϕ , holes $^{15}_{16}$ in. ϕ , unless otherwise noted.

Calculated weight of Structural Steel for Furnishing and Erecting Structural Steel = 208,350 lbs. of Grade 50 and 56,360 lbs. of Grade 36.

Calculated weight of Structural Steel for Structural Steel Repair = 211,510 lbs. of Grade 36 and 10 lbs. of Bronze.

All structural steel shall conform to M270 Grade 36, unless otherwise noted. Reinforcement bars shall conform to the requirements of ASTM A 706 Gr 60 (IL Modified). See Special Provisions

Reinforcement bars designated (E) shall be epoxy coated.

No field welding is permitted except as specified in the contract documents. Prior to pouring the new concrete deck, all heavy or loose rust, loose mill scale, and other loose or potentially detrimental foreign material shall be removed from the surfaces in contact with concrete. Tightly adhered paint may remain unless otherwise noted. Removal shall be accomplished by methods that will not damage the steel and the cost will be included in the pay item covering removal of the existing concrete.

As directed by the Engineer, existing construction accessories welded to the top flange of beams and girders shall be removed. The weld areas shall be around flush and inspected for cracks using magnetic particle testing (MT) or dye penetrant testing (PT) by qualified personnel approved by the Engineer.

Any cracks that cannot be removed by grinding 4 inch deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. The cost of removing welded accessories, grinding and inspecting weld areas and grinding cracks will be paid for according to Article 109.04 of the Standard Specifications.

Plan dimensions and details are subject to routine variations. The Contractor shall field verify existing dimensions and details affecting new construction and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for a change in scope of the work, however, the Contractor will be paid for the quantity actually furnished based upon the unit price bid for the work.

Design drawings and shop drawings from original construction and major rehabilitation performed in 1995 will be made available to the Contractor. The existing structural steel coating contains lead. The Contractor shall take

appropriate precautions to deal with the presence of lead on this project.

The Organic Zinc Rich Primer / Epoxy / Urethane Paint System shall be used for painting of new structural steel except where otherwise noted. The entire system shall be shop applied, with the exception that masked off connection surfaces, field installed fasteners and damaged areas shall be touched up in the field. The color of the final finish coat for all interior steel surfaces shall be Gray, Munsell No. 5B 7/1. The color of the final finish coat for the exterior and bottom flange of the fascia beams shall be Interstate Green, Munsell No. 7.5G 4/8. See Special Provision for "Cleaning and Painting New Metal Structures".

Existing structural steel that will be in contact with new structural steel and existing structural steel adjacent to field welding and mechanical treatment of welds shall be cleaned and painted prior to erection as required by the Special Prvision. "Cleaning and Painting Contact Surface Areas of Existing Steel Structures".

All contact surfaces of connection angles and plates for cantilever floorbeam section to be replaced and splices plates for stringer end replacement shall be treated as primary connections.

Joints shall be adjusted according to Article 520.04 of the Standard Specifications when the deck is poured at an ambient temperature other than 50° F.

Existing reinforcement bars extending into the removal area shall be cleaned, straightened and incorporated into the new construction. Any reinforcement bars that are damaged during concrete removal shall be replaced with an approved bar splicer or anchorage system. Cost included with Concrete Removal.

Cost of removal and re-installation of all members necessary to complete the work as detailed on the plans shall be included with Structural Steel Repair.

The steel beams which are part of the temporary slab support system currently installed over Stringer 7 at FB3 on Span12 and at FB6 on Span 18 are to be removed and returned to the District. The beams and other appurtenant materials should be delivered to the District Day Labor at 505 North MacArthur Blvd., Springfield, IL 62702 between the hours of 8 am and 2 pm. Mr. Rick Brunette should be notified prior to the delivery of the beam at 217-782-7416. The beams shall not be cut for transport. The Contractor shall be responsible for providing the crane to unload the beams. Cost included with Concrete Removal.

Consulting Engineers

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SARs Notes:

The Contractor is advised that the existing structure contains members that are in a deteriorated condition with reduced load carrying capacity. It is the Contractor's responsibility to account for the condition of the existing structure when developing construction procedures. An Existing Structure Information Package is available upon request as noted in the Special

The Contractor shall submit Structural Assessment Report(s) as required for the Contractor's Means and Methods of Construction. See Special Provision.

The Contractor shall retain the services of an engineering firm, prequalified in the IDOT consultant selection category of Highway Bridges Advance Typical, for preparation of the Structural Assessment Report(s). Contractor's pre-approval shall not be applicable for this project. See Special Provision.

Current Ratings on File for Existing Structure Inventory: HS 0.0 (for closed outside lane in each direction)

Operating: HS 0.0 (for closed outside lane in each direction) Live Load Restriction: Legal Load Only (for inside lane in each direction)

Inventory and Operating Ratings and Live Load Restrictions are provided for information only. Inventory and Operating Ratings are based on HS loading and configuration. Live Load Restrictions are based on Illinois legal loads and configurations. The Rating and Live Load Restrictions are not necessarily representative of capacities to support the Contractor's equipment. The above zero capacity Inventory and Operating Ratings are for the outside lanes in each direction due to cracking and deterioration of the cantilever floorbeams and Stringers 1, 2, 7 and 8. As noted, the inside lanes are currently restricted to legal loads only.

The SSPC QP1 Painting Contractor Certification is required for this contract.

DESIGN SPECIFICATIONS

2002 AASHTO Standard Specification for Highway Bridges

2007 AASHTO LRFD Bridge Design Specifications with 2009 Interims (Fatigue only)

LOADING HS25-44

LOADING HL - 93 (Fatigue only) Allow 50#/sq. ft. for future wearing surface.

DESIGN STRESSES

NEW CONSTRUCTION

f'c = 3,500 psi

fy = 60,000 psi (Reinforcement)

fy = 36,000 psi (M270 Grade 36, Structural Steel)

fy = 50,000 psi (M270 Grade 50, Cantilever Floorbeam)

EXISTING CONSTRUCTION

f'c = 3,500 psi

fy = 60,000 psi (Reinforcement)

fy = 36,000 psi (M270 Grade 36, Structural Steel)

fy = 50,000 psi (M270 Grade 50, Structural Steel)

TOTAL BILL OF MATERIAL

7777	LULTT	CUDED	6110	TOTAL
ITEM	UNIT	SUPER	SUB	TOTAL
Concrete Removal	Cu. Yd.	427.2		427.2
Slope Wall Removal	Sq. Yd.		11.7	11.7
Protective Shield	Sq. Yd.	6123		6123
Concrete Superstructure	Cu. Yd.	611.6		611.6
Bridge Deck Grooving	Sq. Yd.	1479		1479
Protective Coat	Sq. Yd.	2224		2224
Furnishing and Erecting Structural Steel	L. Sum	1		1
Stud Shear Connectors	Each	4312		4312
Structural Steel Removal	Pound	155,620		155,620
Structural Steel Repair	Pound	211,520		211,520
Cleaning and Painting Structural Steel, Location 1	L. Sum	1		1
Reinforcement Bars, Epoxy Coated	Pound	167,320		167,320
Slope Wall 4 inch	Sq. Yd.		11.7	11.7
Preformed Joint Strip Seal	Foot	1636		1636
Elastomeric Bearing Assembly, Type I	Each	100		100
Expansion Joint (Special)	Foot	233		233
Jacking and Cribbing	L. Sum	1		1
Temporary Support System	L. Sum	1		1
Embankment	Cu. Yd.		6.3	6.3
Mechanical Splice	Each	10,228		10,228
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.		11.6	11.6
Mechanical Treatment of Steel Welds	Each	828		828
Field Welding of Stiffeners	Each	828		828

Is, Ss: Non-composite moment of inertia and section modulus of the steel section used for computing f_s (Total and Overload) (in 4 and in .3).

M ?: Un-factored moment due to dead load (kip-ft.).

 M_{\pm} : Un-factored live load moment (kip-ft.).

M1: Un-factored moment due to impact (kip-ft.). Ma: Factored design moment (kip-ft.).

 $1.3 [MQ + \frac{5}{3}(M4 + M_I)]$

fs (Overload): Sum of stresses as computed from the moments below (ksi).

 $MQ + \frac{5}{3} (ML + MI)$

fs (Total): Sum of stresses as computed from the moments below on non-compact section (ksi). $1.3 [MQ + \frac{5}{3} (ML + M_I)]$

CANTILEVER FLOC	RBEAM M	NOMENT TAE	BLE
		At Suppor	†
Is	(in ⁴)	51058	
Ss	(in ³)	1514	
MР	('k)	659	
M Ł	('k)	545	
Mi	('k)	163	
⁵ 3[M4 + 1]	('k)	1180	
Ma	('k)	2391	
fs Q	(ksi)	5.2	
fs ⁵ 3 [M & + M _I]	(ksi)	9.4	
fs (Overload)	(ksi)	14.6	
f_{ε} (Total)	(ksi)	9.0	

CANTILE	VER FLO	DORBEAM SHEAR TABLE
		At Support
V P	(k)	69
V 4	(k)	79
VI	(k)	23
V Total	(k)	311

* partially braced section

Moment and shear shown are for cantilever floorbeam at single girder spans.


GENERAL NOTES AND BILL OF MATERIAL I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011


SHEET NO. 3	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEE'
	80	(81-1B)M-4	ROCK ISLAND	75	30
33 SHEETS		SN 081-0011	CONTRACT	NO. 64	F31
	FED. RO	AD DIST. NO. 7 ILLINOIS FED. A	ID PROJECT		

DESIGNED YSS CHECKED DWP DRAWN PRC

CHECKED YSS 09/17/09

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION







(Looking Upstation)

STAGE I REMOVAL (Looking Upstation)

Note: Cross section of single girder span shown, double girder span similar.



(Looking Upstation)



STAGE II CONSTRUCTION (Looking Upstation)

STAGE CONSTRUCTION

- 1. Place Type II barricades or similar to carry one 14'-0" lane in the westbound direction on the East half of the bridge.
- 2. Remove part of deck joint and concrete deck at locations per Sheet Nos. 6 and 7 of 33.
- 3. Install temporary support for concrete decks and stringer end repairs. See Sheet No. 10 of 33 for conceptual details.
- 4. Remove stringer ends and cantilever floorbeam brackets.
- 5. Install cantilever floorbeam brackets and stringer ends.
- 6 Perform miscellaneous steel repairs and remove temporary supports.
- 7. Install deck joints and construct partial concrete deck.

- 1. Place temporary barrier to carry $14'-3l_2$ " lanes in the westbound and eastbound direction on the west half of the bridge.
- Remove part of deck joint and concrete deck at locations per Sheet Nos. 6 and 7 of 33.
 Install temporary support for concrete decks and stringer end repairs. See Sheet No. 10 of 33 for conceptual details. 4. Remove stringer ends and cantilever floorbeam brackets.
- 5. Install cantilever floorbeam brackets and stringer ends.
- 6. Perform miscellaneous steel repairs and remove temporary supports.
- 7. Install deck joints and construct partial concrete deck.

Construction of concrete median shown on Sheet No. 27 of 33 shall be coordinated with Department personnel.


TYPICAL STAGE CONSTRUCTION CROSS SECTIONS I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO.4	F.A.I. RTE.		SEC	TION		COI	UNTY	TOTAL SHEETS	SHEE NO.
	80		(81-1	3)M-4		ROCK	ISLAND	75	31
33 SHEETS		SN 081-0011				CON	FRACT	NO. 64	F31
	FED. R	OAD DIST.	NO. 7	ILLINOIS	FED. A	AID PROJ	ECT		

DESIGNED YSS CHECKED DWP DRAWN PRC CHECKED YSS

MODJESK JandMASTERS Consulting Engineers
SINCE 1893 09/17/09

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



NOTES


Detail I - With Bar Splicer or Couplers: Connect one (I) 1''x7''x10'' steel P_c to the top layer of couplers with $2^{-5}g'' \neq bolts$ screwed to coupler at approximate & of each barrier panel.


Detail II - With Extended Reinforcement Bars: Connect one (1) 1''x7''x 10'' steel II to the concrete slab or concrete wearing surface with $2^{-5}g''$ ϕ Expansion Anchors or cast in place inserts spaced between the top layer of reinforcement at approximate & of each barrier panel.


Cost of anchorage is included with Temporary Concrete Barrier. The 1" x 7" x 10" plate shall not be removed until stage II construction forms and all reinforcement bars are in place and the concrete is ready to be placed.

SECTIONS THRU SLAB OR DECK BEAM

- *** Dimension shown is minimum required embedment into concrete. If hot-mix asphalt wearing surface is present, minimum embedment shall be in addition to wearing surface depth.
- **** If existing deck beam is to remain in place after stage construction, embedment shall only be into wearing surface and not into existing deck beam concrete.







STEEL RETAINER P 1" x 7" x 10"

* Required only with Detail II

**Wood blocks may be omitted when required to provide minimum stage traffic lane width. When the wood blocks are omitted, the concrete barrier shall be in direct contact with the steel retainer plate.

TEMPORARY CONCRETE BARRIER FOR STAGE CONSTRUCTION I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 5	F.A.I. RTE.	SECTION			COUNTY		TOTAL SHEETS	SHEET NO.
	80	(81-1	ROCK	ISLAND	75	32		
33 SHEETS	33 SHEETS SN 081-0011				CON.	TRACT	NO. 64	F31
	FED. RO	DAD DIST. NO. 7	ILLINOIS	FED. A	ID PROJ	ECT		


DESIGNED	YSS	
CHECKED	DWP	MODJESK JandMASTE
DRAWN	PRC	 Consulting Engine

CHECKED YSS

09/17/09

Anchored every 4th barrier to the slab as per details shown on this sheet.





PARTIAL FRAMING PLAN

— € Hinge 15 & Exp. Dam

7 Floorbeam spa, at 23'-2" = 162'-2"

Note: Girders, lateral bracing between girders and inspection walkway not shown for clarity.

REPAIR LEGEND

- (1) Cantilever Floorbeam replacement See Sheet Nos. 8 and 9 of 33
- 2 Cut existing end of Stringer (lines 1-2 & 7-8) and splice in new end section See Sheet Nos. 11 thru 15 of 33
- $\langle \overline{3} \rangle$ Remove and replace concrete deck as required See Sheet Nos. 22 thru 26 of 33
- (4) Remove and replace Relief Joint Preformed Joint Strip Seal See Sheet No. 30 of 33

- Access Walk

7 Floorbeam spa, at 23'-2" = 162'-2"

Span 15

- *€ Pier 14*

- $\langle 5 \rangle$ Cut existing Expansion Dam (Finger P Joint) and reinstall See Sheet No. 29 of 33
- (6) Pier 8 Cap Repair See Sheet No. 32 of 33
- $\langle 7 \rangle$ Missing Fastener Replacement See Sheet No. 21 of 33
- $\langle 8 \rangle$ Structural Steel Repair A See Sheet No. 17 of 33

(10)-

66′-3"

3 Floorbeam

spa, at 22'-1

= 66'-3"

- (9) Structural Steel Repair B See Sheet No. 18 of 33
- (10) Tack Weld Removal See Sheet No. 21 of 33
- (11) Structural Steel Repair C See Sheet No. 19 of 33

- (12) Structural Steel Repair D See Sheet No. 19 of 33
- (13) Structural Steel Repair E See Sheet No. 20 of 33
- $\langle 14 \rangle$ Structural Steel Repair F See Sheet No. 20 of 33
- (15) Structural Steel Repair G See Sheet No. 18 of 33
- (16) Pier 19 Concrete Repair See Sheet No. 32 of 33
- \$\langle 17 \rangle Structural Steel Repair H See Sheet No. 18 of 33
- (18) Slope Wall Repair at North Abutment See Sheet No. 31 of 33

-- € Pier 16

7 Floorbeam spa, at 23'-2" = 162'-2"

Span 17

- (19) Median Barrier Concrete Repair See Sheet No. 27 of 33
- (20) Structural Steel Repair I See Sheet No. 21 of 33
- (21) Protective Shield See Sheet No. 7 of 33

Note: For field welding of stiffeners, see Sheet No. 33 of 33.

Lateral Bracing, typ.

7 Floorbeam spa. at 23'-2" = 162'-2"

Span 18

- *€ Pier 17*

For location of Repair Items 12 to 19, see Sheet No. 7 of 33.

(11)-

- € Pier 18

See Sheet No. 7 of 33

REPAIR AND REPLACEMENT

ITEMS - 1 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

TOTAL SHEET SHEETS NO. SECTION COUNTY SHEET NO. 6 (81-1B)M-4 ROCK ISLAND 75 33 SHEETS SN 081-0011 CONTRACT NO. 64F31 FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT

DESIGNED YSS CHECKED DWP DRAWN PRC CHECKED YSS

09/17/09


Stringer No.

typ.




10 Floorbeam spa, at 23'-9" = 237'-6"


370'-0" Span 14



PARTIAL FRAMING PLAN

Note: Girders, lateral bracing between girders and inspection walkway not shown for clarity.





DESIGNED YSS

CHECKED DWP

DRAWN PRC


CHECKED YSS

09/17/09

MODJESK JandMASTERS

Consulting Engineers
SINCE 1893

PARTIAL PLAN
West Approach - Iowa side



DETAIL OF PROTECTIVE SHIELD

Note:

For locations see Repair Item No. 21 on Sheet No. 6 of 33.

Note

For description of work see Repair Legend on Sheet No. 6 of 33.

REPAIR AND REPLACEMENT


ITEMS - 2

I-80 OVER

MISSISSIPPI RIVER

STRUCTURE NO. 081-0011

SHEET NO. 7	F.A.I. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4			ROCK ISLAND	75	34
33 SHEETS		SN 081-0	011	CONTRACT	NO. 64	F31	
	FED. RO	DAD DIST. NO. 7	ILLINOIS	FED. A	D PROJECT		



SECTION B-B

33 SHEETS

SN 081-0011

FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT


CONTRACT NO. 64F31


side of bridge

For FLRBM NO., see Sheet Nos. 6 and 7 of 33.


CHECKED YSS

09/17/09





SUGGESTED SLAB/STRINGER TEMPORARY SUPPORT - STRINGER LINES 1, 2, 7 AND 8 TYPICAL ELEVATION



SUGGESTED SLAB/STRINGER TEMPORARY SUPPORT - STRINGER LINES 1, 2, 7 AND 8 REMOVAL ELEVATION

(Partial slab, stringer ends and cantilever floorbeam removed)

SLAB/STRINGER TEMPORARY
SUPPORT CONCEPTUAL DETAILS

I-80 OVER

MISSISSIPPI RIVER

STRUCTURE NO. 081-0011

Notes

The Contractor shall submit design of the Temporary Support System for approval by the Engineer prior to commencing any work as specified in the Special Provision "Structural Assessment Reports for Contractor's Means and Methods" and "Temporary Support System".

Dead load = 17k at each stringer end (service load).

Cost of Slab/Stringer Support System shall be included in Temporary Support System.

DESIGNED YSS


CHECKED DWP

DRAWN PRC

CHECKED YSS

09/17/09


Note: Expansion Dams not shown for clarity.



STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 1 AND 8 TYPICAL REMOVAL ELEVATION

Note

Remaining exposed shear connectors damaged as a result of construction shall be replaced, at the contractor's expense to the satisfaction of the engineer.



STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 2 AND 7 TYPICAL REMOVAL ELEVATION

DESIGNED YSS


CHECKED ACK


DRAWN PRC

CHECKED YSS

09/17/09

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION







STRINGER END REPAIR AT EXPANSION DAM PIER 8 AND 24 - STRINGER LINES 1, 2, 7 AND 8 TYPICAL ELEVATION

Note:

Load carrying components designated "NTR" shall conform to the supplemental requirement for Notch Toughness, Zone 2.




SECTION A-A



BEARING P

<u>DIAPHRAGM CONNECTION AT EXPANSION DAM</u> <u>PIER 8 AND 24 - STRINGER LINES 3 AND 6</u>



SECTION B-B Stringer No. 1 & 8 shown, Stringer No. 2 & 7 similar

Notes:

For General Notes, see Sheet No. 3 of 33.
For Splice details, see Sheet No. 14 of 33.
For deck removal, see Sheet No. 23 of 33.
For Expansion Dam details, see Sheet No. 29 of 33.
Two ¹₈" adjusting shims shall be provided for each bearing in addition to all other plates or shims and placed as shown on bearing details.

SECTION C-C


BILL OF MATERIAL

Item	Unit	Total*
Structural Steel Repair	Pound	209,500

^{*} For all stringer end repairs.

STRINGER END REPAIR DETAILS - 1 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 11	F.A.I. RTE.	SECTION		con	INTY	TOTAL SHEETS	SHEET NO.		
0	80	(81-1B)M-4			ROCK	ISLAND	75	38	
33 SHEETS SN 081-0011			CONT	RACT	NO. 64	IF 31			
	FED. RO	DAD DIST.	NO. 7	ILLINOIS	FED. A	AID PROJE	CT		



,52"

NOMINAL SHIM

L3x3x³8, use existing

angles as template, typ.

 $\sqrt{\frac{3}{4}}$ " ϕ H.S. Bolts

¹⁵₁₆ ′′ ¢ Holes

1" min, radius

Remove and replace

diaphragm and conn.

anales

4 C 1'- 11"± 1'-11"± Hinges 12, 13 and 15 1'-3"± 1'-3"± Pier 19 - € Existing Floorbeam


DIAPHRAGM CONNECTION AT EXPANSION DAM HINGES 12, 13, 15 AND AT PIER 19 STRINGER LINES 3 AND 6

TABLE OF BEARING P'S

LOCATION	GDR. SPAN	STRINGER NO.	"m"	"n"	"†"	NOMINAL SHIM
	Single	1 & 8	5"	5"		Req'd.
Hinge 12	Single	2 & 7	5"	5"	12"	
& <i>1</i> 5	Double	1 & 8	5"	5"	14"	Req'd.
	Double	2 & 7	31 ₂ "	5 ³ 4"	14"	
Hinge 13	Double	1 & 8	5"	5"	14"	Req'd.
rilige 15	Double	2 & 7	312"	5 ³ 4"	4"	
Pier 19	Single	1 & 8	5"	5"	2"	
F161 19	Single	2 & 7	5"	5"	2"	

Slope to match existing expansion dam slope. Use existing diaphragm and stringer end as template for locating top of new diaphragm

SECTION A-A



Tight Fit

Mill Stiffener

to bear

Clip 1" Horiz. x 212" Vert.

TOD & Bottom, typ.

Brg. Stiff, 12 58" x 4",

SECTION B-B

Stringer No. 1 & 8 shown, Stringer No. 2 & 7 similar

Notes:

For General Notes, see Sheet No. 3 of 33. For Bill of Material, see Sheet No. 11 of 33. For Splice details, see Sheet No. 14 of 33. For deck removal, see Sheet No. 22 of 33. For Expansion Dam details, see Sheet No. 29 of 33.

Two ^lg" adjusting shims shall be provided for each bearing in addition to all other plates or shims and placed as shown on bearing details.

STRINGER END REPAIR DETAILS - 2 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

TOTAL SHEET NO. F.A.I. RTE. SECTION COUNTY SHEET NO. 12 (81-1B)M-4 ROCK ISLAND 75 39 33 SHEETS SN 081-0011 CONTRACT NO. 64F31 FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT

STRINGER END REPAIR AT EXPANSION DAM HINGES 12, 13, 15 AND AT PIER 19 STRINGER LINES 2 AND 7 - TYPICAL REMOVAL ELEVATION

← @ Exist. Cantilever Floorbeam

1'-11"±

1'-3"±

1'-11"±

1'-3"±

,512",

Existing Stringer BEARING P

-To be removed

1'- 11"

SECTION C-C

Grind cut edge to smooth,

ANSI 1000 finish

Hinges 12, 13 and 15

Existing

Diaphragm

to remain -

Pier 19

MODIESK Iand MASTERS Consulting Engineers

To be removed

DESIGNED YSS


CHECKED ACK


DRAWN PRC


CHECKED YSS

09/17/09

See Sheet No. 20 of 33 for structural steel repair F for additional repair at Pier 19.









ELEVATION SHEAR CONNECTORS FOR STRINGER END LINES 1, 2, 7 AND 8 AT HINGES 12, 13, 14, 15 AND AT PIERS 8 & 24

18 Studs required per stringer end



ELEVATION SHEAR CONNECTORS FOR STRINGER END LINES 1, 2, 7 AND 8 AT PIER 19

21 Studs required per stringer end



SECTION A-A

DESIGNED YSS


CHECKED ACK

DRAWN PRC


CHECKED YSS

09/17/09






SECTION B-B




SECTION C-C




ELEVATION SHEAR CONNECTORS FOR STRINGER END LINES 1, 2, 7 AND 8 AT RELIEF JOINT EXPANSION SIDE

16 Studs required per stringer end



ELEVATION SHEAR CONNECTORS FOR STRINGER END LINES 1, 2, 7 AND 8 AT RELIEF JOINT FIXED SIDE

Stringer lines 1 and 8 without lateral 18 Studs required per stringer end



SHEAR CONNECTORS FOR STRINGER END LINES 1 AND 8 AT RELIEF JOINT FIXED SIDE WITH LATERAL 21 Studs required per stringer end

–2 Spa. at 3³4" = 7¹2" 3 Spa. at 3½" = 10½" - Cut existing lateral to clear wider floorbeam flange - See Note A 0110 12 See Note B-

LATERAL CONNECTON P

2'-212"

At Spans 9, 19 and 22 No. Reg'd. 8

Note A:

Field drill hole maintaining a minimum of 1^{l_2} " from the edge of steel.

Field drill holes using existing holes in lateral as template. Remainder of holes may be shop drilled.

TABLE OF SHEAR CONNECTOR QUANTITIES


LOCATION	NO. STUDS
Pier 8	72
Hinge 12	144
Hinge 13	144
Hinge 14	144
Hinge 15	144
Pier 19	168
Pier 24	72
Relief Jt. Exp.	1600
Relief Jt. Fix	1656
Relief Jt. Fix*	168

*with Lateral connection

Notes: ¹⁵₁₆ " ϕ Holes unless noted otherwise. For Bill of Material, see Sheet No. 11 of 33.

STRINGER END REPAIR DETAILS - 5 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 15	F.A.I. RTE.	SECTION			COUNTY		TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4			ROCK	ISLAND	75	42
33 SHEETS		SN 081-0011			CONT	TRACT	NO. 64	F31
-	FED. RO	DAD DIST. NO. 7	ILLINOIS	FED. AI	D PROJ	ECT		




ELEVATION AT RELIEF JOINT

Adjacent stringer and fixed bearing not shown for clarity.

TABLE OF FILL P's

	LOCATION	GDR. SPAN	STRINGER NO.	"†"	NOMINAL SHIM
	Relief Joint Exp. Side	Single	1, 2, 7 & 8	3 ₁₆ "	
		Double	1 & 8	¹⁵ 16 "	Req'd.
		Double	2 & 7	3 ₁₆ "	




SIDE VIEW

*** Elastomer shall have a specified shear modulus equal to 0.175ksi. The measured shear modulus shall lie with 15% of the specified value. Elastomer with minimum low-temperature Grade 3 is required.

Shim plates shall not be placed under Bearing Assembly.


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



SECTION A-A

* Stringer Lines 1 and 8 - All Girder Spans ** Stringer Lines 2 and 7 - Double Girder Spans only

TYPE I ELASTOMERIC EXP. BRG.




ELEVATION

Stringer Lines 1 and 8 - All Girder Spans

Stringer Lines 2 and 7 - Double Girder Spans only

BEARING ASSEMBLY DETAILS

Note: Not to scale.



ELEVATION

Stringer Lines 2 and 7 - Single Girder Spans only

37₈" € 11/4" \$ Hole 5⁵8"

Notes:

54"

NOMINAL SHIM

Bearing Assembly, Type I,

as shown on bearing details.

Side and longitudinal retainers and steel plates required for the bearing assembly shall be included in the cost of Elastomeric

Two 8" adjusting shims shall be

provided for each bearing in addition

to all other plates or shims and placed

SIDE RETAINER - TYPE B

SECTION A-A


Stringer Lines 2 and 7 - Single Girder Spans only

Equivalent rolled angle with stiffeners will be allowed in lieu of welded plates.


8" 5/2" ⁵16 V 1'-312' 116" \$ Holes -

- Stiff. P 1/2"

LONGITUDINAL RETAINER - TYPE A



LONGITUDINAL RETAINER - TYPE B



LONGITUDINAL RETAINER - TYPE C


BILL OF MATERIAL

Item	Unit	Total
Elastomeric Bearing Assembly, Type I	Each	100

ELASTOMERIC BEARING ASSEMBLY I-80 OVER MISSISSIPPI RIVER

STRUCTURE NO. 081-0011

SHEET NO. 16	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4	ROCK ISLAND	75	43
33 SHEETS		SN 081-0011	CONTRACT	NO. 64	F31
	FFD. RO	DAD DIST. NO. 7 ILLINOIS FED. AL	ID PROJECT		





09/17/09







will be allowed in lieu of welded plates.





STRUCTURAL STEEL REPAIR A SPAN 11, STRINGER 6 AT FLOORBEAM 6





SECTION B-B

The Contractor shall submit Temporary Jacking Details to the Engineer for approval prior to bronze plate replacement. The stringer service level dead load reaction is 17 kips. Cost of Temporary Jacking shall

be included in Jacking and Cribbing.

The bronze plate shall conform to ASTM B22. Cost of bronze plate is included with the cost for Structural Steel Repair.

Coordinate Structural Steel Repair A with cantilever floorbeam replacement and stringer end repair. See Sheets 8 and 13 of 33 for details.

BILL OF MATERIAL


Item	Unit	Total
Structural Steel Repair	Pound	30
Cleaning and Painting Structural Steel, Location 1	L. Sum	1
Jacking and Cribbing	L. Sum	1

MISCELLANEOUS STEEL REPAIR DETAILS - 1 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 17	F.A.I. RTE.	SECTION			COU	NTY	TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4		ROCK I	ISLAND	75	44	
33 SHEETS		SN 081-0011			CONT	RACT	NO. 64	F31
	FED. RO	DAD DIST. NO. 7	ILLINOIS F	ED. AI	D PROJE	СТ		

DESIGNED	RLM	
CHECKED	DWP	MODJESK JandMASTER
DRAWN	AEC	Consulting Engineers
CHECKED	RIM	SINCE 1893

09/17/09



9 Staggered Spa. at 3"


= 2'-3"

VIEW B-B

Note:


Gaps between the existing steel and the new steel angles and/or cover plates shall be sealed with an approval polyurethane sealant. The sealant shall be compatible with the proposed paint system and shall be submitted to the Engineer for approval prior to use. All costs associated with the installation of the sealant shall be included with the cost for Structural Steel Repair.

STATE OF ILLINOIS




STRUCTURAL STEEL REPAIR H SPAN 24, FLOORBEAM 4

(Looking South)



VIEW D-D



Unit

Pound

Total 870

SECTION A-A

BILL OF MATERIAL

Item

Structural Steel Repair

New L5x5x38 --- € Floorbeam

SECTION C-C

Notes:

Grind heels of angles as required for

installation.
Field drill holes in existing floorbeams and new plates using new angles as templates.

Load carrying components designated "NTR" shall conform to the supplemental requirement for Notch Toughness, Zone 2.

MISCELLANEOUS STEEL REPAIR DETAILS - 2 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 18	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
0.122. 10.10	80	(81-1B)M-4	ROCK ISLAND	75	45
33 SHEETS	33 SHEETS SN 081-0011			NO. 64	F31
	FED. RO	DAD DIST, NO. 7 ILLINOIS FED. A	ID PROJECT		

Stringer 4 Stringer 5 **→** C - New Ĺ5x5x ³8 - New L5x5x³8 – New L5x5x³8 New L5x5x³8 - New L5x5x³8 x 2'-6" Long, NTR x 2'-1" Long. x 2'-1" Long, x 4'-4'2" Long, NTR x 2'-6" Long, NTR NTR New ₽ 12" x 3₈" 9 Staggered Spa. at 3" 7 Staggered Spa. 7 Staggered Spa. x 14'-0'8" Long, NTR E_♠ = 2'-3" at 3" = 1'-9" at 3" = 1'-9" 16 Staggered Spa. at 3" = 4'-0" 9 Staggered Spa. at 3" **4** C = 2'-3"

7 Staggered Spa. 4¹⁵16 "3"

STRUCTURAL STEEL REPAIR G SPAN 20, FLOORBEAM 1

(Looking South)

9 Staggered Spa. at 3" 5\(5\) " = 2'-3"	16 Staggered Spa. at 3" = 4'-0"	5 ⁵ 8" 7 Staggered Spa. 4 ⁷ 8" at 3" = 1'-9"	9 Staggered Spa. at 3" 4 ⁷ ₈ '	" 7 Staggered Spa. 2


VIEW E-E


DESIGNED RLM CHECKED DWP DRAWN AEC

09/17/09

CHECKED RLM







VIEW C-C

P Washer 3" \$\phi x \big|_{16}" Thick with 1_{16}^{l} ϕ Hole Std. 34" Ø Washer 34" \$ Self Lock Nut


VIEW B-B


Stringer base plates not shown for clarity.

Gaps between the existing steel and the new steel angles and/or cover plates shall be sealed with an approval polyurethane sealant. The sealant shall be compatible with the proposed paint system and shall be submitted to the Engineer for approval prior to use. All costs associated with the installation of the sealant shall be included with the cost for Structural Steel Repair.

NEW SHOULDER BOLTS TO ACCOMODATE REPAIR ANGLE AT EXPANSION SIDE STRINGER CONNECTIONS AT SPAN 18, FLOORBEAM 6

(2 Required)





STRUCTURAL STEEL REPAIR C SPAN 18. FLOORBEAM 6 (Looking South)

* Fabricate new plates and angles for top flange repairs to match existing top flange profile. See Floorbeam Top Flange Profile detail.

STRUCTURAL STEEL REPAIR D SPAN 19. FLOORBEAM 3

(Looking South)

Grind heels of angles as required for

installation.

Field drill holes in existing floorbeams and new plates using new angles as

BILL OF MATERIAL

Item	Unit	Total
Structural Steel Repair	Pound	450

MISCELLANEOUS STEEL REPAIR DETAILS - 3 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 19	F.A.I. RTE.			SE	EC1	ΓΙΟΝ		со	UNTY	TOT SHEE		SHEE NO.
	80			(81	-1E	3)M-4		ROCK	ISLAND	7.	5	46
33 SHEETS			SN	081	-0	011		CON	TRACT	NO.	64	F31
	FED. R	OAD DI	IST.	NO.	7	ILLINOIS	FED.	AID PROJ	ECT			

SECTION A-A

-⊈ Floorbeam


New L5x5x³₈


4'-0" Parabolic Crown 2'-0" - Horizontal Line --- € Bridge


FLOORBEAM TOP FLANGE PROFILE


DESIGNED RLM CHECKED DWP MODJESK IandMASTERS Consulting Engineers
SINCE | 893 DRAWN AEC CHECKED RLM

09/17/09










STRUCTURAL STEEL REPAIR E

Typical Stringers 3 thru 6 except North side of Stringer 4 (See Repair F)




** Remove existing


L 3 x 3 x 38



Gaps between the existing steel and the new steel angles and/or repair plates shall be sealed with an approval polyurethane sealant. The sealant shall be compatible with the proposed paint system and shall be submitted to the Engineer for approval prior to use. All costs associated with the installation of the sealant shall be included with the cost for Structural Steel Repair.



REPAIR PE P 38" x 1'-3" x 1'-3'2" (14 Required)




REPAIR ANGLE E $L 3 \times 3 \times \frac{3}{8} \times 0' - \frac{5}{2}''$ (16 Reg'd) All Holes to be field drilled.

¹³16 ′′ min. ∮ Crack Arrestor Hole Tip of Crack, see Note.

CRACK ARRESTOR HOLE DETAIL

Note: Locate crack tip using liquid dye penetrant or magnetic particle testing. Drill 13 ₁₆ $^{\prime\prime}$ min. ϕ Crack Arrestor hole at the crack tip. After crack arrestor hole has been drilled, dye penetrant or magnetic particle testing shall be used to verify that the drilled hole has captured the crack tip. Cost shall be included with Structural Steel Repair.



REPAIR P F P 38" x 1'-3" x 2'-0' (2 Required)

BILL OF MATERIAL

Item Unit Total Structural Steel Repair 660 Pound

±12" Field drill holes using existing holes as template 2'-0"

7 Spaces at $\pm 3'' = \pm 1' - 9''$


REPAIR ANGLE F L 4 x 4 x ½ x 2'-0" (2 Req'd) All Holes to be field drilled.

MISCELLANEOUS STEEL REPAIR DETAILS - 4 I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 20	F.A.I. RTE.			SE	EC.	ΓΙΟΝ	со	UNTY	TOTAL SHEETS	SHEET NO.
	80			(81	-1E	3)M-4	ROCK	ISLAND	75	47
33 SHEETS			SN	081	-0	011	CON	TRACT	NO. 64	F31
	FED. F	ROAD D	IST.	NO.	7	ILLINOIS FED.	AID PROJ	ECT		


DESIGNED IDOT CHECKED IDOT DRAWN IDOT

CHECKED IDOT 09/17/09




SHOULDER BOLT DETAIL

Note: Install shoulder bolts with $^{\prime}_{6}$ " gap between bolt head and plate washer.




SPAN 15, INSIDE SOUTH GIRDER
(Looking West)

- * Grinding shall be done parallel to the longitudinal axis of the member. Ground surfaces shall be inspected for cracks using dye penetrant or magnetic particle testing. Any cracks that can not be removed by grinding approximately \(\frac{1}{4} \) deep shall be identified and reported to the Bureau of Bridges and Structures for further disposition. Ground surfaces shall be spot cleaned and pointed with an aluminum epoxy mastic primer followed by a final coat to match the color of the existing beam.
- ** The Contractor shall submit limits of removal and procedure for approval to the Engineer prior to commencing work.



STRUCTURAL STEEL REPAIR I PIER 13, FLOORBEAM 7

Looking South



SECTION A-A

Note:

Coordinate Structural Steel Repair I with field welding of stiffeners, see Sheet No. 33 of 33 for details.

Note

All costs associated with replacing missing fasteners and removing tack welds shall be included with the cost for Structural Steel Repair.

BILL OF MATERIAL

Item	Unit	Total
Structural Steel Repair	Pound	10

MISCELLANEOUS STEEL
REPAIR DETAILS - 5
I-80 OVER
MISSISSIPPI RIVER
STRUCTURE NO. 081-0011

SHEET NO. 21	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4	ROCK ISLAND	75	48
33 SHEETS	·	SN 081-0011	CONTRACT	NO. 64	F31
•	FED. RO	DAD DIST, NO. 7 ILLINOIS FED. A	D PROJECT		

MISSING FASTENER REPLACEMENT

SPAN	MEMBER	LOCATION	REQUIRED NO. BOLTS	BOLT LENGTH	THREAD LENGTH
10 Stringer 5 at Floorbeam 5 Stringer to floorbeam connection / fixed side of		Stringer to floorbeam connection / fixed side of relief joint	2	2 ⁵ 16"	1/2"
11	Stringer 5 at Floorbeam 6	Stringer to floorbeam connection / expansion side of relief joint	2	See Shoulder Bolt Deta	
14	Floorbeam 4 at Inside North Girder	Floorbeam bottom flange to girder connection	1	2 ⁵ 16"	1/2"
17	Stringer 6 at Floorbeam 5	Stringer to floorbeam connection / expansion side of relief joint	1	See Should	ler Bolt Detail


Note:


Missing fasteners shall be replaced with $^{7}_{8}$ " ϕ H.S. bolts unless noted otherwise.


DESIGNED	RLM
CHECKED	DWP
DRAWN	AEC
CHECKED	RLM





09/17/09
















* Locations where existing parapet requires additional removal to facilitate light standard replacement care should be taken to clean, strengthen and incorporate existing reinforcement.






PLAN LIGHT STANDARD REPLACEMENT

See Table for locations


Note:

For deck removal, see Sheet Nos. 25 and 26 of 33.



SECTION A-A


Cost of anchor rods and conduit is included with Concrete Superstructure.



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

TABLE OF DIMENSIONS

SPAN	FLRBM NO.	"d"
9	FB4	± 3'-10" North of Relief Joint
11	FB2	± 4'-10" North of Relief Joint
17	FB5	± 3'-10" South of Relief Joint
19	FB3	± 3'-10" South of Relief Joint
21	FB2	± 4'-0" South of Relief Joint
24	FB2	± 4'-0" South of Relief Joint



14" ANCHOR BOLT

€ Expansion Dam--Existing surface mounted junction boxes and flexible conduit to be removed from the outside of each of the parapets and reinstalled after parapet replacement.

TYPICAL PARAPET ELEVATION AT EXPANSION DAM SHOWING JUNCTION BOXES

Notes:

Services carried in conduits shall remain operational during construction.

Damaged or deteriorated conduit shall be called to the attention of the Engineer.


Conduit system damaged as a result of construction operations shall be repaired or replaced, at the Contractor's expense, to the satisfaction of the Engineer.

The cost for removal and replacement of the conduit system shall be included in the cost bid for Concrete Superstructure.


SUPERSTRUCTURE BILL OF MATERIAL

Bar	No.	Size	Length	Shape
d6(E)	18	#6	4'-5"	L
d7(E)	30	#6	8'-11"	~
Reinfor	cement	Bars,	Pound	530
Epoxy Coated			1 ound	550
Concrete Removal			Cu. Yd.	3.6
Concrete			Cu. Yd.	3.6
Supers	tructure)	Cu. 70.	3.0

Reinforcement bars designated (E) shall be epoxy coated.



BAR d6(E)




BAR dr(E)

LIGHT STANDARD SUPPORT AND MISCELLANEOUS CONCRETE DETAILS

I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 28	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
0.722.7.7(0.124	80	(81-1B)M-4	ROCK ISLAND	75	5 <i>5</i>
33 SHEETS		SN 081-0011	CONTRACT	NO. 64	F31
	FED. RO	DAD DIST. NO. 7 ILLINOIS FED. A	ID PROJECT		



SECTION A-A EXPANSION DAM AT STRINGER LINES 1, 2, 7 AND 8

12'-6"

D

Symm, about

 $B \blacktriangleleft$

0

 $B \blacktriangleleft 1$

09/17/09


Existing W24 Stringer

Studs damaged as a result of construction shall be replaced, at the contractor's expense to the satisfaction of the engineer.

Cut line for existing joint and

< at cut line

elastomeric side flap



SECTION B-B EXPANSION DAM AT STRINGER LINES 3 THRU 6

elastomeric side flap

38'' Stainless steel bolts with

locking washers & nuts. Provide


brass grommet in trough. (Typ.)

elastomeric trough, full length, and existing 12" x 6" R's

New 18" Fabric reinforced


० ठ

1'-6"



SECTION C-C

LOCATION	''d''	′′x′′
Pier 8	6"	5′′
Hinge 12	6"	5′′
Hinge 13	54"	4 ⁵ 8"
Hinge 15	6"	5′′
Pier 19	6 ³ 4"	5 ³ 8''
Pier 24	634''	5 ³ 8′′



Slope 58"/ft.

New Cantilever

Floorbeam

Existing Finger

Plate Joint

±18" cts., typ.

 $A \blacktriangleleft$

New W24

Stringer ena

* Typical both sides of expansion dam except at Pier 8 and 24, girder span side only.

31'-6"

DESIGNED YSS CHECKED DWP MODJESK JandMASTERS DRAWN PRC Consulting Engineers SINCE 1893 CHECKED YSS

Existing

Floorbeam

PART ELEVATION AT EXPANSION DAM SHOWING TROUGH

19'-5" *Limits of existing expansion dam removal and reinstallation

TROUGH SPLICE DETAIL

At centerline of bridge

Cost of the new full length Is" fabric reinforced elastomeric trough shall be included in Expansion Joint (Special).

BILL OF MATERIAL

Item	Unit	Total
Expansion Joint (Special)	Foot	233


Cost of removing, reinstalling and welding

existing finger plate shall be included in

Expansion Joint (Special).

EXPANSION DAM REPAIR AND REPLACEMENT I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011


SHEET NO. 29	F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1B)M-4	ROCK ISLAND	75	56
33 SHEETS		SN 081-0011	CONTRACT	NO. 64	F31
	FED. RO	DAD DIST. NO. 7 ILLINOIS FED. A	ID PROJECT		




* Granular or solid flux filled headed studs conforming to Article 1006.32 of the Std. Specs., automatically end welded.

or chipped off flush with the plates

after forms are removed, typ.



At Hinge 14, where joint is fixed. opening shall be set at 1 2" at all




At Hinge 14, where joint is fixed, opening shall be set at 234" at all temperatures.

bolts. All bolts shall be burned, sawed. or chipped off flush with the plates after forms are removed, typ.


SECTION THRU ROLLED RAIL JOINT

At Hinge 14, where joint is fixed, opening shall be set at 2" at all temperatures.


SECTION THRU WELDED RAIL JOINT



***Back gouge not required if complete joint penetration is verified by mock-up.



ANCHOR P (for welded rail)



TYPICAL END TREATMENT AT PARAPET


Notes:

The strip seal shall be made continuous and shall have a minimum thickness of $\frac{1}{4}$ ". The configuration of the strip seal shall match the configuration of the Locking Edge Rails. Open or "webbed" strip seal gland configurations are not permitted. The gland shall be sized for a maximum rated movement of 4 inches.

The height and thickness of the Locking Edge Rails shown are minimum dimensions. The actual configuration of the Locking Edge Rails and matching strip seal may vary from manufacturer to manufacturer. Flanged edge rails will not be allowed. Locking Edge Rails may be spliced at slope discontinuities and stage construction joints.

The manufacturer's recommended installation methods shall be followed. The joint opening and deck dimensions detailed on the superstructure are based on a rolled rail expansion joint. If the Contractor elects to use the welded rail expansion joint, the opening and deck dimensions shall be modified according to the dimensions detailed on this sheet. Required modifications shall be made at no additional cost to the State.

All steel components shall be galvanized after fabrication according to Article 520.03 of the Standard Specifications.



TYPICAL TREATMENT AT EXISTING MEDIAN

SECTION

(81-1B)M-4

FED. ROAD DIST. NO. 7 ILLINOIS FED. AID PROJECT


ROLLED EXTRUDED RAIL

**Trim as required to clear the stringer flange. WELDED RAIL


LOCKING EDGE RAIL SPLICE

The inside of the locking edge rail groove shall be free of weld residue.

LOCKING EDGE RAILS



26 Eastbound 26 Westbound



SECTION A-A

-Limit of median and slab concrete removal and repair. Existing median reinforcement to remain, clean and incorporate into repair. Bend reinforcement as required to facilitate installation of the joint. Cost included with Preformed Joint Strip Seal.

BILL OF MATERIAL

Item	Unit	Total
Preformed Joint Strip Seal	Foot	1636


PREFORMED JOINT STRIP SEAL I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

DESIGNED YSS CHECKED DWP MODJESK JandMASTERS DRAWN PRC Consulting Engineers CHECKED YSS

09/17/09

SHEET NO. 30	F.A.I. RTE.	SECTIO
311EE1 140. 30	80	(81-1B)M-
33 SHEETS		SN 081-0011


TOTAL SHEET NO. COUNTY ROCK ISLAND 75 57 CONTRACT NO. 64F31



REMOVAL DETAIL

REPAIR DETAIL

SLOPE WALL REPAIR AT NORTH ABUTMENT



Note:

The existing earth bed below the concrete slope protection to be removed is eroded to a depth of approximately 3'-6". The Contractor shall furnish earth fill satisfactory to the Engineer and repair the earth bed as directed by the Engineer. All work required to repair the earth bed, including furnishing and placing earth fill, shall be paid for at the contract unit price per cubic yard for Embankment.

Slope wall shall be reinforced with welded wire fabric, 6" x 6" - W4.0 x W4.0, weighing 58 lbs. per 100 sq. ft. Cost of the welded wire fabric is included with the cost of Slope Wall 4 inch.

BILL OF MATERIAL

Item	Unit	Total
Slope Wall Removal	Sq. Yd.	11.7
Embankment	Cu. Yd.	6.3
Slope Wall 4 inch	Sq. Yd.	11.7

SLOPE WALL REPAIR DETAILS I-80 OVER MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 31	F.A.I. RTE.	SE(СО	UNTY	TOTAL SHEETS	SHEE NO.		
	80	(81-	ROCK	ISLAND	75	58		
33 SHEETS		SN 081-0011				TRACT	NO. 64	1F31
	FED. RO	DAD DIST. NO. 7	ILLINOIS	FED. A	ID PROJ	ECT		

DESIGNED RLM

CHECKED DWP


DRAWN AEC

MODJESK landMASTERS

Consulting Engineers
SINCE | 893


CHECKED RLM

09/17/09



PARTIAL ELEVATION


(Looking South)




PARTIAL ELEVATION (Looking North)


PIER 8 CONCRETE REPAIR

Note:
Access ladders not shown for clarity. The Contractor may remove and reattach the access ladders to perform the required concrete repairs at his expense.





VIEW B-B



PIER 19 CONCRETE REPAIR

(Looking East)

LEGEND

Structural Repair of Concrete (Depth equal to or less than 5")

BILL OF MATERIAL

Item	Unit	Total
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	11.6

CONCRETE REPAIR DETAILS <u>I-80 OVER</u> MISSISSIPPI RIVER STRUCTURE NO. 081-0011

SHEET NO. 32	F.A.I. SECTION			SECTION				COUNTY			S	SHEET NO.
	80	(81-1B)M-4				ROO	K	ISLAND	75		59	
33 SHEETS		SN 081-0011			CC	N	TRACT	NO. 6	54	F31		
	FED. RO	DAD DIST.	NO.	7	ILLINOIS	FED.	AID PF	10	JECT			


VIEW A-A



DESIGNED RLM CHECKED DWP DRAWN AEC

CHECKED RLM

09/17/09




PARTIAL FRAMING PLAN SHOWING MECHANICAL TREATMENT AND FIELD WELDING LOCATIONS

Note:


CHECKED YSS

09/17/09

Mechanical Treatment and Field Welding at Floorbeams along Stringer lines 2, 3, 6 and 7 as shown.



DETAIL OF MECHANICAL TREATMENT OF STEEL WELDS



Note: Stringer not shown.

TYPICAL SECTION AT EXISTING FLOORBEAM Looking Upstation

FIELD WELDING NOTES:

Field Welding:

All field welding operations, including cleaning, testing and inspection, shall be performed in accordance with the AASHTO/AWS Bridge Welding Code D 1.5-2008 (BWC) and additional requirements as specified in these notes.

Steel base materials to be welded have been tested and are considered weldable grades of steel. Carbon equivalents for the floorbeam flange and stiffeners average 0.33 and 0.29 respectively. Therefore, the special weld procedure qualification testing and weldability investigation required by Clause 5.4.3 of the BWC are not required to be performed by the Contractor.

All field welding shall be performed by the manual Shielded Metal Arc Welding (SMAW) process. Other welding processes will not be considered for approval. Welding electrodes used to perform the welding shall be E7018-H4R classification. Welding electrode storage and handling on the worksite shall be in accordance with Clause 4.5 of the BWC and shall be constantly monitored and approved by the Contractor's QC Certified Welding Inspector (CWI).

Prior to start of the work, the Contractor shall submit to the Engineer for approval a properly prepared Welding Procedure Specification (WPS). The WPS shall include all information as required by the BWC.

Welder Qualification Tests:

Welders proposed to perform the work shall be qualified for overhead position fillet welds in accordance with BWC requirements. Copies of welder qualification documents shall be reviewed and approved by the Contractor's QC CWI and subsequently provided to the Engineer.

In addition, all welders shall be required to successfully complete a one-time special on-site overhead fillet weld qualification test immediately prior to start of the work. The qualification test shall be a fillet weld T-Test Plate (Option I) as per Clause 5.23.1.4 of the BWC. Only visual and fillet weld break testing is required. Macroetch testing is not required. On-site welder qualification testing shall be administered by the Contractor's QC CWI. Cost for the additional testing shall be included with the various items of work. No additional compensation will be made to the Contractor for performing these tests.

Cleaning Prior To Welding:

The ends of the stiffeners and the area of the floorbeam flange to be welded shall be prepared by blast cleaning to a near-white condition (SSPC 10). All corrosion and paint shall be removed for at least three (3) inches beyond the limits of the weld zone, with special attention to remove corrosion at the root of the proposed fillet welds.

Surfaces to be welded shall be free of surface rust and meet SSPC-10 condition requirements immediately prior to welding. Should there be a delay between blast cleaning and welding that results in surface flash rusting, blast cleaning of the weld area shall be repeated.

The Contractor's attention is directed to the fact that the existing paint coatings on the structure may contain lead and the work must comply with all applicable federal and state regulations regarding worker safety and environmental hazards for removal of lead-based coatings.

Welding Preheat:

Preheating operations shall be in accordance with Clause 4 of the BWC, except that the minimum preheat and interpass temperature shall be 250 degrees F. The Contractor's QC CWI shall verify and monitor minimum preheat and interpass temperatures.

Weld Quality:

All welds shall be visually inspected and approved by the Contractor's QC CWI.

Weld quality shall meet the requirements of Clause 6.26 of the BWC.

Fillet weld toe undercut shall not exceed 0.010 inches on the floorbeam flange and l_{32} inches on the stiffener.

Non-Destructive Testing (NDT) of Welds:

After visual inspection and approval by the Contractor's QC CWI, all welds shall be 100% inspected by Magnetic Particle Testing (MT). Personnel performing the MT and testing procedures shall be in accordance with Clause 6 of the BWC.

The Contractor's QC CWI shall verify qualifications of the NDT personnel, witness all MT testing and countersign all MT reports. Copies of completed MT reports shall be provided to the Engineer.

Costs for NDT shall be borne by the Contractor and included in the various items of work. No separate payment will be made for NDT.

Quality Control (QC) Inspection:

All phases of the work including cleaning, welding and testing shall be witnessed, inspected and approved by an inspector who is qualified as a Certified Welding Inspector (CWI) by the American Welding Society. Reference Clause 6 of the BWC.

The CWI shall be employed/engaged by the Contractor and costs will be included with the various items of work. No separate payment will be made for inspection costs. Scheduling of QC CWI inspection is the Contractor's responsibility.

Should the Contractor elect to perform work in multiple locations on the structure, a sufficient number of CWI's shall be made available to provide inspection at each work site location. The number of inspectors assigned and work locations shall be approved by the Engineer.

The Contractor's QC CWI shall prepare daily reports, suitable to the Engineer, which document the work inspected and welds approved.

Field Welding of Stiffeners shall be paid for at the contract unit price per each which shall include the required field welding on both sides of an individual bearing stiffener. The contract unit price per each shall include all materials, equipment and labor required for surface preparation, welding, follow-up painting, welder qualification testing, and quality control inspection, including non-destructive testing.

MECHANICAL TREATMENT OF WELD NOTES:

Mechanical treatment of welds shall be performed as specified in the Special Provision "Mechanical Treatment of Steel Welds."


Mechanical Treatment of Steel Welds shall be paid for at the contract unit price per each location. Each location shall include treatment of the new field welds on both sides of an individual bearing stiffener, treatment of the existing vertical welds on both sides of an individual bearing stiffener, and treatment of the existing horizontal weld between the top flange and web of the floorbeam.


BILL OF MATERIAL


Item	Unit	Total
Mechanical Treatment of Steel Welds	Each	828
Field Welding of Stiffeners	Each	828

FIELD WELDING
OF STIFFENERS
I-80 OVER
MISSISSIPPI RIVER
STRUCTURE NO. 081-0011

SHEET NO. 33	F.A.I. RTE.		SECTION				UNTY	TOTAL SHEETS	SHEET NO.
	80	(81-1E	3)M-4		ROCK	ISLAND	75	60
33 SHEETS		SN 081-0011					TRACT	NO. 64	F 31
	FED. RO	DAD DIST. N	0. 7	ILLINOIS	FED. A	ID PROJ	ECT		










GENERAL NOTES:


- 1 All exposed corners are to be filleted with a $\frac{3}{4}^{\prime\prime}$ dressed and beveled strip.
- 1 inch diameter deformed bars or sufficient length to ensure 6 inch minimum embedment in rail and supporting surface. Bars shall be either installed in supporting surface when placed or installed in drilled holes using polymer grout or hydraulic cement grout. Dower location may be adjusted 6 inches to avoid bridge approach reinforcment.
- 3 This work shall be paid for at the contract unit price per cu yd as Concrete Barrier Wall (Special).





Maria de Caractería de Caracte






FILE NAME =	USER NAME = cushmenbw	DESIGNED -	REVISED -	T
c:\pw_work\pwidot\cushmanbw\dØ149192\dØ9	489spl.dgn	DRAWN -	REVISED -	
	PLOT SCALE = 100.0000 '/ IN.	CHECKED -	REVISED -	
	PLOT DATE = Thu Sep 17 08:55:36 2009	DATE -	REVISED -	

STATE	OF	ILLINOIS
DEPARTMENT ()F	TRANSPORTATION

		CC			N BARRIER SECTION			
,	SHEET	NO.	OF	SHEETS	STA.	TO	STA.	

 F.A.I RTE.	SEC ⁻	TION	СО	UNTY	TOTAL SHEETS	SHEET NO.	
80	(81-1B	M-4		ROCK	ISLAND	75	63
			CO	NTRACT	T NO. (64F31	
FED, RO	DAD DIST, NO.	ILLINOIS	FED. A	ID PROJ	ECT		






EXIT SIGN;

6.000" Radius, 1.250" Border, White on Green [WELCOME] D; [CENTER] D; [EXIT] E Mod; Arrow Custom - 20.250" 45°;

Table of letter and object lefts

W E		L	C	0	M	E
5.750 14.250		20.625	27.000	33.875	41.375	49.375
C	E	N	T	E	R	
10.875	17.750	24.125	31.000	37.375	43.750	
E 17.375	X 24.875	1 33.500	T 36.750	10.00		
21 .750						

WELCOME **CENTER EXIT** OPEN **AHEAD**



EXIT SIGN;

6.000" Radius, 1.250" Border, White on Green; [WELCOME] D; [CENTER] D; [EXIT] D; [OPEN] D; [AHEAD] D;

Table of letter and object lefts.

W 5.750	E 14.250	L 20.625	C 27.000	0 33.875	M 41.375	E 49.375
C 10.875	E 17.750	N 24.125	T 31.000	E 37.375	R 43.750	
E 19.625	X 26.000	I 32.875	T 35.625	Sign to 1		
0 16.750	P 24.250	E 31.500	N 37.875			
A 12.500	H 20.750	E 28.000	A 33.875	D 42.125		



48.00" across sides 3.75" Radius, 1.00" Border, 0.63" Indent, Black on Orange; [STAY] E Mod 2K; [IN YOUR] E Mod 2K;

[LANE] E Mod 2K;

Table of letter and object lefts.

S 20.75	T 26.51	A 31.43	Y 37.97		
I 13.13	N 16.01	Y 26.87	o 33.77	U 40.25	R 46.79
L 20.93	A 25.73	N 32.87	E 39.41		

LE NAME =	USER NAME ≈ cushmanbw	DESIGNED -	REVISED -		
\pw_work\pwidot\cushmanbw\d0149192\d04	409spl.dgn	DRAWN -	REVISED -		
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -		
	PLOT DATE = Thu Sep 17 09:01:53 2009	DATE -	REVISED -	5 - 32	7.


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION		STA	GIN	3 SIC	N	DETAILS
Brown March Commencer Comm	SCALE:	SHEET NO.	OF	SHEETS	STA.	TO STA

	F.A.I. SECTION							CO	UNTY	TOTAL	SHEE NO.
	80			(81-1E	3) M-4			ROCK	ISLAND	75	64
_								CON	ITRACT	NO.	64F3:
	FED. R	DAD	DIST.	NO.	ILLINOIS	FED.	AI	PRO.	ECT		


NOTE: ANCHORING SHALL BE DONE USING TIE BARS AS SHOWN IN STANDARD 736006.

COST INCLUDED IN THE PAY ITEM "CONCRETE BARRIER TRANSITION".


ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE SHOWN.




PLAN VIEW



FILE NAME = USER NAME = cushmanbw	DESIGNED -	REVISED -			CONCRETE BARRIER TRANSITION	F.A.I.	SECTION	COUNTY TOTAL SHEET
c:\pw_work\pwidot\cushmanbw\d0149192\d09409spl.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS		CONCILLE DAMMER IMANGERSOR	80	(81-1B) M-4	ROCK ISLAND 75 65
PLOT SCALE = 50.0000 1/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION			- 50	101 107 111 1	CONTRACT NO. 64933
PLOT DATE = Thu Sep 17 09:02:06	009 DATE -	REVISED -		SCALE:	SHEET NO. OF SHEETS STA. TO STA.	FEO. ROA	DIST. NO. ILLINOIS FE	D. AID PROJECT






SECTION THRU MEDIAN BARRIER AT JOINT STA. 52+86

Note:

Cost of sliding plate assembly at the expansion loint shall be included in cost of "J" CONCRETE BARRIER, DOUBLEFACE, 42" HEIGHT. Sliding plate assembly shall be galvanized after fabrication according to Article 520.03 of the Standard Specifications.



SECTION A-A

* Granular or solid flux filled headed studs conforming to Article 1006.32 of the Std. Specs., automatically end welded.


SCALE:

FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED -
o:\pw.work\pwidot\oushmanbw\d0149192\d0	409spl.dgn	DRAWN -	REVISED -
	PLOT SCALE = 50.0000 1/ IN.	CHECKED -	REVISED -
	PLOT DATE = Thu Sep 17 08:56:38 2009	DATE -	REVISED -

STATE	: OF	: ILLINOIS
DEPARTMENT	0F	TRANSPORTATION

CLIDING DIATE DETAIL CTA 52 + 06						F.A.I. RTE.	F.A.I. SECTION			CO	UNTY	TOTAL SHEETS	SHEET NO.
2r	SLIDING PLATE DETAIL, STA. 52 + 86				. 52 + 86	80	(81-1E) M-4		ROCK	ISLAND	75	67
				,						CON	TRACT	NO.	64F31
	SHEET NO.	OF	SHEETS	STA.	TO STA.	FED. RO	AD DIST. NO.	ILLINOIS	FED. A	ID PROJ	ECT		

DELINEATION OF CENTER BARRIER OF TWO-LANE TWO WAY OPERATION




DESIGNER NOTE:

Use this with Traffic Control and Protection Standard 701416 when using concrete barrier vs. flexible delineators as the barrier on centerline.

- 1. All reflectors are to be amber in color and meet the specifications of Section 1097 of the Standard Specifications for Road and Bridge Construction.
- 2. All reflectors are to be installed in accordance with Section 782 of the Standard Specifications for Road and Bridge Construction.
- 3. On Interstates do not use the panels mounted on top of the barriers as shown on Standard 701416.
- 4. The cost of the reflectors will be included in the contract unit price per meter (foot) for Temporary Concrete Barrier.
- 5. ALL DIMENSIONS ARE IN MILLIMETERS (INCHES) UNLESS OTHERWISE NOTED.

ROAD CLOSED TO OVERSIZED LOADS



Permit Loads - Loads Over 13 Feet; 3.0" Radius, 1.3" Border, Black on Orange; [ROAD CLOSED TO] D; [OVERSIZED LOADS] D; [XX MILES AHEAD] D; Table of letter and object lefts.

R 0 A D C L 0 S E D T 0 84.6 0 V E R S I Z E D L 0 A D S 4.8 11.0 17.6 23.1 29.2 35.5 38.2 44.3 49.8 61.5 67.1 73.3 80.5 86.5 X X M I L E S A H E A D 7.6 13.6 25.3 32.3 35.1 40.6 46.2 57.9 65.1 71.4 76.6 83.7

All work to furnish and install these signs shall be included in the cost of the Traffic Control Standards and shall not be paid for separately.

ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.

REVISED - 1-9-08

DELINEATION OF CENTER BARRIER OF TWO-LANE TWO WAY OPERATION

25.4

ROAD CLOSED TO OVERSIZED LOADS

40.4

TYPICAL MEDIAN CROSSOVER CLOSURE


(WITH EMERGENCY OPENING)

REVISED - 1-08-08

REVISED - 1-24-07


WOOD POSTS, CABLE, AND SIGN SUPPORTS SHALL BE IN ACCORDANCE WITH SECTION 634 & 636 OF THE STANDARD SPECIFICATIONS FOR ROAD AND BRIDGE CONSTRUCTION.
THE PANELS SHALL BE ANCHORED TO THE (3/8) CABLE IN SUCH A MANNER SO THEY CANNOT SLIDE


THE REFLECTIVE SHEETING USED FOR THE PANELS SHALL MEET THE REQUIREMENTS OF SECTION 1091 OF THE STANDARD SPECIFICATIONS FOR ROAD & BRIDGE CONSTRUCTION AND SHALL BE ON BOTH SIDES.



REVISED SECTION COUNTY SHEETS NO. REVISED REGION 2 / DISTRICT 2 STANDARD (81-1B) M-4 ROCK ISLAND REVISED CONTRACT NO. 64F31 SCALE: 50.0000 // IN SHEET NO. OF SHEETS STA. TO STA. REVISED


EROSION CONTROL DETAILS FOR SILT FENCE






ALL DIMENSIONS ARE IN MILLIMETERS (INCHES) UNLESS

INFORMATIONAL WARNING SIGN (FOR NARROW TRAVEL LANES)



NOTES

W12-2 - Horizontal Clearance Sign 48.0" across sides, 1.9" Radius, 0.8" Border, 0.5" Indent, Black on Orange; Standard Arrow Custom 10.4" X 8.1" 180° Black 11 Inch D Series Lettering; Standard Arrow Custom 10.4" X 8.1" 0°



W12-I103 (Width is 8D);
No border, Black on White;

No border, Black on Orange; [XX'-XX''] D;

No border, Black on White;
[X MILES] D; [AHEAD] D;

All work to furnish and install these signs shall be included in the cost of the Traffic Control Standards and shall not be paid for separately.

ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.

REVISED REVISED REVISED REVISED SCALE: 50.2000 // IN SHEET NO. OF SHEETS STA.


REVISED - 10-22-01

EROSION CONTROL DETAILS FOR SILT FENCE

29.2[°]

INFORMATIONAL WARNING SIGNS (FOR NARROW TRAVEL LANES)

TRAFFIC CONTROL AND PROTECTION AT TURN BAYS (TO REMAIN OPEN TO TRAFFIC)



LEGEND



WORK AREA



LANE OPEN TO TRAFFIC



TYPE I OR II BARRICADE OR DRUM WITH FLASHING BURNING LIGHT



DRUM OR BARRICADE WITH STEADY BURN LIGHT



SIGN (SEE DETAIL)



TYPE I OR II CHECK BARRICADE WITH STEADY



LIGHT BURN

GENERAL NOTES

CONES MAY BE SUBSTITUTED FOR BARRICADES OR DRUMS AT HALF THE SPACING DURING DAY OPERATIONS. CONES SHALL BE A MINIMUM OF 710 (28) IN HEIGHT.

STEADY BURNING LIGHTS WILL NOT BE REQUIRED ON BARRICADES OR DRUMS FOR DAY OPERATIONS. ALL LIGHTS WILL BE MONODIRECTIONAL.

REFLECTORIZED TEMPORARY PAVEMENT MARKING TAPE SHALL BE PLACED THROUGHOUT THE BARRICADED AREA OF EACH BAY WHERE THE CLOSURE TIME IS GREATER THAN FOURTEEN DAYS.

THIS APPLICATION ALSO APPLIES WHEN WORK IS BEING PERFORMED IN THE RIGHT LANE(S) AND THE RIGHT TURN BAY IS TO REMAIN OPEN. UNDER THIS CONDITION, "RIGHT TURN LANE" R3-100 600 x 600 (24 X 24) AND M6-2R 530 X 380 (21 X 15) SHALL BE USED.

THESE CONTROLS SHALL SUPPLEMENT MAINLINE TRAFFIC CONTROL FOR LANE CLOSURES. LONGITUDINAL DIMENSIONS MAY BE ADJUSTED TO FIT FIELD CONDITIONS.


TRAFFIC CONTROL AND PROTECTION AT TURN BAYS (TO REMAIN OPEN TO TRAFFIC) SHALL BE INCLUDED IN THE COST SPECIFIED TRAFFIC CONTROL STANDARDS OR ITEMS.

ALL DIMENSIONS ARE IN MILLIMETERS (INCHES) UNLESS OTHERWISE NOTED.

REVISED - 10-15-04

REVISED -		F.A.I. RTE.	SECTION	COUNTY	TOTAL	SHEET
REVISED -	REGION 2 / DISTRICT 2 STANDARD	80	(81-1B) M-4	ROCK ISLAND	75	70
REVISED -			L	1.10011 2001110	NO. E	4F 31
REVISED -	SCALE: 50.0000 '/ IN SHEET NO. OF SHEETS STA. TO STA.	FED. RO	DAD DIST. NO. ILLINOIS FED. A			

TRAFFIC CONTROL TYPICAL WEAVE



LEGEND

- O DRUM WITH STEADY BURN MONO-DIRECTIONAL LIGHTS
- SIGN ON PERMANENT
 MOUNT

DESIGNER NOTE:

W1-4R(0)-48

W13-1(0)-2424

- USE ON LONG 4-LANE PROJECTS WHERE THE CONTRACTOR MAY CHANGE A PORTION OF THE WORK TO THE OPPOSITE LANE.
- USE WHERE THE PROJECT IS ADJACENT TO ANOTHER AND THE CONTRACTOR COULD BE WORKING ON DIFFERENT LANES.
- 3. TEMPORARY PAVEMENT MARKING SHALL BE USED WHEN TYPICAL WEAVE IS USED FOR 14 DAYS OR MORE.
- 4. TRAFFIC CONTROL TYPICAL WEAVE SHALL BE INCLUDED IN THE COST OF THE SPECIFIC TRAFFIC CONTROL STANDARDS OF ITEMS.

STANDARD WEAVE CONDITIONS FOR DIFFERENT SPEED LIMITS

POSTED SPEED LIMIT ADVISORY SPEED LIMIT WEAVE LENGTH

110 Km/h (65 MPH) 80 Km/h (45 MPH) 240m (780 FT.)
90 Km/h (55 MPH) 60 Km/h (35 MPH) 200m (660 FT.)

 90 Km/h (55 MPH)
 60 Km/h (35 MPH)
 200m (660 FT.)

 80 Km/h (45 MPH)
 40 Km/h (25 MPH)
 165m (540 FT.)

ALL DIMENSIONS ARE IN MILLIMETERS (INCHES)
UNLESS OTHERWISE NOTED.


										- 1
FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED - 5-30-91			F.A.I.	SECTION	COUNTY	TOTAL SHE	ET
c:\pw_work\pwidot\cushmonbw\d0149192\d0	409spl.dgn	DRAWN ~	REVISED -	STATE OF ILLINOIS	REGION 2 / DISTRICT 2 STANDARD	80 (8	81-1B) M-4	ROCK ISLAND	75 7	1
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION				CONTRACT	NO. 64F3	i1
1	PLOT DATE = Thu Sep 17 (8:57:31 2009	DATE -	REVISED -		SCALE: SHEET NO DE SHEETS STA TO STA	SED BOAD DIST NO	O THE INDIE EED AL	O DDO FOT		

TYPICAL PAVEMENT MARKINGS

MEDIAN PAVEMENT MARKING

100 (4) YELLOW

TYPICAL PAVEMENT MARKING FOR FLUSH MEDIAN AT LEFT TURN LANE



No Parking Zone

└-6m (20') Min.


No Parking Zone

— 100 (4) 200 (8) --- 3m (10')-9m (30') 76m (250') 2.4m (8') High White

TYPICAL ISLAND OFFSET SHOULDER WIDTH


600 (24) WHITE --200(8) WHITE -600 (24) WHITE 200 (8) WHITE 5 Diagonals Minimum -300 (12) WHITE

PARKING SPACING



6m (20') Min. —

SCALE:



** ALL DIMENSIONS ARE IN MILLIMETERS (INCHES) UNLESS OTHERWISE NOTED.

STANDARD CROSSWALK MARKING

See Schedules for Locations

	200(6) WHITE	of Pavement
300 (12)	1.8m (6') Minimum 1.2m (4') All Stop Bars 600 (24) WHITE	

* Distance to the nearest edge of the intersecting roadway in the absence of a marked crosswalk.


FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED - 10-21-08
c:\pw_work\pwidat\cushmanbw\d0149192\d0	409spl.dgn	DRAWN -	REVISED -
	PLOT SCALE = 50.0000 '/ IN.	CHECKED -	REVISED -
	PLOT DATE = Thu Sep 17 08:57:45 2009	DATE -	REVISED -

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**


Face of Curb

REGION 2 / DISTRICT 2 STANDARD SHEET NO. OF SHEETS STA.


COUNTY TOTAL SHEE SHEETS NO. SECTION ROCK ISLAND 75 72 80 (81-1B) M-4 CONTRACT NO. 64F31 FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT



TYPICAL PAVEMENT MARKINGS




MULTI-LANE / DIVIDED



- * REDUCE TO 12.2m (40') O.C. ON CURVES WHERE ADVISORY SPEEDS ARE 15Km/H(10MPH) LOWER THAN POSTED SPEEDS.
- ** USE DOUBLE MARKERS WHEN ADT > 25,000

MULTI-LANE / UNDIVIDED

TYPICAL PAVEMENT MARKING FOR TWO LANE SECTION - NO PASSING ZONES



FILE NAME =	USER NAME = cushmanbw	DESIGNED -	REVISED - 10-21-08			F.A.I.	SECTION	COUNTY	TOTAL SHEET
c:\pw_work\pwidot\cushmanbw\d0149192\d09	409spl.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS	REGION 2 / DISTRICT 2 STANDARD	80	(81-1B) M-4	ROCK ISLAND	75 74
	PLOT SCALE = 50,0000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION				CONTRACT	NO. 64F31
	PLOT DATE = Thu Sep 17 08:58:12 2009	DATE	REVISED -		SCALE: SHEET NO. OF SHEETS STA. TO STA.	FED. ROAD DIST.	NO. ILLINOIS FED. A	ID PROJECT	

PAINTING DETAILS RAMP EXIT NOTE: GORE HATCHING PLACED ONLY EOP-- 100 (4) YELLOW WHEN SCHEDULED IN TH PLANS _100 (4) WHITE 300 (12) WHITE 9m (30') CENTERS 100 (4) WHITE7 /-- EOP 200 (8) WHITE-3m (10') SHOULDER 100 (4) WHITE --1.2m (4') SHOULDER 2.4m (8') SHOULDER 100 (4) YELLOW 100 (4) YELLOW-EOP ← OPTIONAL METHOD FOR ENTRANCE RAMP HIGH VOLUME OFF RAMPS 100 (4) WHITE 100 (4) WHITE-EOP -3m (10') SHOULDER -200 (8) WHITE 2.4m (8') SHOULDER ALL DIMENSIONS ARE IN MILLIMETERS (INCHES) UNLESS OTHERWISE NOTED. 100 (4) YELLOW 100 (4) YELLOW CLOVERLEAF 3m (10') SHOULDER 3m (10') SHOULDER 100 (4) WHITE 3m (10') SHOULDER 200 (8) WHITE -- 100 (4) WHITE 200 (8) WHITE EOP 100 (4) WHITE 200 (8) WHITE -100 (4) YELLOW EOP --100 (4) YELLOW 200' (TYP.) (TAPER LENGTH AS DIRECTED BY THE ENGINEER) FILE NAME = DESIGNED REVISED 5-27-09 COUNTY TOTAL SHEE SHEETS NO. SECTION DRAWN REVISED STATE OF ILLINOIS REGION 2 / DISTRICT 2 STANDARD ROCK ISLAND 75 75 CONTRACT NO. 64F31 (81-1B) M-4 CHECKED REVISED **DEPARTMENT OF TRANSPORTATION** PLOT DATE = Thu Sep 17 Ø8:58:26 2009 DATE REVISED SCALE: SHEET NO. OF SHEETS STA. FED. ROAD DIST. NO. | ILLINOIS FED. AID PROJECT **PAINTING DETAILS** 44.1