

REVISED

REPAIR DESCRIPTIONS

REPAIR 3571 - REMOVE AND REPLACE WITH NEW THE EXISTING CASTING AND LID OF MANHOLE ESAN-4. CAREFULLY REMOVE ANY LOOSE BRICKS BELOW THE EXISTING CASTING AND LID AND REPLACE THEM WITH ADJUSTING RINGS IN ACCORDANCE WITH GPSD SPECIFICATIONS.

REPAIR 3572 - REMOVE AND REPLACE WITH NEW THE EXISTING CASTING AND LID OF MANHOLE ESAN-2. CAREFULLY REMOVE ANY LOOSE BRICKS BELOW THE EXISTING CASTING AND LID AND REPLACE THEM WITH ADJUSTING RINGS IN ACCORDANCE WITH GPSD SPECIFICATIONS.

REPAIR 3573 - REMOVE AND REPLACE WITH NEW THE EXISTING CASTING AND LID OF MANHOLE ESAN-3. CAREFULLY REMOVE ANY LOOSE BRICKS BELOW THE EXISTING CASTING AND LID AND REPLACE THEM WITH ADJUSTING RINGS IN ACCORDANCE WITH GPSD SPECIFICATIONS.

SANITA	ARY SCHEDULE	
	X6026056	
LOCATION	SANITARY MANHOLES TO BE	
	ADJUSTED WITH NEW TYPE 1	
	FRAME, CLOSED LID	
	EACH	
REPAIR 3571	1	
REPAIR 3572	REPAIR 3572 1	
REPAIR 3573	1	
TOTAL	3	





ADAMS STREET AND JEFFERSON AVENUE

TO STA.

SHEET NO. OF SHEETS STA.

SCALE: 1"=20"

A.U TE.	SECTION	COUNTY	TOTAL	SHEET NO.
233	12-00356-01-PV		519	210
		CONTRACT	NO.896	326
	ILLINOIS	FED. AID PROJECT TI	G-5093(158	3)