

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

ROUTE NO.	SECTION	con	JNTY	TOTAL SHEETS	SHEET NO.	SHE	ET	NO.	5
FAI 64	95- 6VB-1	WASHI	NGTON	83	56	7	SHE	ETS	
ED. ROAD DIST. NO. 7		ILLINOIS	FED. AID PROJECY-						

Contract #76A39



WEST ABUTMENT - SN 095-0061 (EB)




WEST ABUTMENT - SN 095-0062 (WB)

E	3 <i>ILL</i>	0F	MAT	ERIAL
	(S	N 095	5-0061)
	ITEM			UNIT


ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	14
Cleaning Bridge Seats	Sq. Ft.	243
Bridge Seat Sealer	Sq. Ft.	243

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	14
Cleaning Bridge Seats	Sq. Ft.	243
Bridge Seat Sealer	Sq. Ft.	243



EAST ABUTMENT - SN 095-0061 (EB)



EAST ABUTMENT - SN 095-0062 (WB)

- Notes:

 ① Hatched area indicates approximate area of
 Structural Repair of Concrete. Exact repairs
 are to be determined by the Engineer.
- (2) All existing abutment seats shall be cleaned & sealed. Work will be paid for as Cleaning Bridge Seats & Bridge Seat Sealer.

ABUTMENT CONCRETE REPAIRS

FAI 64 OVER
CNIC RAILROAD

FAI ROUTE 64 SECTION 95-6VB-1
WASHINGTON COUNTY
STATION 3263+73.50
STRUCTURE NO. 095-0061 (EB)
STRUCTURE NO. 095-0062 (WB)