

SOUTH ABUTMENT ELEVATION

(Looking South)

Note:

Repair of the existing abutment shall include but may not be limited to the areas shown. The actual areas to be repaired will be determined by the Engineer at the time of construction.

BILL OF MATERIAL

Item Unit Total
Structural Repair of Concrete (Depth equal to or less than 5 in.)

Sq. Ft. 14

LEGEND



Structural Repair of Concrete (Depth equal to or less than 5")

sf Square Feet



SH	EET	NO.	6
Ω	CHEE	TC	

10.6	F.A.I. RTE.	SECTION	COUNTY
	290	(531-3.1,0305-302K)RS-5	соок
S			CONTRACT

290 (531-3.1,0305-302K)RS-5 COOK 314 257

CONTRACT NO. 60I38

FED. ROAD DIST. NO. _ | ILLINOIS | FED. AID | PROJECT

<u>ABUTMENT REPAIR</u> STRUCTURE NO. 016-2133