

## SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

## WORK ZONE EXIT OPENING





## NOTES

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS)
UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = abrevah	DESIGNED -	REVISED - J.A.F. 04-03		OLONINO FOR ELACORIO OPERATIONO	F.A.I. SECTION	COUNTY TOTAL SHEET
c:\pw.work\pwidot\abreuah\dØ166688\DistS	td.dgn	DRAWN	REVISED - J.A.F. 02-06	STATE OF ILLINOIS	SIGNING FOR FLAGGING OPERATIONS	290 (531-3.1 0305-302 K) RS-5	COOK 314 3/0
	PLOT SCALE = 100.0000 '/ IN.	CHECKED -	REVISED - S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION	AT WORK ZONE OPENINGS	TC-18	CONTRACT NO. 60138
	PLOT DATE = 2/4/2010	DATE -	REVISED - S.P.B. 12-09		SCALE: NONE SHEET NO. 1 OF 1 SHEETS STA. TO STA.	FED. ROAD DIST. NO. 1 ILLINOIS FED. AN	