



HMA TAPER AT BUTT JOINTS


- * STA 494+20
- * STA 12+61
- * STA 66+21
- * STA 68+51
- * STA 196+45.5
- * STA 198+14.5
- * STA 80+17
- * STA 80+83
- * STA 264+23



PAVEMENT MARKING



HMA SURFACE REMOVAL - BUTT JOINT



NOTE: WHEN MILLING OPERATIONS PRODUCE A ROUNDED EDGE,
THEN A SAW CUT SHALL BE USED TO MANUFACTURE
A PERPENDICULAR EDGE AS SHOWN IN THE DETAIL.
THE ENGINEER SHALL BE THE SOLE JUDGE
CONCERNING THE USE OF THIS DETAIL

BITUMINOUS DETAIL AT BUTT JOINTS

DESIGNED -	REVISED -	
DRAWN -	REVISED -	ĺ
CHECKED -	REVISED -	
DATE -	REVISED -	
-	DRAWN - CHECKED -	DRAWN - REVISED - CHECKED - REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

	DETAILO					F.A.P. RTE.	SECTION	COUNTY	TOTAL	SHEET NO.	
DETAILS					332	(2X, 1X, 17, 48X-4)RS-3	IROQUOIS	15	- 10		
									CONTRACT	NO. 6	6663
	SCALE:	SHEET NO.	OF	SHEETS	STA.	TO STA.	ILLINOIS FED. AID PROJECT				