


DETECTOR LOOP INSTALLED IN TRENCH

INSTALLATION IS TO BE DONE IN CONFORMANCE WITH THE REQUIREMENTS OF THE PLANS AND SECTION 886 OF THE STANDARD SPECIFICATIONS WITH THE FOLLOWING EXCEPTIONS:

- 1. SLOTS ARE TO BE TRENCHED INSTEAD OF SAWED.
- 2. THIS WORK SHALL NOT BE PAID FOR SEPERATELY BUT SHALL BE INCLUDED IN THE COST OF "TEMPORARY BRIDGE TRAFFIC SIGNALS (STATE FURNISHED CONTROLLER)" 1 EACH.



BUTT JOINT DETAIL

FILE NAME =	USER NAME = gelinh	DESIGNED -	REVISED -
c:\pw_work\pwidot\gelinh\dms69644\pln009	07a.dgn	DRAWN -	REVISED -
	PLOT SCALE = 100.0000 '/ in.	CHECKED -	REVISED -
	PLOT DATE = 9/10/2012	DATE -	REVISED -

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

						F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
MISCELLANEOUS DETAILS						793	40BR-1	MADISON	72	32
								CONTRAC	T NO.	76A36
SCALE:	SHEET NO.	0F	SHEETS	STA.	TO STA.	FED. RO	AD DIST. NO. ILLINOIS FE	AID PROJECT		