



TYPICAL SECTION AT MAILBOX TURNOUT


NOTE: SEE STANDARD 406201 FOR MAILBOX TURNOUT DETAILS

- EXISTING MAILBOX TURNOUTS THAT ARE BITUMINOUS SHALL BE FEATHERED WITH INCIDENTAL HOT-MIX ASPHALT SURFACING. SEE SIDE ROAD & ENTRANCE SCHEDULE FOR LOCATION.



BUTT JOINT ELEVATION VIEW

STA. 1116+83.5 TO STA. 1116+98.5
 STA. 1121+11.5 TO STA. 1121+26.5
 STA. 1140+99 TO STA. 1141+14



ENTRANCE DETAIL
 (FOR EXISTING HMA OR PCC APRONS)

FILE NAME =	USER NAME = harbaughrd	DESIGNED -	REVISED -
et:\pwork\pwork\pwork\harbaughrd\0332311\...		DRAWN -	REVISED -
	PLOT SCALE = 100.0000' / in.	CHECKED -	REVISED -
	PLOT DATE = 5/9/2014	DATE -	REVISED -

STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION

MISCELLANEOUS DETAILS		RESURFACING DETAILS	
SCALE: N/A	SHEET NO. 2 OF 3 SHEETS	STA.	TO STA.

F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
805	126-IRS-3	CLINTON	16	15
CONTRACT NO. 76G30				
ILLINOIS FED. AID PROJECT				