

NOTE: QUANTITIES ARE ESTIMATED. ACTUAL QUANTITIES TO BE DETERMINED BY THE RESIDENT ENGINEER.





NORTHEAST WING

SOUTHEAST WING

Structural Repair of Concrete (Depth < 5")

FILE NAME =	USER NAME = swartzrw	DESIGNED -	REVISED -		STRUCTURAL REPAIR - EAST ABUTMENT SN 058-0097					F.A.I.	SECTION	COUNTY	TOTAL SHEET SHEETS NO.	
c:\pw.work\PWIDOT\SWARTZRW\dms37779\ka	renbridge.dgn	DRAWN -	REVISED -	STATE OF ILLINOIS						72	66(B.HVB.HB-1)BR	MACON	83 73	
	PLDT SCALE = 20.0000 '/ IN.	CHECKED -	REVISED -	DEPARTMENT OF TRANSPORTATION								CONTRACT	T NO. 74343	
	PLOT DATE = 9/28/2009	DATE -	REVISED -		SCALE: N/A	SHEET NO. 8	OF 17 SH	EETS	STA.	TO STA.	FED. ROA	D DIST. NO. ILLINOIS FED. A	ID PROJECT	