

DESIGNED	2 -	DMS/TJJ
CHECKED	-	EFS/AAY
DRAWN	-	RMG
CHECKED	-	AAY
Lannananan		

alfred benesch & company Engineers - Surveyore - Planners Skorth Michaen Avenue, Suite 2400 Chicago, Illinois 80801 Job No. 10050



Exist. Approach Pavement Connector See note 3

Symbol	ltem	Unit	Quantity	
	Deck Slab Repair (Partial)	Sq. Yd.	5.6	
	Approach Slab Repair (Partial Depth)	Sq. Yd.	10.0	
	Protective Shield	Sq. Yd.	130	

BILL OF MATERIAL

<u>Notes:</u>

- 1. Deck and approach slab repair areas are estimated based on visual inspection completed in June 2009. Actual repair areas and locations shall be determined by the Engineer and shown on As-Built plans.
- Protective Shield, required for deck slab and/or parapet repairs, shall be installed according to Article 501.03 of the Standard Specifications. For limits of Protective Shield, see Protective Shield Detail on this sheet and Elevation on General Plan and Elevation sheet.
- The Engineer shall determine the type and quantity of Class A patching and the quantity of Mixture for Cracks, Joints and Flangeways. Estimated quantities are included in the overall Summary of Quantities in Roadway Plans.

	BRIDGE DECK AND APPROACH SLAB REPAIRS STRUCTURE NO. 016-0085						
SHEET NO. 4	F.A.I. RTE.	SEC	TION	COUNTY	TOTAL SHEETS	SHEET NO.	10
	290	(3435, ETC.,	3838)RS-5	СООК	264	204	120
9 SHEETS	CONTRACT NO. 60G5					G52	125
	FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT						6