


WEST ABUTMENT ELEVATION



EAST ABUTMENT ELEVATION

<u>TWO ABUTMENTS</u> <u>BILL OF MATERIAL</u>

Item	Unit	Total
Epoxy Crack Injection	Foot	8
Structural Repair of Concrete (Depth equal to or less than 5")	Sq. Ft.	23

<u>LEGEND</u>

Structural Repair of Concrete (Depth equal to or less than 5")

~ Epoxy Crack Injection

Coombe-Bloxdorf P.C.
-CIVIL ENGINEERS-STRUCTURAL ENGINEERS-LAND SURVEYORSDesign Firm License No. 184-002703

							Besign Tilli Breense No. 101 000100			
FILE NAME =	USER NAME = keysrb	DESIGNED CME	REVISED -		ABUTMENT REPAIR DETAILS	F.A.P.	SECTION	COUNTY	CHEETC	SHEET
c:\pw_work\pwidot\keysrb\d0134590\07400	3-70432-015-RPR.dgn	CHECKED GJB	REVISED -	STATE OF ILLINOIS		721	(115BR)BR	PIATT	39	26
	PLOT SCALE = 8:0.0000 ':' / in.	DRAWN MML	REVISED -	DEPARTMENT OF TRANSPORTATION	STRUCTURE NO. 074-0003			CONTRACT	T NO. 7	0432
CB PROJECT NO. Ø8Ø49-7	PLOT DATE = 1/24/2014	CHECKED MCB	REVISED -		SHEET NO. 15 OF 18 SHEETS	ILLINOIS FED. AID PROJECT				