


 $\square$  —Structural Repair of Concrete (Depth equal to or less than 5")

——Structural Repair of Concrete (Depth greater than 5")



REAC	CTION TABLE
	PIER 7
Reaction DL:	15.8 kips
Reaction SDL	14.3 kips
Reaction LL	33.7 kips
Reaction Impact	IO.11 kips
Reaction Total	73.91 kips

**BILL OF MATERIAL** 

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth equal to or less than 5")	SQ. FT.	62.0
Structural Repair of Concrete (Depth greater than 5")	SQ. FT.	18.0
Temporary Shoring and Cribbing	EACH	10

NOTES: Beams are numbered from North to South end of the Pier.

\* Temporary Shoring and Cribbing required for East Face and West Face of Pier.

				•			
FILE NAME =	USER NAME = curryav	DESIGNED - ARP	REVISED -		39TH ST. (PERSHING RD) OVER RACINE AVE (SN 016-0396)	F.A.I. SECTION	COUNTY SHEETS NO.
ci/pw_work/pwidot/corryaw/dØ263496/01625	ll-sht-plan.dgn	DRAWN - ARP	REVISED -	STATE OF ILLINOIS	SUBSTRUCTURE REPAIRS	90/94 2011-068-BR	C00K 21 8
	PLOT SCALE = 3942.6523 ' / m	CHECKED - AM	REVISED -	DEPARTMENT OF TRANSPORTATION	SUBSTRUCTORE REPAIRS		CONTRACT NO. 60P87
	PLOT DATE = 1/19/2012	DATE - 12 (22 (1)	REVISED -		SCALE: SHEET 5 OF 7 SHEETS STA. TO STA.	ILLINOTS	S FEO. AID PROJECT