<u>FASCIA</u>	BEAN	<u> 1S</u>
(SHEET	2 OF	2)

ROUTE	SECTION	COUNTY	SHEETS	SHEE
1-24	•	MASSAC	58	9

• D-9 BRIDGE PAINTING FY 05-2 CONTRACT NO. 98882

Bridge No.	Structure	Painted Length (Foot)	Surface Preparation
13	064–0034	*	NEAR WHITE METAL BLAST CLEANING-SSPC-SP10
14	064-0037	137	NEAR WHITE METAL BLAST CLEANING-SSPC-SP10
15	064-0038	236	NEAR WHITE METAL BLAST CLEANING-SSPC-SP10

^{*} CLEAN AND PAINT ALL STRUCTURAL STEEL ON BRIDGE NO. 13

At each pier shown in the table below, the bottom flange at each existing new bearing shall be cleaned on the top, bottom, and side surfaces above the bearing and extending 3" past the bearing. This area shall be cleaned per Modified SP3 and touched up with / Urethane paint shall be applied according to the requirements of Paint System 2.

the penetrating BOTTOM FLANGE AT PIER BEARINGS

sealer/Epoxy Mastic.

Bridge No.	Structure	Pier
1	064-0017	2
2	064–0018	2
3	064-0020	2
4	064-0021	2
5	064-0023	2
6	064-0024	2
9	0640030	11
10	064-0031	1
13	064-0034	2