



DETAIL "A"
(3 Thus)

* Seal gap with approved Sealant as required

* Exist. Vane Grate to be Removed and Replaced on new Adjusting Ring

* New Adjusting Ring (Typ.)

60°

Prop. Concrete Overlay

Existing Scupper

* Contractor to measure existing Scupper in the Field prior to ordering Materials. Cost included with Deck Slab Repair (Full Depth, Type II)

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Deck Slab Repair (Full Depth, Type II)	Sq. Yd.	44

NOTE:
The Locations of Deck Slab Repairs, as shown on this Plan, are from the most recent Survey that was performed in October of 2007

LEGEND:
 Deck Slab Repair (Full Depth, Type II)

CHRISTIAN-ROGE & ASSOCIATES, INC.
ENGINEERS / PLANNERS / SURVEYORS
211 W. WACKER DRIVE CHICAGO, IL. 60606
PHONE: (312)372-2023 FAX: (312)372-5274