Contract # 60D74

REACTION TABLE

Posting Longtion	Reaction (kips)			
Bearing Location	R Q	R4	Impact	RTotal
© S. Brg. Pier 3	35.5	37.9	8.9	82.3
© N. Brg. Pier 3	36.6	46.5	11.7	94.8

## BILL OF MATERIAL

Item		Unit	Quantity
Structural Repair of Co (Depth equal to or less	ncrete than 5″)	Sq. Ft.	246
Temporary Shoring and	Cribbing	Each	2


## NOTE:

\*\* Indicates location for Temporary Shoring and Cribbing


Structural Repair of Concrete (Depth equal to or less than 5")

Detach the downspouts from the pier if necessary and reattach once the work is complete. Cost included with Structural Repair of Concrete (Depth equal to or less than 5").

Structural Repair of Concrete will not be allowed on any two adjacent columns at the same time, except in locations supported by Temporary Shoring and Cribbing. Work on an adjacent column shall not begin until the required curing period has elapsed on the previous column repair.



## PIER 3-SOUTH FACE ELEVATION



PIER 3-NORTH FACE ELEVATION

**rjn**group

Excellence through Ownership

200 West Front Street Wheaton, IL 60187

ILLINOIS DEPARTMENT OF TRANSPORTATION

PIER 3 REPAIRS BURNHAM AVE OVER STATE ST, R.R. & RIVER FAU RTE 2943 SECTION 1212.8-I-1 COOK COUNTY STATION 231+79.04 STRUCTURE NO. 016-0806

DATE: 1-14-2009

DRAWN BY JMT CHECKED BY WJV