

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION



*-The existing rail post shall be removed during the repairs and the anchor devices shall be reused. The existing steel rail tubing shall remain in place during the work. Cost included with Structural Repair of Concrete.




SECTION THRU EXIST. MEDIAN


Looking East

SECTION THRU PROP. MEDIAN

Looking East



SECTION AT DRAINS



SECTION A-A

<u>LE</u>GEND

Hairline Crack (No Repairs)

Structural Repair of Concrete

Hydroscarify Slab Surface

Median Removal Partial Depth

Concrete Superstructure

NOTES:

- 1. Repairs shall include but not be limited to the areas shown. The actual areas to be repaired will be determined by engineer at the time of construction and marked on as-built plans.
- The contractor is ultimately responsible for the means and methods to assure the complete stability of the structural members during construction.
- 3. Protective coat to be applied to roadway, median and inside faces of curbs.
- The repair concrete shall be securely anchored to the headwall using self drilling anchors. Cost included with Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches).

BILL OF MATERIAL

ITEM	UNIT	QUANTITY	
Concrete Superstructure	Cu.Yd.	3.3	
Protective Coal	Sq. Yd.	182	
Median Removal Partial Depth	Sq. Ft.	203	
Structural Repair of Concrete (Depth Equal to or Less then 5 inches)	Sq. Ft.	8.0	

<u>DETAILS</u> IL RTE. 38 OVER KRESS CREEK STA. 169+84.54 S.N. 022-0150

				-			
SHEET NO. 53	F.A.P. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEET NO.
	347	2 Y-B-I			DU PAGE	34	29
S3 SHEETS					CONTRACT	NO. 6	0D82
	FED. RC	AD DIST. NO.	ILLINOIS FE	D. AI	D PROJECT		

DESIGNED B. Sauter CHECKED E. Mroczek DRAWN R. Danley CHECKED B. Sauter

