

Wed Feb 4 09:23:19 2004  
 c:\p\ro\bo\as\982022\982022.dgn LV#25-20,22,24-28,30-47,50,52-63  
 DWS: D982022\982022.dwg LWF#25-20,22,24-28,30-47,50,52-63  
 DWS: D982022\982022.dwg LWF#25-20,22,24-28,30-47,50,52-63  
 DWS: D982022\982022.dwg LWF#25-20,22,24-28,30-47,50,52-63

**LEGEND**

⊕ MILE POST	--- CLEARING OR GRADING LIMITS
--- TREE REMOVAL	⊠ DISK AND RESEED
◇ EXISTING EARTH DITCH CHECK	← GENERAL CLEANING
--- EXISTING DITCH FLOW	⊠ RIPRAP
- x - x - WOVEN WIRE FENCE	

BM-1207 CHISELED "□" IN MEDIAN INLET  
 STA. 321+98 Ⓞ OF MEDIAN

F. A. REL.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
24	*	JOHNSON	150	59

FEED. ROAD DIST. NO. 11100000  
 FEED. AID PROJECT # (44-5,6)RS, BSMART FY04-3  
 98836

TREE REMOVAL, ACRES  
 53' X 10' LT. STA. 321+98 (Ⓞ WBL)  
 COST TO INCLUDE GENERAL CLEANING OF DOWNSTREAM DITCH

STONE DUMPED RIPRAP, CLASS A4  
 12' X 10' X 16"  
 LT. STA. 321+98 (Ⓞ WBL)

IMPROVEMENT BEGINS  
 STA. 320+50 (WBL)  
 FOR BUTT JOINT, SEE DETAIL SHEET 99

PROJECT BEGINS  
 STA. 320+50 (EBL)  
 FOR BUTT JOINT, SEE DETAIL SHEET 99

GRADING AND SHAPING  
 MEDIAN CROSSOVER  
 STA. 322+41 (Ⓞ MEDIAN)  
 SEE DETAIL SHEET 101

