

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES:

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.

SCALE: NONE

- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS)
UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = leyso	DESIGNED -	REVISED -	J.A.F. 04-03
W:\diststd\22x34\tc18.dgn		DRAWN -	REVISED -	J.A.F. 02-06
	PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED -	S.P.B. 01-07
	PLOT DATE = 1/26/2010	DATE -	REVISED -	S.P.B. 12-09

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

SIGNING FOR FLAGGING OPERATIONS					F.A.I. RTE.	SECTION		COUNTY
AT WORK ZONE OPENINGS				55 87B, D-BR-1		WILL		
	AT WORK ZONE OPENINGS					TC-18		
	SHEET NO. 1 OF 1	SHEETS	STA.	TO STA.	FED. R	OAD DIST. NO. 1	ILLINOIS FED. A	ID PROJECT

CONTRACT NO. 60R62

106 106

COUNTY