



NOTES:
1. Actual quantities of repairs shall be approved by the Engineer.

LEGEND
 Structural Repair of Concrete (Depth equal to or less than 5 inches)
 Epoxy Crack Injection

BILL OF MATERIAL

ITEM	UNIT	QUANTITY
Structural Repair of Concrete (Depth equal to or less than 5 inches)	Sq. Ft.	122
Epoxy Crack Injection	Foot	16
Jack and Remove Existing Bearings	Each	4

2/26/23 PM
 12/7/2012
 S:\1072_05_CADD\Structure\1 SN 0162437\CADD Sheets\0162437-60J12-051-PR04.dgn

BOWMAN, BARRETT & ASSOCIATES INC.
 CONSULTING ENGINEERS
 Chicago, Illinois
 312.228.0100
 www.bbainc.com

USER NAME =	DESIGNED - TL	REVISED -
	CHECKED - BAK	REVISED -
PLOT SCALE =	DRAWN - MTR	REVISED -
PLOT DATE = 11/08/2012	CHECKED - TL	REVISED -

STATE OF ILLINOIS
 DEPARTMENT OF TRANSPORTATION

PIER 4 REPAIR DETAILS
 STRUCTURE NO. 016-2437
 SHEET NO. S-51 OF S-83 SHEETS

F.A.I. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
94	2012-060-BR	COOK	285	214
CONTRACT NO. 60V61				
ILLINOIS FED. AID PROJECT				