



**STRUCTURAL REPAIR**

Cost included in Structural Repair  
of Concrete (Depth < 5')

Patch Number	Station	Area Sq Ft
1	24+57	2.3
2	24+41	2.3
3	23+70	2.3
	Total	6.9

**SOUTH PARAPET**

Looking South

FILE NAME =	USER NAME = swartzw	DESIGNED - KLB	REVISED -	<b>STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION</b>	<b>STRUCTURAL REPAIR - PARAPET SN. 080-0003</b>		F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.
ca:\pw_work\pwsdot\swartzw\d0207669\077482-sht-brdetails-0800003.dgn	PLOT SCALE = 20,0000 ' / IN.	DRAWN - KLB	REVISED -		327		Richland	53	12		
	PLOT DATE = 1/27/2011	CHECKED - MEA	REVISED -		SCALE: NA SHEET NO. 6 OF 15 SHEETS STA. TO STA.		CONTRACT NO. 74482				
		DATE - 12/1/10	REVISED -		ILLINOIS FED. AID PROJECT						

\*G-2VB-1.5-2HB,5-2VB-2IBR-2