



PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SO	YD	
1	16.5 x 12.0	198.0		
2	15.0 x 3.0	45.0		
3	3.0 x 3.0			9.0
4	2.0 x 7.0			14.0
5	28.0 x 12.0	336.0		
6	3.0 x 3.0			9.0
7	2.0 x 3.0			6.0
8	2.0 x 3.0			6.0
9	3.0 x 3.0			9.0
10	24.0 x 5.0	120.0		
11	5.0 x 4.0			20.0
12	2.0 x 10.0			20.0
13	2.0 x 3.0			6.0
14	3.0 x 3.0			9.0
15	18.0 x 3.0	54.0		
16	4.0 x 6.0			24.0
17	8.0 x 2.0			16.0

  

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SO	YD	
18	2.0 x 7.0			14.0
19	4.0 x 4.0	16.0		
20	2.0 x 3.0			6.0
21	22.5 x 3.0	67.5		
22	2.0 x 3.0			6.0
23	37.0 x 3.0	111.0		
24	3.0 x 3.0			9.0
25	5.0 x 6.0			30.0
26	10.0 x 3.0	30.0		
27	2.0 x 3.0			6.0
28	4.0 x 3.0			12.0
29	26.0 x 3.0	78.0		
30	5.0 x 3.0	15.0		
31	2.0 x 10.0			20.0
32	21.0 x 3.0	63.0		
33	24.0 x 3.0	72.0		
34	2.0 x 3.0			6.0

  

PATCH NO.	SIZE	DECK SLAB REPAIR (PART DEPTH)		
		SO	YD	
35	2.0 x 6.0			12.0
36	3.0 x 3.0	9.0		
TOTAL		1215	0	269
PARTIAL DEPTH (FOR INFORMATION ONLY)				
		1215	/ 9 =	134.9
		USE	135	\$0 YD
FULL DEPTH, TYPE 1				
		0	/ 9 =	0.0
		USE	0	\$0 YD
FULL DEPTH, TYPE 2				
		269	/ 9 =	29.9
		USE	30	\$0 YD

THE LOCATIONS AND SIZES SHOWN GRAPHICALLY ABOVE ARE APPROXIMATE. SEE THIS TABLE FOR ACTUAL SIZES.

**PATCHING LEGEND**

□ PARTIAL DEPTH (FOR INFORMATION ONLY)

▨ FULL DEPTH

DATE OF SURVEY: 09-15-10  
 SURVEY BY: MEA, ESS, KLB  
 METHOD OF SURVEY: VISUAL

BRIDGE DECK PATCHING  
 RICHLAND COUNTY  
 LOCATION

SN 080-0005

005