



EAST QUARTER CORNER
SEC 16 T35N R7E THIRD PM KENDALL COUNTY
FOUND P.K. NAIL ±7.6' S. OF & US 52




EAST QUARTER CORNER


SEC 16 T35N R8E THIRD PM KENDALL COUNTY
FOUND RR SPIKE ON & US 52




WEST QUARTER CORNER SECTION 18 T35N R8E THIRD PM KENDALL COUNTY FOUND BRASS DISK $\pm 6.6^{\circ}$ S OF \updownarrow US 52




CENTER OF SECTION 15 T35N R8E THIRD PM KENDALL COUNTY FOUND BRASS DISK ON & US 52



EAST QUARTER CORNER SECTION 18 T35N R8E THIRD PM KENDALL COUNTY FOUND BRASS DISK ±11.5' S OF ¢ US 52



T35N R8E THIRD PM KENDALL COUNTY
FOUND BRASS DISK ±1.5 S OF ¢ US 52



EAST QUARTER CORNER SECTION 15
T35N R8E THIRD PM KENDALL COUNTY
FOUND BRASS DISK ±3.0' S. OF ¢ US 52

FILE NAME =	USER NAME = duncambd	DESIGNED -	REVISED -
c:\projects\ed06204\allshts.dgn		DRAWN -	REVISED -
•	PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED -
	PLOT DATE = Mar 18, 2008 - 10:31:24 AM	DATE -	REVISED -

STATE	0F	ILLINOIS
DEPARTMENT (OF 1	TRANSPORTATION

TIE DOINTS					F.A.P. RTE.	SECTION	COUNTY	TOTAL SHEETS	SHEET NO.			
TIE POINTS				607	(129,130)RS-3	KENDALL	9	6				
	·····					* 1	-		CONTRACT	NO. 6	6749	
SCALE:	SHEET	NO.	OF	SHEETS	STA.	TO STA.	FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT					
												•