



## **HMA SURFACE REMOVAL BUTT JOINT**


STA. 183+64.38 TO STA. 184+24.38
STA. 185+84.40 TO STA. 186+44.40
STA. 237+80 TO STA. 238+40
STA. 249+85 TO STA. 250+45
STA. 321+42.47 TO STA. 322+02.47
STA. 324+39.61 TO STA 324+99.61
STA. 406+66.03 TO STA. 407+26.03
STA. 408+41.97 TO STA. 409+01.97
STA. 428+00 TO STA. 428+60




## **HMA TRANSITION DETAIL**


STA. 4+44.40 TO STA. 5+04.40








PRISMATIC REFLECTORS



## NOTES

- PRISMATIC REFLECTORS SHALL BE MONO-DIRECTIONAL AND POSITIONED SO THAT THE REFLECTIVE FACE IS FACING THE APPROACHING TRAFFIC.
- 2. PRISMATIC REFLECTORS SHALL BE SECURED IN PLACE WITH AN EPOXY ADHESIVE.
- 3. PRISMATIC REFLECTORS SHALL BE EITHER AMBER OR CRYSTAL IN COLOR.



## NOTES

- PRISMATIC REFLECTORS SHALL BE MONO-DIRECTIONAL AND POSITIONED SO THAT THE REFLECTIVE FACE IS FACING THE APPROACHING TRAFFIC.
- 2. PRISMATIC REFLECTORS SHALL BE SECURED IN PLACE WITH AN EPOXY ADHESIVE.
- 3. PRISMATIC REFLECTORS SHALL BE EITHER AMBER OR CRYSTAL IN COLOR.