




NOTES:

1. SEE SHEETS GI-1 AND GI-2 FOR INSTRUMENTATION SYMBOL LISTS, ABBREVIATIONS, AND GENERAL NOTES.
2. REFER TO SPECIFICATION SECTION 40 94 23 FOR SCADA PANEL REQUIREMENTS.

1 POWER TRANSFER P&ID DRAWING