

SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

WORK ZONE EXIT OPENING





NOTES:

- 1. THE ARROWBOARD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY OPENINGS SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE EXIT OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED.
- 4. ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

FILE NAME =	USER NAME = ZACH WALLSTEN	DESIGNED -	REVISED - JAF 04-03		SIGNING FOR FLAGGING OPERATIONS	FAP.	SECTION	COUNTY	TOTAL SH SHEETS N	ī
4085.877-TR1.dwg		DRAWN -	REVISED - JAF 02-06	STATE OF ILLINOIS		VARIES	2011-209-TS	COOK	52 4	П
	PLOT SCALE = 1" = .0833'	CHECKED -	REVISED - SPB 01-07	DEPARTMENT OF TRANSPORTATION	AT WORK ZONE OPENINGS		TC-18	CONTRACT #: 60R		R47
	PLOT DATE = 3/22/2012	DATE -	REVISED - SPB 12-09		SCALE: NONE SHEET NO. 1 OF 1 SHEETS STA. TO STA.		ILLINOIS FED. AID PROJECT			