

Mon Mar 13 13:45:08 2000 \\dlcaddl\projects\diststd\bd32.dgn LV=35 VI=8032



FOR MILLING AND RESURFACING



BD400-05 (VI=BD32)