06-16-2023 LETTING ITEM 186

FOR INDEX OF SHEETS, SEE SHEET NO. 3

FOR SUMMARY OF QUANTITIES, SEE SHEET NO. 4

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS

PROPOSED HIGHWAY PLANS

F.A.I. ROUTE 57 NB (I-57) **OVER FAS 2936 (OLD RTE US 51) SECTION D9 BRIDGE REPAIR 2023-3 PULASKI COUNTY**

MAJOR BRIDGE PREVENTATIVE MAINTENANCE PROJECT: STP-YLDC (341)

C-99-031-23

TRAFFIC DATA

1–57 (NORTHBOUND ONLY)

2023 ADT = 7,780 58% TRUCKS

0

0

0

TOWNSHIPS:

COUNTY UNIT ROAD DISTRICT

R1W Mounds EXISTING SRUCTURE NO. 077-0001 FAI 57 (I-57) NB **Mound City** COUNTY Cairo R 1 W

SN 077-0001 (NB)

BRIDGE LENGTH = 1013.16 FT NET LENGTH = 1013.16 FT

JOINT UTILITY LOCATION INFORMATION FOR EXCAVATION 1-800-892-0123 OR 811

PROJECT ENGINEER: Grant Deterding, P.E. (618) 351-5226 **DESIGNER: Moshe Cohen, S.E. (618) 233-5877**

CONTRACT NO. 78986

Signed: Make & Chu

Dated: 2023-03-07 Kaskaskia Santa Hilinois Structural Engineer No. 081-008104 License Expires: 11-30-2024 57 D9 BRIDGE REPAIR 2023-3 PULASKI 24 1



STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SUBMITTED Morch 17 20 23

DIRECTOR OF HIGHWAYS PROJECT IMPLEMENTATION

PRINTED BY THE AUTHORITY OF THE STATE OF ILLINOIS

PREPARED BY: OFFICE STRINGS & DIAMS ENGINEED

EXAMINED BY: DISTRICT LAND ACQUISITION FNGINFFR

EXAMINED BY:
DISTRICT PROGRAM DEVELOPMENT ENGINEER

EXAMINED BY: DISTRICT OPERATIONS ENGINEER

EXAMINED BY: DISTRICT PROJECT IMPLEMENTATION ENGINEER

EXAMINED BY: DISTRICT CONSTRUCTION ENGINEER

EXAMINED BY: Handland

TO STA.

Kaskaskia

Figureering Group, LLC

Engineering Group, LLC

Figureering Group,

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SIGNATURES

SHEET OF SHEETS STA.

SCALE:

GENERAL NOTES

COMMITMENTS: NONE

INDEX OF SHEETS

- 1 COVER SHEET
 2 SIGNATURES
 3 GENERAL NOTES, INDEX OF SHEETS AND HIGHWAY STANDARDS
 4 SUMMARY OF QUANTITIES
 5-24 STRUCTURE PLANS

INDEX OF HIGHWAY STANDARDS

| 000001-08 | STANDARD SYMBOLS, ABBREVIATIONS AND PATTERNS |
|-----------|---|
| 701001-02 | OFF-ROAD OPERATIONS 2L2W 15FT MIN FROM EOP |
| 701006-05 | OFF-ROAD OPERATIONS 2L2W 15FT TO EOP |
| 701101-05 | OFF-ROAD OPERATIONS MULTILANE LESS THAN 15FT TO EOP |
| 701106-02 | OFF-ROAD OPERATIONS MULTILANE MORE THAN 15FT AWAY |
| 701201-05 | LANE CLOSURE 2 LANE 2 WAY-DAY ONLY |
| 701400-11 | APPROACH TO LANE CLOSURE FREEWAY EXPRESSWAY |
| 701406-13 | LANE CLOSURE FREEWAY EXPRESSWAY DAY OPERATIONS ONLY |
| 001001-02 | AREAS OF REINFORCEMENT BARS |
| 001006 | DECIMAL OF AN INCH AND OF A FOOT |
| 701901-08 | TRAFFIC CONTROL DEVICES |
| | |

REV. - MS

| USER NAME = mmc | DESIGNED | REVISED = |
|---------------------------|----------|-----------|
| | DRAWN | REVISED - |
| PLOT SCALE = 2.0000 / in. | CHECKED | REVISED - |
| PLOT DATE = 1/9/2023 | DATE - | REVISED - |

| STATE | E OF | F ILLINOIS |
|------------|------|----------------|
| DEPARTMENT | OF | TRANSPORTATION |

| | | COUNTY: | PULASKI |
|----------|--|-----------|---------------------------------------|
| | | ROUTE: | FAI 57 |
| | | JND I NG: | 80% FEDERAL; 20% STATE SN 077-0001 |
| CODE | | CATION: | CONSTRUCTION CODE |
| NO. | ITEM | UNIT | 0013 |
| 50300225 | CONCRETE STRUCTURES | CU YD | 100.5 |
| | | | |
| 50800205 | REINFORCEMENT BARS, EPOXY COATED | POUND | 18,810 |
| | | | |
| 58700300 | CONCRETE SEALER | SQ FT | 6,705 |
| | | | |
| 67000400 | ENGINEER'S FIELD OFFICE, TYPE A | CAL MO | 6 |
| | | | |
| 67100100 | MOBILIZATION | L SUM | 1 |
| 70100450 | TRAFFIC CONTROL AND PROTECTION, STANDARD 701201 | L SUM | 1 |
| 70100700 | TRAFFIC CONTROL AND PROTECTION, STANDARD 701406 | L SUM | 1 |
| | | | |
| 70107025 | CHANGEABLE MESSAGE SIGN | CAL DA | 28 |
| | | | |
| X0321778 | SEISMIC RESTRAINER | EACH | 168 |
| | | | |
| Z0012754 | STRUCTURAL REPAIR OF CONCRETE (DEPTH EQUAL TO OR LESS THAN 5 INCHES) | SQ FT | 2,232 |
| | | | |
| Z0073200 | TEMPORARY SHORING AND CRIBBING | EACH | 83 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

REV. - MS

| askaskia gineering Group, LLC | 477 South Third Street Suite 270 Genera, Illinois 60134 630.332.9157 phone www.kashaskineng.com | ŀ |
|---|---|---|
| Illinois Professional Design Firm Professional Engineering Group | 184.004773 20-5080586 | t |

| Street | USER NAME = mmc | DESIGNED | REVISED = |
|-------------|---------------------------|----------|-----------|
| 60134 nc | | DRAWN | REVISED = |
| ng.com | PLOT SCALE = 2.0000 / in. | CHECKED | REVISED - |
| | PLOT DATE = 1/9/2023 | DATE | REVISED + |

| 1 | | | | | | | F.A.I. RTE. | SEC | TION | | COUNTY | TOTAL SHEETS | |
|---|-----------------------|-------|----|--------|------|---------|----------------|----------|----------|---------|-----------|-----------------|------|
| I | SUMMARY OF QUANTITIES | | | | | 57 | D9 BRIDGE R | EPAIR 20 | 023-3 | PULASKI | 24 | 4 | |
| Į | | | | | | | | | | | CONTRACT | NO. 78 | 3986 |
| 1 | SCALE: | SHEET | OF | SHEETS | STA. | TO STA. | | | ILLINOIS | FED. A | D PROJECT | | |

Existing Structure: SN 077-0001 was originally constructed in 1967 as one of two dual structures with simple span, P.P.C. I-Beam superstructures on open type abutments and combination of multi-column and hammerhead type piers on pile Structure to remain open to traffic during construction. Salvage: None.

DESIGN STRESSES

Original Construction (1967)

 $\overline{f_c} = 1,400$ psi (Superstructure & Substructure) $f_s = 20,000$ psi (Reinforcement)

vc = 75 psi (Footings)n = 10

<u>Precast Prestressed Units</u> $f_{c} = 5,000 \text{ psi}$

 $f_{ci} = 4,000 \text{ psi}$ $f_s = 248,000 \text{ psi } (7_{16}'' \otimes \text{Stress Relieved Strands})$

 $f_{si} = 173,600 \text{ psi } (7_{16}" \odot \text{Stress Relieved Strands})$ Existing Structure (1998 Rehab)

 $f_{c}' = 3,500 \text{ psi}$

 $f_V = 60,000$ psi (Reinforcement) $f_y = 36,000 \text{ psi } (M270 \text{ Gr. } 36)$

Existing Structure (2011 Rehab)

 $f_y = 60,000$ psi (Reinforcement) Existing Structure (2015 Rehab)

 $f_{\rm V} = 36,000$ psi (M270 Gr. 36) New Construction

 $f_c' = 3,500 \text{ psi}$

 $f_V = 60,000 \text{ psi (Reinforcement)}$ $f_{\rm V} = 36,000 \ \rm psi \ (M270 \ Gr. \ 36)$

DESIGN SPECIFICATIONS INDEX OF SHEETS


2002 AASHTO Standard Specifications for Highway Bridges, 17th Ed.

LOADING HS20-44


1 - General Plan & Elevation - General Data Substructure Repair - Pier 2 Substructure Repair - Pier 3 Substructure Repair - Pier 4 6 - Substructure Repair - Pier 5 Substructure Repair - Pier 6 8 - Substructure Repair - Pier 7 9 - Substructure Repair - Pier 8 10 - Substructure Repair - Pier 9 11 - Substructure Repair - Pier 10 12 - Substructure Repair - Pier 11 13 - Substructure Repair - Pier 12 14 - Substructure Repair - Pier 13 15 - Substructure Repair - Pier 14 16 - Substructure Repair - Pier 15 17 - Pier Encasement Details (Piers 1 & 2) 18 - Pier Encasement Details (Piers 3 Thru 15) 19 - Seismic Restrainer Details (Piers 1 & 2) 20 - Seismic Restrainer Details (Piers 3 Thru 15)

1013'-17/8" Bk. to Bk. Abuts. E F 846 ¢ F.A.S. Rte. 2936

ELEVATION



PLAN



Project -Location LOCATION SKETCH

GENERAL PLAN & ELEVATION I-57 (NORTHBOUND) OVER F.A.S. 2936 F.A.I. RTE. 57 - SEC. D9 BRIDGE REPAIRS 2023-3 PULASKI COUNTY STATION 881+37.61 STRUCTURE NO. 077-0001 (NB)

Kaskaskia

DESIGNED - MMC REVISED CHECKED - MLC REVISED -DRAWN REVISED PLOT DATE = CHECKED - MLC REVISED -

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

SECTION COUNTY 57 D9 BRIDGE REPAIR 2023-3 PULASKI 24 5 CONTRACT NO. 78986 SHEET 1 OF 20 SHEETS

Reinforcement bars designated (E) shall be epoxy coated.

All structural steel shall be AASHTO M 270 Grade 36 unless otherwise noted.

Plan dimensions and details relative to existing plans are subject to nominal construction variations. The Contractor shall field verify existing dimensions and details affecting new construction and make necessary approved adjustments prior to construction or ordering of materials. Such variations shall not be cause for additional compensation for a change in scope of the work, however, the Contractor will be paid for the quantity actually furnished at the unit price bid for the work.

All exposed concrete edges shall have a standard 3/4" chamfer unless otherwise noted. Concrete Sealer shall be placed over new pier cap encasement.

SCOPE OF WORK

- and construct concrete pier encasement.
- 2. Replace Seismic Restrainer cable assemblies.

DESIGNED - MLC REVISED -Kaskaskia 68.233.977 (s. CHECKED - MMC REVISED -DRAWN - MLC REVISED -PLOT DATE = CHECKED - MMC REVISED -

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

GENERAL DATA STRUCTURE NO. 077-0001 SHEET 2 OF 20 SHEETS

| F.A.I. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEET NO. |
|----------------|-------------------------|------------|-----------------|--------------|
| 57 | D9 BRIDGE REPAIR 2023-3 | PULASKI | 24 | 6 |
| | | CONTRAC | T NO. 78 | 3986 |
| | ILLINOIS FED A | ID PROJECT | | |

| 1. | Repair | piers | at | designated | locations | or | as | directed | by | the | Engineer | а |
|----|--------|-------|----|------------|-----------|----|----|----------|----|-----|----------|---|
| | | | | ± | | | | | | | | |

GENERAL NOTES

| OTAL | BILL | 0F | MATERIAL | |
|------|------|----|----------|------|
| | | | | |
| | | | | UNIT |

QUANTITY

100.5

18,810 6,705

168

2,232

83

Cu. Yd.

Pound

Sq. Ft.

Each

Sq. Ft.

Each

ITEM

Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)


Concrete Structures


Concrete Sealer

Seismic Restrainer

Reinforcement Bars, Epoxy Coated


Temporary Shoring and Cribbing





END ELEVATION

(Southeast Face - Looking Northwest)



∉ Brg.—

Beam 3

∉ Brg.— Beam 5 ⊈ Brg.– Beam 4 (Northeast Face - Looking Southwest)

BEAM REACTIONS

| Reactio | n | Span 2 | Span 3 |
|-----------|-----|--------|--------|
| R₽ | (k) | 52.7 | 42.8 |
| R Ł | (k) | 82.4 | 78.1 |
| R Imp. | (k) | 22.5 | 23.0 |
| R (Total) | (k) | 157.6 | 143.9 |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 17 of 20 for pier cap encasement details.


See sheet 19 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 17 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Item | Unit | Total |
|---|---------|-------|
| Structural Repair of Concrete (Depth Equal to or Less than 5 Inches) | Sq. Ft. | 42 |
| Temporary Shoring and Cribbing | Each | 3 |



<u>END ELEVATION</u> (Northwest Face - Looking Southeast)

| | ····· | | | | | | | | | 1 | | | |
|---------|-------|-----|------|-----|-----|-----|-----|-----|-----|-----|-----|---|--|
| | | | | | | | | | | | | į | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | : | |
| | | | | | | | | | | | | | |
| | | | | - [| | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | ::: | | : | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| F11 F11 | 113 | 111 | | | [1] | 1 1 | 111 | : : | 111 | [1] | 1.1 | | |

ℚ Brg.—— Beam 2

∉ Brg.-

____1 Sq. Ft.

Beam 1


<u>ELEVATION</u>
(Southwest Face - Looking Northeast)

| | | 208 E. Main St., Snine 100 Belleville, Ellinois 62220 | USER NAME = | DESIGNED - MMC | REVISED - | |
|---|---|---|--------------|----------------|-----------|--|
| 1 | 📉 Kaskaskia 🔞 | 618,233,5877 physic 618,233,5877 fax energy, least lands again, cum | | CHECKED - MLC | REVISED - | |
| | PROPESSIONAL REGISTRATIONS L. Illinois Professional Design Nam. 1 | LICENSE NO. 184,004773 | PLOT SCALE = | DRAWN - MMC | REVISED - | |
| 1 | Professional Engineering Group 2 | 20-5080396 | PLOT DATE = | CHECKED - MLC | REVISED - | |


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE REPAIR - PIER 2 STRUCTURE NO. 077-0001 1 1-57 over Old 115 51 Bridge Rehab\0 100T\\$tructures\0770001-78986-003-\$ubstructureRe


EL: Default NAME: P:\22-1




5/8/2023 2:50:41 PM




5/8/2023 2:50:41 PM




5/8/2023 2:50:42 PM



5/8/2023 2:50:43 PM





⊈ Brg.—

Beam 3

⊈ Brg.—

Beam 2

3 Sq. Ft.

⊈ Brg.—


Beam 4

1 Sq. Ft.—

₲ Brg.-

Beam 5

1 Sq. Ft. —-₩



BEAM REACTIONS

| Reaction | | Span 7 | Span 8 |
|-----------|-----|--------|--------|
| R₽ | (k) | 57.7 | 57.7 |
| R Ł | (k) | 84.4 | 84.4 |
| R Imp. | (k) | 22.2 | 22.2 |
| R (Total) | (k) | 164.3 | 164.3 |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 18 of 20 for pier cap encasement details.


See sheet 20 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Unit | Total |
|---------|---------|
| Sq. Ft. | 91 |
| Each | 6 |
| | Sq. Ft. |



END ELEVATION

(West Face - Looking East) DESIGNED - MMC REVISED -CHECKED - MLC REVISED -DRAWN - MMC REVISED -PLOT DATE = CHECKED - MLC REVISED -

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

ELEVATION (South Face - Looking North)

> **SUBSTRUCTURE REPAIR - PIER 7 STRUCTURE NO. 077-0001** SHEET 8 OF 20 SHEETS


F.A.I. SECTION

RTE. SECTION

57 D9 BRIDGE REPAIR 2023-3 PULASKI 24 12 CONTRACT NO. 78986

5/8/2023 2:50:44 PM

Kaskaskia Bellevite, Ulindi 68.233.8977 pha



DEPARTMENT OF TRANSPORTATION

57 D9 BRIDGE REPAIR 2023-3

STRUCTURE NO. 077-0001

SHEET 9 OF 20 SHEETS

PULASKI 24 13

CONTRACT NO. 78986

5/8/2023 2:50:45 PM

PLOT DATE =

CHECKED - MLC


DRAWN - MMC


CHECKED - MLC


REVISED -

REVISED -

REVISED -







ELEVATION (South Face - Looking North)

BEAM REACTIONS

| Reactio | n | Span 9 | Span 10 |
|-----------|-----|--------|---------|
| R₽ | (k) | 57.7 | 57.7 |
| R Ł | (k) | 84.4 | 84.4 |
| R Imp. | (k) | 22.2 | 22.2 |
| R (Total) | (k) | 164.3 | 164.3 |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

1 Sq. Ft.—

1 Sq. Ft.

 \Box PLAN

1 Sq. Ft.

See sheet 18 of 20 for pier cap encasement details.

See sheet 20 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Item | Unit | Total |
|---|---------|-------|
| Structural Repair of Concrete (Depth Equal to or Less than 5 Inches) | Sq. Ft. | 109 |
| Temporary Shoring and Cribbing | Each | 5 |

(West Face - Looking East) Kaskaskia Bellevite, Illinois PLOT DATE =

END ELEVATION

DESIGNED - MMC REVISED -CHECKED - MLC REVISED -DRAWN - MMC REVISED -CHECKED - MLC REVISED -

— 6 Sq. Ft.

UNDERSIDE OF CAP

(West End - Looking East)


STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** **SUBSTRUCTURE REPAIR - PIER 9 STRUCTURE NO. 077-0001** SHEET 10 OF 20 SHEETS


F.A.I. SECTION


RTE. SECTION

57 D9 BRIDGE REPAIR 2023-3 COUNTY TOTAL SHEET NO.

PULASKI 24 14 CONTRACT NO. 78986








ELEVATION

(North Face - Looking South)



 $\frac{\textit{ELEVATION}}{\textit{(South Face - Looking North)}}$

BEAM REACTIONS

3 Sq. Ft. —

PLAN

1 Sq. Ft.

| Reaction | | Span 10 | Span 11 | | |
|-----------|-----|---------|---------|--|--|
| R₽ | (k) | 57.7 | 57.7 | | |
| R Ł | (k) | 84.4 | 84.4 | | |
| R Imp. | (k) | 22.2 | 22.2 | | |
| R (Total) | (k) | 164.3 | 164.3 | | |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 18 of 20 for pier cap encasement details.

See sheet 20 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Unit | Total |
|---------|---------|
| Sq. Ft. | 210 |
| Each | 9 |
| | Sq. Ft. |


Kaskaskia
Engineering Group LLC
Engineering


STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION


SUBSTRUCTURE REPAIR - PIER 10 STRUCTURE NO. 077-0001 SHEET 11 OF 20 SHEETS


9 Sq. Ft. —

21 Sq. Ft.









BEAM REACTIONS

| Reaction | | Span 11 | Span 12 | | |
|-----------|-----|---------|---------|--|--|
| R₽ | (k) | 57.7 | 57.7 | | |
| R Ł | (k) | 84.4 | 84.4 | | |
| R Imp. | (k) | 22.2 | 22.2 | | |
| R (Total) | (k) | 164.3 | 164.3 | | |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 18 of 20 for pier cap encasement details.

See sheet 20 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Item | Unit | Total |
|---|---------|-------|
| Structural Repair of Concrete (Depth Equal to or Less than 5 Inches) | Sq. Ft. | 119 |
| Temporary Shoring and Cribbing | Each | 5 |

(West Face – Looking East)

Kaskaskia
Engineering Group, LLC

West Mana N, you told

Medicity, Brook 1982

MANA N, you told

USER NAME =


USER NAME =


STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

(South Face - Looking North)

SUBSTRUCTURE REPAIR - PIER 11
STRUCTURE NO. 077-0001

SHEET 12 OF 20 SHEETS






(South Face - Looking North)

STATE OF ILLINOIS

-@ Brg. Beam 4

Beam 5



PLAN

BEAM REACTIONS

| Reaction | | Span 12 | Span 13 | | |
|-------------|----|---------|---------|--|--|
| R ₽ (| k) | 57.7 | 57.7 | | |
| R 4 (| k) | 84.4 | 84.4 | | |
| R Imp. (| k) | 22.2 | 22.2 | | |
| R (Total) (| k) | 164.3 | 164.3 | | |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 18 of 20 for pier cap encasement details.

See sheet 20 of 20 for seismic cable details.

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Item | Unit | Total |
|---|---------|-------|
| Structural Repair of Concrete (Depth Equal to or Less than 5 Inches) | Sq. Ft. | 230 |
| Temporary Shoring and Cribbing | Each | 10 |

UNDERSIDE OF CAP END ELEVATION (West Face - Looking East) (West End - Looking East) DESIGNED - MMC Kaskaskia Bellevile, Blinds CHECKED - MLC DRAWN - MMC

PLOT DATE =

11 Sq. Ft.—

CHECKED - MLC

DEPARTMENT OF TRANSPORTATION

REVISED -

REVISED -

REVISED -

REVISED -


SUBSTRUCTURE REPAIR - PIER 12 STRUCTURE NO. 077-0001

 F.A.I. RTE.
 SECTION

 57
 D9 BRIDGE REPAIR 2023-3
 PULASKI 24 17 CONTRACT NO. 78986

5/8/2023 2:50:50 PM

SHEET 13 OF 20 SHEETS



STATE OF ILLINOIS

DEPARTMENT OF TRANSPORTATION

57 D9 BRIDGE REPAIR 2023-3

STRUCTURE NO. 077-0001

SHEET 14 OF 20 SHEETS

PULASKI 24 18

CONTRACT NO. 78986

5/8/2023 2:50:51 PM

Kaskaskia Bellevile, Blinds

PLOT DATE =

CHECKED - MLC


DRAWN - MMC


CHECKED - MLC

REVISED -

REVISED -

REVISED -






REVISED -

REVISED -

REVISED -

REVISED -



BILL OF MATERIAL

| Item | Unit | Total |
|---|---------|-------|
| Structural Repair of Concrete (Depth Equal to or Less than 5 Inches) | Sq. Ft. | 254 |
| Temporary Shoring and Cribbing | Each | 5 |

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

See sheet 18 of 20 for pier cap

* Location of Temporary Shoring and

See sheet 20 of 20 for seismic cable

All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete

UNDERSIDE OF CAP END ELEVATION (West Face - Looking East) (West End - Looking East)

DESIGNED - MMC

CHECKED - MLC

DRAWN - MMC

CHECKED - MLC

| STATE OF ILLINOIS | |
|---------------------------|-----|
| DEPARTMENT OF TRANSPORTAT | ION |

(South Face - Looking North)

| SUBSTRUCTURE REPAIR - PIER 14 | F.A.I. RTE. | SECTION |
|-------------------------------|----------------|--------------------|
| STRUCTURE NO. 077-0001 | 57 | D9 BRIDGE REPAIR 2 |
| 3111001011L110.077-0001 | | |
| SHEET 15 OF 20 SHEETS | | ULINO |

Notes:

details.

Cribbing.

encasement details.

detailed on sheet 18 of 20.


COUNTY TOTAL SHEETS NO.


PULASKI 24 19 R 2023-3 CONTRACT NO. 78986


Kaskaskia Bellevite, Illinois

PLOT DATE =

5/8/2023 2:50:52 PM







<u>BEAM REACTIONS</u>

| Reaction | Span 15 | Span 16 |
|---------------|---------|---------|
| R ₽ (k) | 57.7 | 57.1 |
| R Ł (k) | 84.4 | 84.4 |
| R Imp. (k) | 22.2 | 22.3 |
| R (Total) (k) | 164.3 | 163.8 |

<u>LEGEND</u>

Indicates Structural Repair of Concrete (Depth Equal to or Less Than 5 Inches)

Notes:

See sheet 18 of 20 for pier cap encasement details.


See sheet 20 of 20 for seismic cable details.


All concrete necessary for the repairs to the pier cap shall be poured monolithically with the pier cap encasement concrete detailed on sheet 18 of 20.

* Location of Temporary Shoring and Cribbing.

BILL OF MATERIAL

| Unit | Total |
|---------|---------|
| Sq. Ft. | 188 |
| Each | 4 |
| | Sq. Ft. |






| USER NAME = DESIGNED - MMC REVISED - MICROSCOPE - MICRO

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SUBSTRUCTURE REPAIR - PIER 15 STRUCTURE NO. 077-0001 SHEET 16 OF 20 SHEETS

5/8/2023 2:50:53 PM



F.A.I. RTE. SECTION

57 D9 BRIDGE REPAIR 2023-3 DESIGNED - MMC REVISED -COUNTY PIER ENCASEMENT DETAILS (PIERS 1 & 2) Kaskaskia **STATE OF ILLINOIS** CHECKED - MLC REVISED -PULASKI 24 21 **STRUCTURE NO. 077-0001 DEPARTMENT OF TRANSPORTATION** DRAWN REVISED CONTRACT NO. 78986 SHEET 17 OF 20 SHEETS PLOT DATE = CHECKED - MLC REVISED -


Reinforcement Bars, Epoxy Coated

Pound

2,760

Order v4(E) full length. Cut as shown and

use remainder of bars in opposite end.



1/4/2023 2:11:56 PM

PLOT DATE =

DRAWN


CHECKED - MLC

REVISED -

REVISED -


STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION **STRUCTURE NO. 077-0001** SHEET 18 OF 20 SHEETS

| F.A.I. RTE. | SECTION | COUNTY | TOTAL SHEETS | SHEE NO. |
|----------------|-------------------------|------------|-----------------|-------------|
| 57 | D9 BRIDGE REPAIR 2023-3 | PULASKI | 24 | 22 |
| | | CONTRAC | T NO. 78 | 3986 |
| | ILLINOIS FED A | ID PROJECT | | |



PIER PLAN

(Showing location of Seismic Restrainers) (Pier 2 shown, Pier 1 similar)



BEARING PLATE

SEISMIC RESTRAINER NOTES

All steel parts except cables shall be galvanized according to AASHTO M 232. Restrainer cables shall be galvanized according to AASHTO M 120 Class C.

Cable shall be $\frac{3}{4}$ "0 preformed, 6 x 19 wire rope, ultimate strength = 47,600 pounds in accordance with

The swagged fitting shall be machined from hot-rolled bars of steel conforming to AISI C 1035, and shall be annealed, suitable for cold swagging. The manufacturer's identifying mark shall be stamped on the body of the swagged fitting.

The 1 inch diameter stud shall conform to the requirements of AASHTO M 314.

Nuts shall conform to the requirements of AASHTO M 164 except they need not be Grade DH or Grade 2H nor is it necessary for the nuts to be lubricated. After galvanizing, the pitch diameter of the nut and the head of the swagged fitting may be tapped over ANSI B1.1 Class 2B tolerance by $\frac{3}{16}$ inch oversize if the stud threads conform to Class 2A fit before galvanizing.

The swagged fitting, stud, and nut assembly shall develop 125 percent of the specified ultimate strength

The Contractor shall be responsible for determining the required lengths of cable to account for the additional cap encasement. The restrainer cable shall be installed after concrete encasement has cured.

Each seismic restrainer consists of ¾"Ø Restrainer Cable with 2 end anchorage assemblies, 1 bearing plate (including neoprene pad), and misc. hardware.

Cost of cables, cable end anchorages, plates, neoprene pads, washers, and nuts, including removal of the existing and installation of restrainers will be paid for at the unit bid price each for each "Seismic Restrainer."

Cost of removal and disposal of existing cables and associated elements is included in the cost of "Seismic Restrainer."

Cored holes shall be sealed with sealant, subject to approval of the Engineer. Cost of the sealant is included with "Seismic Restrainer."

For details of the ¾"Ø Restrainer Cable Ends, existing Beveled Spacer, and existing Brackets, see sheet

SEISMIC RESTRAINER INSTALLATION PROCEDURES

- 1.) Locate and install cables snug tight.
- 2.) For Restrainers at fixed bearings, back off the nut at bracket end of cable by 3/4".
- 3.) For Restrainers at expansion bearings, back off the nut at bracket end of cable by "D" $+ \frac{3}{4}$ ".


"D" = $+\frac{1}{2}$ " per 100' of expansion length for every 15°F temperature rise above 50°F Normal Temperature.

"D" =-1%" per 100' of expansion length for every 15°F temperature drop below 50°F Normal Temperature.

4.) Tighten jam nuts.

- Ç S. Brg.

⊊ Beam 1




* Estimated. Contractor required to check actual length.

DESIGNED - MLC REVISED -Kaskaskia CHECKED - MMC REVISED -REVISED PLOT DATE = CHECKED - MMC REVISED -


STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** SEISMIC RESTRAINER DETAILS (PIERS 1 & 2) **STRUCTURE NO. 077-0001** SHEET 19 OF 20 SHEETS

SECTION COUNTY D9 BRIDGE REPAIR 2023-3 57 PULASKI 24 23 CONTRACT NO. 78986

12




RESTRAINER CABLES AT PIERS 3 THRU 15



CABLE END ANCHORAGE

(2 per Cable)



EXISTING BRACKET DETAILS

ELEVATION SECTION C-C

¶ 1¼"Ø hole — 15%" (Piers 3 thru 15) 2" (Piers 1 & 2)

R Washer

Nut & Jam Nut

EXISTING BEVELED <u>SPACER</u>

BILL OF MATERIAL

| Item | Unit | Total |
|--------------------|------|-------|
| Seismic Restrainer | Each | 156 |
| | | |

For Seismic Restrainer notes and installation procedure, see sheet 19 of 20. Existing brackets to be re-used.

DESIGNED - MI REVISED -Kaskaskia Beterte, Blinds CHECKED - MMC REVISED -DRAWN REVISED -PLOT DATE = CHECKED - MMC REVISED -

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION** SEISMIC RESTRAINER DETAILS (PIERS 3 THRU 15) **STRUCTURE NO. 077-0001** SHEET 20 OF 20 SHEETS

€ Pier ——

Chip corners smooth to 4"

Radius (Typ.)

2'-9"

Exist. Cap

3'-9"

SECTION A-A

*Estimated. Contractor required to check actual length.

* 10'-9"

Existing Bracket —

Existing Beveled Spacer —

- Cable End Anchorage

Bearing Plate with $\frac{1}{4}$ " Neoprene Pad.

(Bond to Bearing

Plate)

R Washer

- Nut & Jam Nut

* 10'-9"

Existing

Spacer

¾"Ø Restainer Cable (6 strands with 19 wires per strand)

(Typ.)

-Existing Beveled

∉ Existing 3"Ø

6" New Cap

Encasement (Typ.)

Cored Hole

F.A.I. RTE. SECTION

57 D9 BRIDGE REPAIR 2023-3 PULASKI 24 24 CONTRACT NO. 78986

SECTION B-B

1/4/2023 2:11:58 PM