



PLAN

Repair of the existing deck slab shall include but may not be limited to the areas shown. The actual area to be repaired will be determined by the Engineer at the time of construction.

Limits of Protective Shield shall extend longitudinally from Pier 1 to Pier 3 and transversely from North to South fascia beams.

BILL OF MATERIAL

ITEM	UNIT	TOTAL
Deck Slab Repair (Partial)	Sq. Yd.	9.1
Protective Shield	Sq. Yd.	539

<u>LEGEND</u>



Deck Slab Repair (Partial)

Square Feet

APPEN 1518508		US
	LIN ENGINEERING,LTD.	FI
	Consulting Engineers	PL
	Chatham, Illinois	PL

	USER NAME =	DESIGNED - TBP	REVISED -	
).	FILE NAME :	CHECKED - ADB	REVISED -	
	PLOT SCALE =	DRAWN - AJF	REVISED -	
	PLOT DATE ≈	CHECKED - MTH	REVISED -	
				-

STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION

SUPERSTRUCTURE REPAIR	F.A.P. RTE.	SE
STRUCTURE NO. 016-0218		8R-
SHOOTORE NO. 010-0210		
SHEET NO. 3 OF 7 SHEETS		

	F.A.P. RTE.	SECTION		COUNTY	TOTAL SHEETS	SHEET NO.
	345 8R-1-RS-4		T	COOK	124	96
				CONTRACT	NO. 6	50M46
		ILLINOIS FED.	AID	PROJECT		