



**EARTHWORK SUMMARY IN CUBIC YARDS**

<b>CUT</b>		
Topsail	1,085	
Clay	5,435	
<b>TOTAL UNCLASSIFIED CUT</b>	<b>6,520</b>	
<b>CLAY FILL</b>		
Fill	157	
Shrink (10%)	16	
<b>TOTAL UNCLASSIFIED FILL</b>	<b>173</b>	
<b>Excess Clay for Disposal Onsite</b>		<b>5,262</b>
<b>TOPSOIL FILL</b>		
Topsail from On Site	1,085	
<b>TOTAL TOPSOIL REQUIRED</b>	<b>1,010</b>	
<b>Excess Topsoil for Stockpile on Airport</b>		<b>75</b>

MATCH LINE STA. 205+00

**STAKING PLAN  
ALIGNMENT 200/300**

**REHABILITATE NORTH HANGAR PAVEMENTS,**  
 IDA No. LOT-4020 AIP No. 3-17-0140-B48



©Copyright Hanson Professional Services Inc. 2011

**Hanson Professional Services Inc.**  
 815 Commerce Drive Suite 200  
 Oak Brook, Illinois 60523

Hanson No. 10A0072  
 Filename 18-STAKING PLAN 1.DWG  
 Scale 1"=20'  
 Date APRIL 22, 2011

LAYOUT	KMS	02/24/11
DRAWN	KMS	02/24/11
REVIEWED	RMH	4/22/11



**Chicago-Romeoville Airport**  
**JOLIET REGIONAL PORT DISTRICT**  
 1 George Michas Drive  
 Romeoville, Illinois 60446  
 Telephone: 815.838.9497  
 Fax: 815.838.9524

DATE	REVISION