



**CROSS SECTIONS
 ALIGNMENT 200
 204+50 - 208+00**

REHABILITATE NORTH HANGAR PAVEMENTS,
 IDA No. LOT-4020 AIP No. 3-17-0140-B48

HANSON
 Copyright Hanson Professional Services Inc. 2011

Hanson Professional Services Inc.
 815 Commerce Drive Suite 200
 Oak Brook, Illinois 60523

Hanson No.	10A0072
Filename	22-CROSS SECTIONS 200-2.DWG
Scale	1"=20'
Date	APRIL 22, 2011
LAYOUT	KMS 02/22/11
DRAWN	KMS 02/22/11
REVIEWED	RMH 4/22/11

Chicago-Romeoville Airport
JOLIET REGIONAL PORT DISTRICT
 1 George Michas Drive
 Romeoville, Illinois 60446
 Telephone: 815.838.9497
 Fax: 815.838.9524

DATE	REVISION

LE042