

	X	Ŷ
S. Abutment	2'8"	<sup>5</sup> 8"
S. Brg. Pier 1	2'8"	5 <sub>8</sub> "
N. Brg. Pier 1	2'8"	34"
S. Brg. Pier 2	2"	1"
N. Brg. Pier 2	2"	1"
N. Abutment	2"	1"

E LIN

anchor bolts may be used in lieu of ASTM F1554 Grade 36 (Fy=36ksi). The corresponding specified grade of AASHTO M314 anchor bolts may be used in lieu of ASTM F1554.

Anchor bolts may be either cast in place or installed in holes drilled after the supported member is in place.

Drilled and set anchor bolts shall be installed according to Article 521.06 of the Standard Specifications. Cost of all steel plates, shim plates, field drilling, and

field welding & grinding for stringer bearings shall be included with Structural Steel Repair. Cost of temporary support of existing stringers during

bearing installation is included with Jack and Remove Existing Bearings. See Sheet 13 of 23.

ξ

All bearing plates shall be placed perpendicular to stringers.

ROUTE NO.	SECTION	COUNTY Alexander Illingis FED. aid pr		TOTAL SHEETS	SHEET NO.	SHEET NO. 14
S.B.I. 150	(133A) D,I			32	21	23 SHEETS
FED. RDAD DIST.	NO. 7			OJECT-		1

Contract #98910



in bearing plate.

## SECTION B-B

An	<u>BILL OF MATERIAL</u> Item Unit Total chor Bolts <sup>3</sup> 4" \$ Each 72				
	ILLINOIS DEPARTMENT OF TRANSPORTATION STRINGER BEARING DETAILS OLD ILLINOIS ROUTE 3				
IN ENGINEERING, LTD. Consulting Engineers Chattam, lifnois	OVER SEXTON CREEK S.B.I. ROUTE 150 - SECTION (133A)D,I ALEXANDER COUNTY STATION 1212+84.95				
Checked By: STD Drawn By: AJF	STRUCTURE NO. 002-0009				