I OCATIONS FOR INTERSTATE 200	REPAIR	REPAIR	REPAIR	REPAIR	SURFACE	REPAIR WORK
LOCATIONS FOR INTERSTATE 290	LENGTH (FT)	WIDTH (FT)	AREA (SF)	AREA (SY)	TYPE	
EB I-290 EXIT RAMP TO PAULINA AVENUE						
25 - 266 EAT TO WILL TO TACEINA AVENUE	5	12	60	7	HMA	HMA SURF REM & RESURF
EB I-290 RAMP TO NB KENNEDY EXPY		16				
	5	12	60	7	HMA	HMA SURF REM & RESURF
	4	12	48	5	HMA	HMA SURF REM & RESURF
NB DAN RYAN EXPY TO WB I-290		10				
	4	12	48	5	HMA	HMA SURF REM & RESURF
	4	12	48	5	HMA	HMA SURF REM & RESURF
AID DAN DYAN DANS COME	- 8	12	96	11	HMA	HMA SURF REM & RESURF
NB DAN RYAN RAMP CONC SECT TO BRIDGE ABUTMENT	300	16.	4800	533	HMA	HMA SURF REM & RESURF
BRIDGE ABUTMENT TO GORE AREA NW QUADRANT	400	16	6400	711	HMA	HMA SURF REM & RESURF

	V V V	\vee \vee \vee	\sim		$\overline{}$		
WB I-290 ENTRANCE RAMP FROM INDEPENDENCE AVE	12	12	144	16	HMA	HMA SURF REM	
	\wedge				1 110//	A A A A	ARESURF

	SURFACE TYPE	REPAIR WORK
<u>Y)</u>	ITPE	
	HMA	HMA SURF REM & RESURF
		MAINLINE ONLY - NO SHLDS
	HMA	HMA SURF REM & RESURF

LOCATIONS FOR OHIO STREET FEEDER	REPAIR	REPAIR	REPAIR	REPAIR	SURFACE	REPAIR WORK
LOCATIONS FOR UNIO STREET FEEDER	LENGTH (FT)	WIDTH (FT)	AREA (SF)	AREA (SY)	TYPE	
EASTBOUND OHIO STREET FEEDER RAMP	470	V(4.D)(5.0				
EN OF BOOKE OF HE OTHER TELBER RAMP	470	VARIES	24444	2716	HMA	HMA SURF REM & RESURF
			· · · · · · · · · · · · · · · · · · ·			MAINLINE ONLY - NO SHLDS
WESTBOUND OHIO STRET FEEDER RAMP	405	VADIEO				
TO TO OTHE OTHER TELEVISION	465	VARIES	16929	1881	HMA	HMA SURF REM & RESURF
NOTE: USE POLYMERIZED HMA SURFACE COURSE, MI	V "E" NOO AT THEOR	10017/01/0				MAINLINE ONLY - NO SHLDS
NOTE: GOLT GET METALED THEAT SOLVE AGE GOOKSE, WI	A F, NOU AT THESE	LOCATIONS				

(7-15-08)

USER NAME = wilgreendp DESIGNED -REVISED - 7/15/08 - DPW DRAWN -CHECKED -REVISED -PLOT SCALE = 108.8888 '/ IN. REVISEO -PLOT DATE = 7/15/2008 DATE -REVISED -

STATE	OF	ILLINOIS
DEPARTMENT O)F '	TRANSPORTATION

SCALE

PATCHING SCHEDULE SHEET NO. OF SHEETS STA. TO STA.