Bar	No.	Size	Length	Shape
h(E)	16	#6	33′-2″	
Concrete Removal			Cu. Yd.	9.9
Concrete Superstructures			Cu. Yd.	8.3
Structure Excavation			Cu. Yd.	26
Granular Backfill for Structures			Cu. Yd.	20
Reinforcement Bars, Epoxy Coated			Pound	800

Any reinforcement bars that are damaged during concrete removal operations shall be repaired or replaced using and

Removal and disposal of handrail included in the cost with





COLLINS Suite 300 ENICINIEERS (212) 704-9300 PLOT DATE = CHECKED -REVISED AMS