


## SAW CUT JOINT (INCIDENTAL) EXISTING BITUMINOUS PAVEMENT OR CONCRETE SIDEWALK ST. P.C.C. SIDEWALK REMOVAL AND REPLACEMENT OR PAVEMENT REMOVAL AND BITUMINOUS REPLACEMENT, SPECIAL WARNING TAPE AS SPECIFIED TRENCH BACKFILL TRENCH BACKFILL 1° CABLE DUCT WITH 3 #6 WIRES, AND 1/C NO.8 GROUND

BITUMINOUS PAVEMENT OR CONCRETE SIDEWALK REMOVAL AND REPLACEMENT



SERVICE CONNECTION FOR ALL CONTROLLERS

TRENCH DETAIL

## MFT SECTION 06-00173-00-LT

	ROBINSON ENGINEERING, LTD. CONSULTING REGISTERED PROFESSIONAL ENGINEERS AND SURVEYORS		REVISIONS		
		OUTH HOLLAND, ILLINOIS 60473 FAX (708) 331-3826 HT 2006	No.	Date	Remarks
	F.A.P. ROUTE 344 127TH STREET @ MAPLE ROAD STREET LIGHTING DETAILS				
	BLUE ISLAND,	ILLINOIS	H		<b> </b>
	Drawn by: RG	Date: 11/27/06			1
	Checked by: PAP	Scale: NONE			
-	Sheet of	Project No. 06-688			

06688-LGHT-DTLS-01 (01)