

## STORM SEWER CONCRETE COLLAR AND GROUT CONNECTION




## UNDERDRAIN ALONG PAVEMENT EDGE




- 1. UNDERDRAIN TO BE INSTALLED WITHIN THE 8" DRAINAGE LAYER IN ACCORDANCE WITH THE SCHEDULE.
- 2. ANY SEPARATION FABRIC DAMAGED DURING THE INSTALLATION OF THE UNDERDRAIN TO BE EXCAVATED AND REPLACED.

# **UNDERDRAIN UNDER PAVEMENT**



**UNDERDRAIN CLEANOUT** 



UNDERDRAIN INSPECTION HOLE

LE038



### HANSON PROFESSIONAL SERVICES INC.

815 Commerce Drive, Suite 200 Oak Brook, Illinois 60523 Telephone: 630.990.3800 Fax: 630.990.3801

Illinois Professional Design Firm Registration No. 184-001084



© Copyright Hanson Professional Service Inc. 2007

#### JOLIET REGIONAL PORT DISTRICT

1 George Michas Drive Romeoville, Illinois 60446 Telephone: 815.838.9497 Fax: 815.838.9524

### REMOVE AND REPLACE PORTIONS OF RUNWAY 9-27 AND TAXIWAY C

AIP PROJECT NO. 3-17-0140-B41 IDA PROJECT NO. LOT-3709

		i	
			T
			T
			T
			T
$\Box$			I
No.	Drawing Issue Description	Date	Ву

JUNE 18, 2007

Sheet Title

## **UNDERDRAIN DETAILS**

840-071	38053	
Project Number		
LDH	06/05/07	
Layout By	Date	
LDH	06/05/07	
Designed By	Date	
RMH	06/18/07	
Davidson of D.	D-1-	

LDH | ---- | ----

23