

## SIGNING FOR FLAGGING OPERATIONS AT WORK ZONE OPENINGS

## WORK ZONE EXIT OPENING





## NOTES:

- 1. THE ARROWBORAD, THE FLAGGER AHEAD SIGN AND THE TRUCKS LEAVING HIGHWAY SIGN SHALL BE REMOVED OR TURNED AWAY FROM TRAFFIC AND THE EXIT AND ENTRY NON OPERATING EQUIPMENT SHALL BE CLOSED WHEN THE FLAGGING OPERATION CEASES. NON OPERATING EQUIPMENT SHALL COMPLY WITH ARTICLE 701.11
- 2. WORK ZONE OPENINGS SHOULD BE A MINIMUM OF ONE HALF MILE APART.
- 3. EXITING THE WORK ZONE AT ANY PLACE OTHER THAN AT A WORK ZONE EXIT OPENING WILL BE PROHIBITED
- ALL VEHICLES SHALL ENTER THE WORK ZONE AT ENTRY OPENINGS, USING THEIR TURN SIGNALS TO WARN MOTORISTS.

ALL DIMENSIONS ARE IN INCHES (MILLIMETERS) UNLESS OTHERWISE SHOWN

FILE NAME	1E = :	USER NAME = legso	DESIGNED -	REVISED - J.A.F. 04-03		SIGNING FOR FLAGGING OPERATIONS	F.A.U. SECTION	COUNTY TOTAL SHEET
W:\distate	W:\diststd\22x34\tc18.dgn		DRAWN -	REVISED - J.A.F. 02-06	STATE OF ILLINOIS	AT WORK ZONE OPENINGS	4061 09-00371-00-RS	MCHENRY 12 10
- 1		PLOT SCALE = 50.000 '/ IN.	CHECKED -	REVISED - S.P.B. 01-07	DEPARTMENT OF TRANSPORTATION		TC-18	CONTRACT NO. 63386
l		PLOT DATE = 1/26/2010	DATE -	REVISED - S.P.B. 12-09		SCALE: NONE SHEET NO. 1 OF 1 SHEETS STA. TO STA.	FED. ROAD DIST. NO. 1 ILLINOIS	FED. AID PROJECT