


STA 28+77.06 TO STA 32+09.17

MEDIAN ONLY EXISTS FROM STA 19+52.28 TO STA 20+57.10

EX ASPHALLIC DAVEMENT — SAL CINB — SAL CINB

TYPICAL EXISTING SECTION
STA 37+31.33 TO STA 40+33.23

NAME SCALE




TYPICAL EXISTING SECTION

STA 20+57.10 TO 28+77.06

**T.S.

STA 24+25.23 TO STA 28+77.06 IS NOT TYPICAL AND DOES NOT FOLLOW ANY TYPICAL SECTION.






NORTH WALL DOES NOT EXIST AND NORTH SIDEWALK EXTENDS TO CURB FROM STA 40+33.23 TO STA 40+37.91 AND FROM STA 40+61.74 TO STA 40+81.24

NORTH SIDEWALK EXTENDS TO CURB FROM STA 40+61.74 TO STA 40+81.24 $\,$


NORTH SIDEWALK DOES NOT EXIST FROM STA 40+33.23 TO STA 40+36.47 AND FROM STA 41+92.15 TO STA 42+00.93

SOUTH WALL DOES NOT EXIST AND SOUTH SIDEWALK EXTENDS TO CURB FROM STA 40+58.69 TO STA 40+77.19

SOUTH SIDEWALK DOES NOT EXIST FROM STA 42+15.37 TO STA 42+25.28



EAST ST. LOUIS
TYPICAL SECTIONS



TYPICAL EXISTING SECTION

STA 32+09.17 TO STA 37+31.33


N. T. S.

NORTH CURB DOES NOT EXIST FROM STA 32+09.17 TO STA 32+38.41 AND FROM STA 34+25.00 TO STA 36+07.95

SOUTH CURB DOES NOT EXIST FROM STA 35+41.22 TO STA 37+08.48

SOUTH SIDEWALK WITH BUFFER ONLY EXISTS FROM STA $36+19.75\ \text{TO}$ STA 37+31.33

SOUTH SIDEWALK BECOMES 13' WIDE AND HAS NO BUFFER FROM STA 35+62.05 TO STA 36+19.75



TYPICAL EXISTING SECTION

STA 42+25.28 TO STA 44+90.22

N. T. S.