LOCATIONS FOR INTEROTATE CO.	REPAIR	REPAIR	REPAIR	REPAIR	SURFACE	REPAIR WORK
LOCATIONS FOR INTERSTATE 290	LENGTH (FT)	WIDTH (FT)	AREA (SF)	AREA (SY)	TYPE	. •
EB I-290 EXIT RAMP TO PAULINA AVENUE						
ED 1 200 EXTENSION TO PACEINA AVENUE	5	12	60	7	HMA	HMA SURF REM & RESURF
EB I-290 RAMP TO NB KENNEDY EXPY	<i>-</i>	10				
TO THE TANKET LATE	5	12	60	7	HMA	HMA SURF REM & RESURF
	4	12	48	5	HMA	HMA SURF REM & RESURF
NB DAN RYAN EXPY TO WB I-290		40				
	4	12	48	5	HMA	HMA SURF REM & RESURF
· · · · · · · · · · · · · · · · · · ·	4	12	48	5	HMA	HMA SURF REM & RESURF
NR DAN DVAN DAMD CONG SECT TO PRIBOT ARITHMENT	8	12	96	11	HMA	HMA SURF REM & RESURF
NB DAN RYAN RAMP CONC SECT TO BRIDGE ABUTMENT	300	16.	4800	533	HMA	HMA SURF REM & RESURF
BRIDGE ABUTMENT TO GORE AREA NW QUADRANT	400	16	6400	711	HMA .	HMA SURF REM & RESURF

- /		V V V	V V \	$\wedge$		$\overline{}$		
(	WB I-290 ENTRANCE RAMP FROM INDEPENDENCE AVE	12	12	144	16	HMA	HMA SURF REM & RESURF	)
`		人 <u> </u>	$\wedge$			^ ^ ^	A A A A A A	Ĺ

LOCATIONS FOR OHIO STREET FEEDER	REPAIR LENGTH (FT)	REPAIR WIDTH (FT)	REPAIR AREA (SF)	REPAIR AREA (SY)	SURFACE TYPE	REPAIR WORK
EASTBOUND OHIO STREET FEEDER RAMP	470	VARIES	24444	2716	HMA	HMA SURF REM & RESURF
						MAINLINE ONLY - NO SHLDS
WESTBOUND OHIO STRET FEEDER RAMP	465	VARIES	16929	1881	НМА	HMA SURF REM & RESURF
NOTE: USE POLYMERIZED HMA SURFACE COURSE,	MIX "F", N90 AT THESE	LOCATIONS				MAINLINE ONLY - NO SHLDS

(7-15-08)

STATE OF ILLINOIS
DEPARTMENT OF TRANSPORTATION

SCALE

PATCHING SCHEDULE

SHEET NO. OF SHEETS STA. TO STA.