
STATE OF ILLINOIS DEPARTMENT OF TRANSPORTATION


naunc va.	SEDYXIN	Débitefy	20 g 7 ents	Markey.	SHEET NO. 5
FAP THE	×	MACON	22	£	5 SHEETS
"CD. 10AC D	PAR PRO- 10	Library reducer and			
*ดเวยห-ขอห		CONTANC! NO. 14839			i

*Cost included in PPC Deck Beams

** Existing dowel rads are to be burned off and ground flush prior to placement of new beams. Cost included in Removal of Existing PPC Deck Beams. After beams have been erected holes shall be drilled into cap and dowel rods placed. Dowel holes shall be filled with non-shrink grout to top of beam and allowed to cure a minimum of 24 hours prior to grouting the shear keys, cost included in PPC Deck Beams.



TYPICAL SECTION AT ABUTMENT
(Horizontal dimensions are at right angles to beam ends)



TYPICAL SECTION AT PIER
(Horizontal dimensions are at right angles to beam ends)

DECK BEAM DETAILS
FAP ROUTE 716 (IL 48)

OAKLAND AVENUE
SECTION (130BR-1)BR

MACON COUNTY
SN 058-0056

ESCA
CONSULTANTS, INC.
DESIGNED BY: ELH 02/07
DRAWN BY: PC 02/07
CHECKED BY: ELH 02/07
APPROVED BY: ROP 02/07

EXISTING BRIDGE PLANS