8075 03-00167-04-FP SANGAMON 109

ILLINOIS

SECTION

*STA 200+00.00 OAK HILL RD

STA 468+28.53 CARDINAL HILL RD

COUNTY TOTAL SHEETS

FED. AID PROJEC

COVER THE OPEN ENDS OF PIPES IN TRENCHES AT THE CLOSE OF EACH WORKING DAY.

PROP. INLET & PIPE PROTECTION, 1 EA 192100 PROP. 15"ø CSCP STA 188+63.50, RT STEEL END SECTION, 2 EA 46 FEET, TY 1 USFL 574.30 DSFL 574.05 **EROSION CONTROL NOTES** MAINTAIN OR REPLACE (IF SPECIFIED BY THE RESIDENT ENGINEER) SEDIMENT CONTROL THE TEMPORARY EROSION CONTROL SYSTEMS INSTALLED BY THE CONTRACTOR SHALL BE PROPERLY MAINTAINED AS DIRECTED BY THE ENGINEER TO CONTROL SILTATION AT ALL TIMES DURING THE LIFE OF THE CONTRACT. THIS WORK SHALL INCLUDE REPAIR OF THE VARIOUS SYSTEMS, REMOVAL OF TRAPPED SEDIMENT AND CLEANING OF ANY SILT FILTER FABRIC. IF THE CONTRACTOR FAILS TO MAINTAIN THE TEMPORARY EROSION CONTROL SYSTEMS AS DIRECTED BY THE ENGINEER, THE ENGINEER MAY AT THE EXPIRATION OF A PERIOD OF 48 HOURS, AFTER HAVING GIVEN THE CONTRACTOR WRITTEN NOTICE, PROCEED TO MAINTAIN THE SYSTEMS AS DEFMED NECESSARY, AND THE COST THEREOF WILL BE DEDUCTED FROM ANY COMPENSATION DUE, OR WHICH MAY BECOME DUE TO THE CONTRACTOR UNDER THIS CONTRACT IF THE CONTRACTOR FAILS TO MAINTAIN THE TEMPORARY EROSION CONTROL SYSTEMS AS DIRECTED BY THE ENGINEER. THE ENGINEER MAY AT THE EXPIRATION OF A PERIOD OF 48 HOURS, AFTER HAVING GIVEN THE CONTRACTOR WRITTEN NOTICE, PROCEED TO MAINTAIN THE SYSTEMS AS DEEMED NECESSARY, AND THE COST THEREOF WILL BE DEDUCTED FROM ANY COMPENSATION DUE. OR WHICH MAY BECOME DUE TO THE CONTRACTOR UNDER THIS CONTRACT. PRIOR TO LANDSCAPING/RESTORATION IMMEDIATELY PRIOR TO LANDSCAPING/RESTORATION WORK, THE CONTRACTOR SHALL: REMOVE AND DISPOSE OF SILT RETAINED BY THE TEMPORARY DITCH CHECKS. REINSTALL TEMPORARY DITCH CHECKS AFTER CLEANING, AND REMOVE AND REPLACE PLUGGED HAY OR STRAW BALES. FOLLOWING LANDSCAPING/RESTORATION AFTER LANDSCAPING/RESTORATION WORK, THE CONTRACTOR SHALL: MAINTAIN OR REPLACE (IF SPECIFIED BY THE RESIDENT ENGINEER) SEDIMENT CONTROL VEGETATION ESTABLISHED AFTER THE VEGETATION IS ESTABLISHED IN THE DISTURBED AREAS, THE CONTRACTOR REMOVE THE REMAINING SEDIMENT CONTROL ITEMS (SEDIMENT BARRIERS, INLET PROTECTION, AND OTHER REMAINING ITEMS). RESTORE THE AREAS DISTURBED BY THE SEDIMENT CONTROL ITEMS BY PERMANENT SEEDING AND MULCHING. INSTALL TEMPORARY DITCH CHECKS AT LOCATIONS SPECIFIED IN THE PLANS OR AS DIRECTED BY THE RESIDENT ENGINEER. INSTALL INLET PROTECTION AS SPECIFIED IN THE PLANS OR AS DIRECTED BY THE RESIDENT ENGINEER FOR CULVERTS AND INLETS AS THEY ARE INSTALLED AND AS WORK

-SEE/NEXT SHEET

P.C. STA 247+52.58

STA 192+39.43 OAK HILL RD= STA 245+28.09 CARDINAL HILL RD DEGRADING STEEL END SECTION, 2 EA 46 FEET, TY 1 PROP. INLET & PIPE PROTECTION, 1 EA USFL 567.60 DSFL 567.00 PROP. & CONST. To to 195+00 - - 197+00 OAK HILL ROAD 467±00 RD (80) P.T. STA 243+18.90 -P.I. STA 239+64.67 PROP. PERIMETER EROSION BARRIER 725 FEET PROP. © CONST. DEGRADING LEGEND TEMPORARY DITCH CHECK PERIMETER EROSION BARRIER INLET & PIPE PROTECTION FLOW DIRECTION EROSION CONTROL PLAN SEC. 03-00167-04-FP CARDINAL HILL ROAD (C.H. 37) SANGAMON COUNTY 03S2035B 6/21/06